

ComfortDelGro Engineering Pte Ltd 59 Loyang Drive Singapore 508969

Our Ref : 305542315

Via Fax : Email

Date

10.01-23

Your Insured

SHE 7580D

Time of Fax

-

Date of Acc

10.01.2023

Attn: Motor Claims Department

Alliant.

Dear Sirs

SURVEY OF CLIENT'S DAMAGED VEHICLE REG NO. SH

Our client has engaged us to repair the above vehicle and submit claims against the other party/parties-involved in the accident.

In accordance to the motor claims framework, we hereby request your presence at 59 Loyang Drive, Singapore 508969 to survey our client's damaged vehicle.

Enclosed, please find:

- i) Our initial estimate of repairs of the damaged vehicle;
- ii) Accident report made by our client.

I would appreciate it if you could call us to arrange for the survey of the vehicle:

♦ Ms. Loke YY	<u>Tel: 6214 8355</u>	LakaMV@anarkaaraara
♦ Jumani Bin Masudin	Tel: 6214 8315 or HP: 9635 5305	LokeWY@sparkcarcare.com
◆ Lim Tien Siong	Tel: 6214 8398 or HP: 9635 8546	Fax no. 6546 8156
♦ Chiang Liat Choon	Tel: 6214 8314 or HP: 9296 6006	3
-)

If we do not hear from you within the <u>next 48 hours</u>, we shall deem that you have waived your rights to survey our client's vehicle and we shall proceed to engage independent surveyor without further reference to you. We henceforth reserve our rights to claim for Loss of Use and Loss of Rental during any delayed period of this survey arrangement.

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a Motor Surveyor appointed by the Insurance company.

Thank you.

Yours faithfully

For Vice President Taxi Accident Repair

COMFORT TRANSPORTATION PTE LTD

REPAIR ESTIMATE

Vehicle No.: SHC1122P

Make : HYUNDAI

Model: IONIQ

Date: 01/10/23 Insurance: ALLIANZ

MVA: MS. LOKE YY

Qty	Parts Description / Labour	Туре	Unit Price	Amount
1	REAR BUMPER COVER			\$459.40
10	REAR BUMPER CLIPS			\$22.00
1	REAR BUMPER CENTRE MOULDING ASSY			\$451.25
1	REAR BUMPER REINFORCEMENT			\$394.80
1	REAR BUMPER REINFORCEMENT BRACKET LH			\$138.10
1	REAR BUMPER TOWING COVER			\$98.80
	SUB TOTAL			\$1,564.35
	LESS 25%			\$391.09
	DISCOUNTED TOTAL			\$1,173.26
	REAR BUMPER REVERSE SENSOR			\$180.00
			NETT	\$180.00
	Labour Charge			
	PANEL BEATING			\$400.00
	SPRAY PAINTING CHARGE			\$300.00
	REMOVE/REFIX REVERSE SENSOR			\$80.00
	TOTAL LABOUR			\$780.00
	ESTIMATE TOTAL			\$2,133.26

This is an initial actimate based on a vicual inspection of the above vehicle. The final repair quantum will be prepared after



ComfortDelGro Engineering Pte Ltd

205 Braddell Road Singapore 579701 Mainline + 65 6383 6280 Facsimile + 65 6280 9755

Workshops
205 Braddell Road Singapore 579701
59 Loyang Drive Singapore 508969
383 Sin Ming Drive Singapore 575717
Date/Time: 10.01.2023 16:13

Page: 1

∍am:

ARC Repair TP(CLSO)1

JOB CARD Sales Order: 5612403

JC NO.305542315

OMER

COMFORT TRANSPORTATION PTE LTD

7010045

OMER NO 383 SIN MING DRIVE RESS

Singapore SINGAPORE 575717

65508755 (R)

(O)

(P)

DUNT CARD NO.

REGN NO.	MILEAGE
MAKE : HYUNDAI	FUEL
MODELIONIQ(G2) 10	01.2023 13:30
YR OF MANU 26.2019	TARGET DATE
CHASSIS CODE KMHC851CVKU164425	COMPLETION DATE/TIME:

JOB DESCRIPTION


ccident Date: 10.01.2023

ATURE: 3P 10.01.2023 '

/NO

LABOR CODE

DESCRIPTION



KED & PASSED OUT BY:	 s		
SERVICE ADVISOR	š 	CUSTOMER'S SIGNATURE	
edgement Slip	Exit Pass		
No.: SHC1122P YY	Vehicle No.: SHC1122P		

Service Advisor urned to Service Reception upon collection Name of Service Advisor

Signature/Date

Date

To be kept by Security Guard