

REPAIR ESTIMATE

Model : IONIQ

MVA: MS. LOKE YY

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after

Tanpin 97445749
WP 11/1/23 C 130 pm
2/3 Resing after repair
tanpin C 11/1/23 was
2 days

Acknowledged by Repairer
Signature:
Date:

Date/Time: 10.01.2023 16:13

Page : 1

Team: ARC Repair TP(CLSO)1

JOB CARD Sales Order: 5612403

JC No. 305542315


CUSTOMER IS CUSTOMER NO LESS 383 SIN MING DRIVE Singapore SINGAPORE 575717 65508755 (R) (P)	REGN NO:	SHC1122P	MILEAGE
	MAKE:	HYUNDAI	FUEL E.....1/2.....F
	MODEL	IONIQ(G2)	DATE/TIME IN 10.01.2023 13:30
	YR OF MANU	26.06.2019	TARGET DATE
	CHASSIS CODE	KMHC851CVKU164425	COMPLETION DATE/TIME:

COUNT CARD NO.

JOB DESCRIPTION

Accident Date: 10.01.2023
 ATURE: 3P 10.01.2023

/NO LABOR CODE DESCRIPTION



KED & PASSED OUT BY: _____

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

edgement Slip

Exit Pass

to.: SHC1122P YY

Vehicle No.: SHC1122P

Service Advisor

Signature/Date

Name of Service Advisor

Date

urned to Service Reception upon collection

To be kept by Security Guard