



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
ALLIED WORLD ASSURANCE COMPANY LTD (SINGAPORE BRANCH) 60 ANSON ROAD #08-01 (8th FLOOR) MAPLETREE ANSON SINGAPORE 079914			Ref: CS/AWA23000370/Aqy3m4 Date: 09/03/2023 Code: AWA	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	YM 8057U	Veh. Inspected	TRB 7376X (XE 5102X)	
Policy No.	BVFCB0013872201	Coverage (\$)	0.00	
Claim No.	YM8057U/SG	Excess (\$)	0.00	
Assign From	GOH STELLA	Assign Date	11/01/2023	
2. Vehicle Particulars & Condition				
Make & Model	HOCK NAM SENG 40 FOOTER	c.c	0	
Engine No.	HIDDEN	Year of Reg.	2005	
Chassis No.	HNS804605	Colour	YELLOW	
Odometer	-	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	11.00 R20	SHAN LING	8 mm	
L/H Front Tyre	11.00 R20	SHAN LING	8 mm	
R/H Rear Tyre	11.00 R20	SHAN LING	8 mm	
L/H Rear Tyre	11.00 R20	SHAN LING	8 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	09/01/2023	Inspection Date	18/01/2023	
Survey held at	51 GUL CIRCLE			
Repairer	YSK AUTO WORKSHOP			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			3 Working Days	