



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

EQ INSURANCE COMPANY LTD
5 MAXWELL ROAD
#17-00 TOWER BLOCK
MND COMPLEX SINGAPORE 069110

Ref: CS3/EQI23000371/Rwy3

Date: 11/01/2023

Code: EQI

1. Policy Particulars :- (THIRD PARTY CLAIM)

Insured Veh.	FBJ 257A	Veh. Inspected	SLW 9544A
Policy No.		Coverage (\$)	0.00
Claim No.	DM23HO00058	Excess (\$)	0.00
Assign From	NEO JIE SI	Assign Date	11/01/2023

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	06/01/2023	Inspection Date	11/01/2023
Survey held at	CAR LABORATORIES PTE LTD NO. 1 BUKIT BATOK CRESCENT #04-56 WCEGA PLAZA SINGAPORE 658064		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.
--