



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Immediate Advice

To : Allianz Insurance Singapore Pte. Ltd

Date: 10.02.2023

Survey Details:

| | |
|---------------------|------------------|
| Date of loss | 09.01.2023 |
| Date of appointment | 11.01.2023 |
| Date of survey | 11.01.2023 |
| Location of survey | NPH AUTO SERVICE |

Vehicle Details:

| | |
|----------------------|------------------------------|
| Claim Type: | THIRD PARTY CLAIM |
| Vehicle number | SLQ5585P |
| Make and Model | MAZDA 3 SEDAN 1.5 AT LED EU6 |
| Date of registration | 14-Jul-17 |
| Market Value | \$ 58,000.00 |
| Parf Rebate | \$ 29,367.00 |
| Nett Loss | \$ 28,633.00 |

Repair details:

| | |
|------------------|----------|
| Initial Estimate | 8,712.60 |
|------------------|----------|

Proposed/Revised repair cost:

| | |
|--------------------------------|--------------------|
| Parts | \$ 4,969.36 |
| Check items (estimate) | \$ - |
| Labour | \$ 1,985.00 |
| Total | \$ 6,954.36 |
| Lump Sum(if applicable) | \$ 5,500.00 |

| | |
|----------------------------------|------------|
| Number of days for repair | 5.0 |
|----------------------------------|------------|



Remarks:

Liability: 100%. BOLA:27 Insured driver rear-ended third party. Liability is not in our driver's favour.

XD8279E (OI) -> SLQ5585P (TP)

Mandate:

| Liability(TP) | | 100% |
|------------------------------------|-----------|-----------------|
| Proposed repair cost (w/GST) | \$ | 5,940.00 |
| Loss of use (7 days x \$60) | \$ | 420.00 |
| Loss of rental (7 days x \$100.00) | \$ | 700.00 |
| Loss of income | | NIL |
| LTA search fees | \$ | 7.45 |
| Others | | NIL |
| Proposed Total | \$ | 7,067.45 |