

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

CC4/A1523000373/4p93

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

GIA / PR Seen:

Est. Repairs:

Lump Sum:

Consistent? : Yes or No

Consistent? : Yes or No

Res.: Yes or No

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour:

Sp. Reading

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Date/Time, File Pass to?

1)

Date/Time, File Return to?

2)

Report Format :

Lump Sum / I.B.I: (\$)

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

☐

Site Insp (\$)

☐

Interview (\$)

☐

Tech. Invs (\$)

☐

Weekend (\$)

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL



NPH AUTO SERVICE



Block 9005 Tampines Street 93 #01-246/254 Singapore 528839 Tel: 67840663 (8 Lines) Fax: 67840692

GST Reg No: MX-0869103-NO Business Reg No: 394773/00D

E-mail: nphauto@pacific.net.sg

Your Ref :

Page

: 1/2

Our Ref : TP0006/01/23

Date

: 11/01/2023

THIRD PARTY CLAIM

M/S : TANG HAN WEI

222A BEDOK NORTH DRIVE

#13-22 SINGAPORE 461222

Attn :

Dear Sir/Madam

RE: ACCIDENT REPAIR ON : SLQ5585P - MAZDA 3

INSURED : TANG HAN WEI

DATE OF ACCIDENT : 09/01/2023

POLICY NO : MP320428

ENGINE# : D

CHASSIS# : E

APPENDED BELOW ARE THE ESTIMATED COST OF REPAIR & TO BE REPLACED:

	Qty	U/Cost	U/Price	Total
		\$	\$	\$
<u>Replacement of Parts</u>				
1 rear boot	10	1004.00	1004.00	1,004.00
2 rear boot hinge L & R	20	152.00	152.00	304.00
3 rear boot lamp L & R	20	466.00	466.00	932.00
4 rear boot center logo	10	77.00	77.00	77.00
5 rear mazda 3 emblem	10	55.00	55.00	55.00
6 rear skyactiv emblem	10	67.00	67.00	67.00
7 rear boot lock top	10	185.00	185.00	185.00
8 rear boot finisher clip	120	6.90	6.90	82.80
9 rear boot lower lock catch	10	57.00	57.00	57.00
10 rear lamp assembly L & R	20	960.00	960.00	1,920.00
11 rear bumper	10	1127.00	1127.00	1,127.00
12 rear bumper reflector lamp L & R	20	53.00	53.00	106.00
13 rear bumper side retainer L & R	20	38.00	38.00	76.00
14 rear bumper enforcement	10	563.00	563.00	563.00
15 rear lamp end panel	10	530.00	530.00	530.00
16 rear boot rubber	10	135.00	135.00	135.00
17 rear end panel inner center garnish	10	99.70	99.70	99.70
18 rear end panel keyless sensor	10	123.00	123.00	123.00
19 rear parking sensor wire	10	141.00	141.00	141.00
				7,584.50
Less 20%				-1,516.90
Total Material				\$6,067.60
<u>Special Nett Items</u>				
1 rear bumper parking sensor	10	200.00	200.00	200.00
				200.00
				0.00

Not Authorized
11/01/23
1/5 \$5500
5 days

20/3ent
M
11
rel
M
rel
3ent
11
one
DIS
11
3ent
3ent
Body on
TWI
TWI
Dage/cu
8u

skunk

1set



NPH AUTO SERVICE



Block 9005 Tampines Street 93 #01-246/254 Singapore 528839 Tel: 67840663 (8 Lines) Fax: 67840692

GST Reg No: MX-0869103-NO Business Reg No: 394773/00D

E-mail: nphauto@pacific.net.sg

Your Ref :
Our Ref : TP0006/01/23

Page : 2/2
Date : 11/01/2023

THIRD PARTY CLAIM

APPENDED BELOW ARE THE ESTIMATED COST OF REPAIR & TO BE REPLACED:

	Qty	U/Cost	U/Price	Total
		\$	\$	\$
Total S/Nett				\$200.00
Labour & Misc				
1 Remove and install rear boot, rear lamp, rear bumper, cut out and renew rear end panel. Knocking spare tyre panel, rear lamp panel and restraighthen body and chassis.			1,200.00	900
2 Spray Painting			1,000.00	950
3 Check wiring system.			25.00	✓
4 Reset and renew parking sensor.			100.00	50
5 Remove and install rear boot carpet.			120.00	60
			2,445.00	
Total Labour			\$2,445.00	
Nett Total Before Gst			\$8,712.60	

Your faithfully

NPH AUTO SERVICE
(Manager)

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P-5961.7
202
476936
200
1985
6950