



**Section A - Accident Details**

Registration Number	SHD6070S
Case Reference Number	TAX/01/23/2019
Registration Date	19/Dec/2017
Company Type	Strides Taxi Pte Ltd
Make	TOYOTA
Model	PRIUS4
Name of Driver	CHIA YEW HOCK
Type of Accident	Side Swipe
Accident Date and Time	11/Jan/2023 10:40 AM
Accident Reported Date and Time	11/Jan/2023 12:31 PM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24117391
Special Instruction to ARC, if any	TP/ LEFT PORTION/AXA
Prepared Date and Time	11/Jan/2023 2:04 PM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

**Section B - Summary of Repair Estimates**

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$1,014.00	\$400.00
Total Spray Cost	\$1,674.00	\$750.00
Total Spare Part Cost	\$8,161.37	\$2,810.51
Total Other Cost	\$620.00	(\$610.51)
<b>TOTAL COST</b>	<b>\$11,469.37</b>	<b>\$3,350.00</b>
<b>Lump Sum Total</b>	<b>\$0.00</b>	<b>\$0.00</b>
Number of Repair Days	7.0	4.0
Prepared / Adjusted By	<b>Boon Chew Tay</b>	<b>Kenneth Kong (LKK)</b>
ARC / Surveyor Sign Off Date	<b>12/01/2023 12:19 PM</b>	<b>12/01/2023 11:37 AM</b>
Signature		
Remarks	LUMPSUM REPAIR / AFTER REPAIR PHOTOS, FOR CHECK ITEM and REPLACE ITEM PLEASE CALL SURVEYOR Kenneth Kong (LKK) HP/97888708 & KennethKong@lkkauto.com.	

**Section C - Quotation and Accident Invoice Details**

<b>Quotation Number</b>	QN-2302-0040	<b>Invoice Number</b>	
<b>Quotation Date</b>	06.02.2023	<b>Invoice Date</b>	
<b>Invoice Amount</b>		<b>Prepared Date</b>	

**Section D - Details of Repair Estimates**
**Part 1 - Labour Works**

<b>Job Scope</b>	<b>Quotation from AR</b>	<b>Adjusted by Surveyor, if applicable</b>
TO REPAIR LH PORTION	\$1,014.00	\$400.00 ✓
<b>Total Labour</b>	<b>\$1,014.00</b>	<b>\$400.00</b>

**Part 2 - Spray Painting & Panel Beating Related Works**

<b>Job Scope</b>	<b>Quotation from ARC</b>	<b>Adjusted by Surveyor, if applicable</b>
TO RESPRAY FRONT FENDER LH	\$378.00	\$200.00 ✓
TO RESPRAY ROCKER PANEL MOULDING	\$180.00	\$150.00 ✓
TO RESPRAY FRONT DOOR LH	\$378.00	\$200.00 ✓
TO RESRAY REAR DOOR LH	\$378.00	\$200.00 ✓
TO RESPRAY CENTRE PILLAR LH	\$180.00	\$0.00
TO RESPRAY APRON PANEL LH	\$180.00	\$0.00
<b>Total Spray Painting &amp; Panel Beating</b>	<b>\$1,674.00</b>	<b>\$750.00</b>

**Part 3 - Other Costs - Accident and Accident Repair Related Expense**

<b>Job Scope</b>	<b>Quotation from ARC</b>	<b>Adjusted by Surveyor, if applicable</b>
Lump Sum Adjustment by Surveyor	\$0.00	(\$840.51)
TO WASH AND VACUUM	\$60.00	\$0.00
TO CHECK WIRING AND SYSTEM FUNCTION	\$120.00	\$20.00 ✓
TO APPLY RUST-PROOFING ON AFFECTED AREA	\$100.00	\$90.00 ✓
TO TRANSFER DOOR MECHANISM	\$240.00	\$120.00 ✓
TO REPLACE SUNDRY PARTS	\$100.00	\$0.00
<b>Total Other Costs</b>	<b>\$620.00</b>	<b>(\$610.51)</b>

**Part 4 - Spare Parts / Material Usage**

<b>Part Number</b>	<b>Portion</b>	<b>Stock Number</b>	<b>Part Name</b>	<b>Quantity</b>	<b>List Price (\$)</b>	<b>Discount (%)</b>	<b>Final Price (\$)</b>	<b>Estimator Approved</b>	<b>Surveyor Approved</b>
		5380247100	FENDER SUB-ASSY, FR, LH	1.00	\$1,060.70	30.00	\$742.49	Replace	Replace
		7537447140	EMBLEM, SIDE PANEL (HYBRID)	1.00	\$59.10	30.00	\$41.37	Replace	Replace
		5387647110	LINER, FR FENDER, LH	0.00	\$219.10	0.00	\$0.00	Replace	Not Given
		5385247041	PAD, FR WHEEL LH	0.00	\$65.00	0.00	\$0.00	Replace	Not Given
		5380847020	SEAL SUB-ASSY, LH	0.00	\$56.20	0.00	\$0.00	Replace	Not Given
		5382847070	PROTECTOR, FR FENDER LH	0.00	\$101.80	0.00	\$0.00	Replace	Check
		7586047900	MOULDING ASSY, BODY ROCKER PANEL, LH	1.00	\$649.10	100.00	\$0.00	Replace	Repair
		6700247162	PANEL SUB-ASSY, FRONT DOOR LH	1.00	\$1,407.80	30.00	\$985.46	Replace	Replace
			STICKER STRIDES TAXI (DOOR)	1.00	\$60.00	0.00	\$60.00	Replace	Replace

✓ BT  
 ✓ NEC  
 X  
 X  
 X XNN  
 X  
 R  
 ✓ DD  
 ✓ NEC

**STRIDES Accident Vehicle Repair Estimates**

<b>STRIDES Automotive Services Pte Ltd</b>
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 19/02/2023

User ID : PohSuan

		68720121 51	HINGE ASSY, FRONT DOOR , UPPER LH	1.00	\$105.50	100.00	\$0.00	Replace	Repair	R
		68740121 20	HINGE ASSY, FRONT DOOR , LOWER LH	1.00	\$120.00	100.00	\$0.00	Replace	Repair	R
		69802210 10	DOOR FRONT WINDOW REGULATOR SUB-ASSY, LH	0.00	\$257.80	0.00	\$0.00	Replace	Check	X
		85720471 40	DOOR FRONT MOTOR ASSY, POWER WINDOW	0.00	\$996.60	0.00	\$0.00	Replace	Check	X
		68610470 40	CHECK ASSY, FRONT DOOR	0.00	\$199.40	0.00	\$0.00	Replace	Check	X
		67862470 50	WEATHERSTRIP, FRONT DOOR LH	0.00	\$250.70	0.00	\$0.00	Replace	Not Given	X
		69040471 00	LOCK ASSY, FRONT DOOR LH	0.00	\$607.90	0.00	\$0.00	Replace	Not Given	X XNN
		69410201 10	DOOR LOCK STRIKER	0.00	\$42.60	0.00	\$0.00	Replace	Not Given	X
		75720470 40	MOULDING ASSY, FRONT DOOR BELT, LH	0.00	\$99.90	0.00	\$0.00	Replace	Not Given	X
		82152475 51	WIRE, FRONT DOOR, LH	0.00	\$576.30	0.00	\$0.00	Replace	Not Given	X
		861600W X80	FRONT DOOR SPEAKER ASSY, RADIO RH & LH	0.00	\$982.10	0.00	\$0.00	Replace	Check	X
		67004472 10	PANEL SUB-ASSY, REAR DOOR, LH	1.00	\$1,401.70	30.00	\$981.19	Replace	Replace	√ DD
		53702471 01	APRON SUB-ASSY, FRONT FENDER, LH	0.00	\$1,060.90	0.00	\$0.00	Replace	Not Given	X
		61312470 40	PILLAR, CENTER BODY, OUTER LH	0.00	\$349.50	0.00	\$0.00	Replace	Not Given	X
<b>Total</b>					<b>\$10,729.70</b>		<b>\$2,810.51</b>			

Added Spare Parts / Material Usage After Surveyor Signed off									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

2,810.51  
 + 400.00 L/S \$3,350/-  
 + 980.00  
 4,190.51  
 -20%  
 3,352.41