



## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

		Affiliated to Federation Internation	onale Des Experts E	n Automo	bile	
	CHINA TAIPING IN	ISURANCE (S) PTE LTD		Ref:	CS3/CTI23000392/Tvp3	
	3 ANSON ROAD #			Date:	11/01/2023	
	SPRINGLEAF TO	VERSINGAPORE 079909		0 1		
_		Delieu Deutieuleus	. /TUDD DADT	Code:		
1.	I	Policy Particulars :- (THIRD PARTY CLAIM)				
	Insured Veh.	SLH 9927H	Veh. Inspected	<u> </u>	SMK 2420X	
	Policy No.	0.11.400000000	Coverage (\$)		0.00	
	Claim No.	SNM23D200238	Excess (\$)		0.00	
	Assign From	LYNN KHONG	Assign Date		11/01/2023	
2.						
	Make & Model		c.c		0	
	Engine No.	HIDDEN	Year of Reg.			
	Chassis No.	Colour				
	Odometer	-	Steering			
	Brakes		Modification			
	General					
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre				mm	
	L/H Front Tyre				mm	
	R/H Rear Tyre				mm	
	L/H Rear Tyre				mm	
4.	Description of Damages					
5.	General Information					
	Accident Date	10/01/2023	Inspection Da	te	11/01/2023	
	Survey held at ASSURE AUTO ASSIST PTE LTD					
		23 TUAS AVENUE 18 SINGAPORE 638902				
5a.	l Remarks					
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.					