



Supplementary Estimate-1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 / Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/0022/2023/EQ 1-Feb-23 CHANG 1 of 1 SDB 5957 Z AUDI A8L D5 3.0 TFSI	
Quantity	Description	Unit Price	Amount	
Labours				
1	TO DISMANTLE AND RENEW LHS CHARGE AIR COOLER.	S/N \$ 480.00	\$ 480.00	
Parts				
1	FRONT BUMPER REINFORCMENT BRACKET - RH	\$ 36.00	\$ 28.24	
2	FRONT WHEEL SPOILER - RH	\$ 112.00	\$ 89.20	
3	FRT FENDER TOP COVER - LH	\$ 42.00	\$ 33.28	
4	WIRE CONNECTOR - 14PIN BROWN	\$ 35.00	\$ 27.68	
5	WIRE CONNECTOR - 14PIN BLACK	\$ 30.00	\$ 23.60	
6	ADAPTER CABLE LOOM	\$ 464.00	\$ 371.20	
7	CORRUGATED PIPE	\$ 97.00	\$ 77.28	
8	CHARGE AIR COOLER AIR GUIDE - LH	\$ 81.00	\$ 64.08	
9	CHARGE AIR COOLER - LH	\$ 1,962.00	\$ 1,569.60	
PARTS		\$ 2,859.00	\$ 2,284.16	
LABOUR		\$ 480.00	\$ 480.00	
GRAND TOTAL		\$ 3,339.00	\$ 2,764.16	

For Premium Automobiles Pte Ltd

Authorized Signature