

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0022/2023/EQ
DATE : 10-Jan-23
WIP : 58198

VEHICLE IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 11/1/2023

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

*Hi Rasul,
6 days - ok - Johnny Boo
23-Mar-23*

OWNER'S NAME : MS COUDRAY BOOKER MARIE EMMANUELLE LUCIE
ADDRESS : 14 SWISS CLUB ROAD
SINGAPORE 288107

TELEPHONE : HP +65 96253450
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 1800152122-03
VEHICLE NO : **SDB 5957 Z**
MODEL CODE : AUDI A8 D5 3.0 TFSI
MODEL YEAR : 31/12/2018
ENGINE NO : CZS 016956
CHASSIS NO : WAUZZZF82KN006271
MILEAGE : 30,486
DATE IN : 9-Jan-23
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 7-Jan-23
PLACE OF ACCIDENT : JALAN ANAK BUKIT

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SDB 5957 Z

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$	480.00	\$ 480.00
2	TO REMOVE AND TRANSFER LHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$	450.00	\$ 300.00
3	TO DISMANTLE AND RENEW FRONT BUMPER, LHS FRONT FENDER AND LHS HEADLIGHT. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	2,700.00	\$ 1,200.00
4	TO RESPRAY FRONT BUMPER AND LHS FRONT FENDER.	\$	2,000.00	\$ 1,200.00
5	TO CARRY OUT CALIBRATION FOR FRONT BUMPER 360 CAMERA, DISTANCE REGULATION AND RADAR SENSOR.	S/N \$	480.00	\$ 480.00
6	TO RENEW LHS FRONT RIM. TO CARRY OUT PRE/POST WHEEL ALIGNMENT.	S/N \$	520.00	\$ 320.00
7	ADD LABOUR	\$	480.00	\$ 480.00
8	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$	192.00	\$ 192.00
TOTAL LABOUR CHARGES		:	\$ 7,302.00	\$ 4,652.00

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SDB 5957 Z

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
1	FRONT BUMPER	1	\$ 3,985.00	\$	3,188.00
2	FRONT BUMPER FIXING PARTS	1	\$ 570.00		
3	FRONT BUMPER CLOSING ELEMENT	1	\$ 456.00	\$	364.40
4	FRONT BUMPER COVER - CENTER	1	\$ 77.00		
5	FRONT BUMPER COVER - LH / RH	2	\$ 176.00		
6	FRONT BUMPER BRACKET - LH / RH	2	\$ 260.00	\$	208.00
7	FRONT BUMPER GRILLE - LOWER CENTRE	1	\$ 551.00	\$	440.40
8	FRONT BUMPER CHROME TRIM - LH / RH	2	\$ 450.00	\$	180.00
9	FRONT BUMPER TRIM CAP - LH	1	\$ 18.00	\$	13.84
10	FRONT BUMPER END CAP - LH / RH	2	\$ 138.00		
11	FRONT BUMPER AIR GUIDE GRILLE - LH / RH	2	\$ 1,404.00	\$	561.60
12	FRONT BUMPER OUTER TRIM - LH REAR UPPER	1	\$ 260.00		
13	FRONT BUMPER OUTER TRIM - LH / RH LOWER	2	\$ 520.00		
14	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	1	\$ 310.00	\$	247.60
15	FRONT BUMPER SPOILER	1	\$ 349.00	\$	279.20
16	FRONT BUMPER LOWER COVER BRACKET	1	\$ 94.00		
17	RADIATOR GRILLE	1	\$ 2,631.00	\$	2,104.80
18	"QUATTRO" INSCRIPTION	1	\$ 118.00		
19	RADIATOR GRILLE COVER	1	\$ 74.00		
20	RADIATOR GRILLE COVER CAP	1	\$ 149.00		
SUB TOTAL SPARE PARTS		:	\$ 12,590.00	\$	7,587.84

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SDB 5957 Z

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
		<i>c/f</i>		<i>\$ 7,587.84</i>
21	RADIATOR GRILLE BRACKET	1	\$ 56.00	
22	RADIATOR GRILLE END CAP - LH / RH	2	\$ 54.00	
23	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	1	\$ 209.00	
24	FRONT BUMPER AIR GUIDE - LH / RH	2	\$ 158.00	
25	FRONT PARKING AID SENSOR SUPPORT - LH / RH	2	\$ 120.00	
26	FRONT LICENCE PLATE HOLDER	1	\$ 972.00	
27	FRONT BUMPER SUPPORT - LH / RH	2	\$ 72.00	
28	FRONT BUMPER FOAM FILLER PIECE	1	\$ 149.00	
29	FRONT BUMPER REINFORCEMENT BEAM	1	\$ 1,412.00	
30	FRONT BUMPER CROSS MEMBER	1	\$ 430.00	
31	FRONT BUMPER GUIDE SECTION - LH	1	\$ 71.00	<i>\$ 56.56</i>
32	FRONT REBOUND STRAP	1	\$ 94.00	
33	FRONT BUMPER BRACKET	1	\$ 36.00	<i>\$ 28.24</i>
34	FRONT BUMPER TOP COVER	1	\$ 236.00	<i>\$ 188.40</i>
35	FRONT BUMPER TOP COVER CAP	1	\$ 41.00	
36	AIR CONDITIONER STICKER	1	\$ 24.00	<i>\$ 18.56</i>
37	CAUTION SIGN STICKER	1	\$ 17.00	<i>\$ 13.28</i>
38	HORN HIGH TONE - RH	1	\$ 165.00	
39	HORN BRACKET - UPPER	1	\$ 27.00	
40	HORN BRACKET - LOWER	1	\$ 56.00	
SUB TOTAL SPARE PARTS			\$ 4,399.00	\$ 7,892.88

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SDB 5957 Z

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
		<i>c/f</i>		\$	<i>7,892.88</i>
41	FRONT PARKING AID SENSOR - INNER	2	\$ 598.00		
42	FRONT PARKING AID SENSOR - OUTER	2	\$ 598.00	\$	<i>239.20</i>
43	FRONT PARKING AID SENSOR - INNER / OUTER	2	\$ 598.00		
44	FRONT PARKING AID SEAL RING	4	\$ 11.00	\$	<i>8.32</i>
45	FRONT BUMPER WIRING SET	1	\$ 756.00	\$	<i>604.40</i>
46	FRONT FENDER - LH	1	\$ 3,088.00	\$	<i>2,470.40</i>
47	FRONT FENDER BRACKET - LH FRONT	1	\$ 100.00	\$	<i>79.28</i>
48	FRONT FENDER BRACKET - LH CENTRE	1	\$ 74.00		
49	FRONT FENDER BRACKET - LH UPPER	1	\$ 35.00		
50	FRONT FENDER BRACKET - LH UPPER	1	\$ 54.00	\$	<i>42.96</i>
51	FRONT FENDER BRACKET - LH LOWER	1	\$ 42.00		
52	FRONT FENDER BRACKET - LH REAR	1	\$ 74.00		
53	FRONT FENDER BRACE - LH INNER	1	\$ 642.00	\$	<i>513.20</i>
54	FRONT FENDER BRACE - LH OUTER	1	\$ 180.00	\$	<i>143.60</i>
55	FRONT FENDER CONNECTING PIECE - LH	1	\$ 215.00	\$	<i>171.60</i>
56	FRONT FENDER RETAINING BRACKET - LH	1	\$ 22.00	\$	<i>17.20</i>
57	FRONT FENDER ATTACHMENT PARTS	1	\$ 65.00		
58	FRONT WHEEL HOUSING LINER - LH	1	\$ 495.00	\$	<i>395.60</i>
59	FRONT WHEEL SPOILER - LH	1	\$ 112.00	\$	<i>89.20</i>
60	FRONT WHEEL SPOILER STONE CHIP GUARD - LH	1	\$ 60.00		
SUB TOTAL SPARE PARTS		:	\$ 7,819.00	\$	<i>12,667.84</i>

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SDB 5957 Z

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
		<i>c/f</i>		\$ 12,667.84
61	FRONT FENDER CHROME LINING - LH	1	\$ 190.00	\$ 151.60
62	HEADLIGHT - LH	1	\$ 14,751.00	\$ 11,800.80
63	LIFT CYLINDER - LH / RH	2	\$ 630.00	
64	LIFT CYLINDER HOSE	1	\$ 104.00	
65	LIFT CYLINDER PIPE	1	\$ 72.00	
66	LIFT CYLINDER WASH WATER RESERVOIR	1	\$ 476.00	
67	FRONT ALUMINIUM RIM	1	\$ 3,338.00	\$ 2,670.40
68	FRONT ALUMINIUM RIM RUBBER VALVE	1	\$ 4.00	\$ 3.04
69	FRONT NO PLATE	S/N	\$ 60.00	\$ 60.00
70	SUPPLEMENTARY		\$ 2,859.00	\$ 2,284.16
71	SUNDRIES		\$ 500.00	\$ 120.24
TOTAL SPARE PARTS			\$ 47,792.00	\$ 29,758.08
TOTAL LABOUR CHARGES			\$ 7,302.00	\$ 4,652.00
GRAND TOTAL			\$ 55,094.00	\$ 34,410.08

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.
 BL-21/02/23



PREMIUM AUTOMOBILES

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg



Supplementary Estimate-1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 / Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/0022/2023/EQ 1-Feb-23 CHANG 1 of 1 SDB 5957 Z AUDI A8L D5 3.0 TFSI	
Quantity	Description		Unit Price	Amount
<u>Labours</u>				
1	TO DISMANTLE AND RENEW LHS CHARGE AIR COOLER.	S/N	\$ 480.00	\$ 480.00
<u>Parts</u>				
1	FRONT BUMPER REINFORCMENT BRACKET - RH	1	\$ 36.00	\$ 28.24
2	FRONT WHEEL SPOILER - RH	2	\$ 112.00	\$ 89.20
3	FRT FENDER TOP COVER - LH	1	\$ 42.00	\$ 33.28
4	WIRE CONNECTOR - 14PIN BROWN	1	\$ 35.00	\$ 27.68
5	WIRE CONNECTOR - 14PIN BLACK	1	\$ 30.00	\$ 23.60
6	ADAPTER CABLE LOOM	1	\$ 464.00	\$ 371.20
7	CORRUGATED PIPE	1	\$ 97.00	\$ 77.28
8	CHARGE AIR COOLER AIR GUIDE - LH	1	\$ 81.00	\$ 64.08
9	CHARGE AIR COOLER - LH	1	\$ 1,962.00	\$ 1,569.60
PARTS			\$ 2,859.00	\$ 2,284.16
LABOUR			\$ 480.00	\$ 480.00
GRAND TOTAL			\$ 3,339.00	\$ 2,764.16

For Premium Automobiles Pte Ltd

Authorised Signature

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT