



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623			Ref: CS/SMO23000401/Kvy3q2	
			Date: 03/02/2023	
			Code: SMO	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
	Insured Veh.	SJT 2507T	Veh. Inspected	SMW 6428K
	Policy No.		Coverage (\$)	0.00
	Claim No.	CMTD2300161/RUC	Excess (\$)	0.00
	Assign From	GRACE TEO	Assign Date	12/01/2023
<b>2. Vehicle Particulars &amp; Condition</b>				
	Make & Model	VOLKSWAGEN GOLF TSI (A)	c.c	1395
	Engine No.	HIDDEN	Year of Reg.	2015
	Chassis No.	WVWZZZAUZFW015244	Colour	METALLIC DARK GREY
	Odometer	94526 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
	General	GOOD		
<b>3. Conditions of Tyres</b>				
		Size	Make	Balance
	R/H Front Tyre	225/45 R17	CONTINENTAL	8 mm
	L/H Front Tyre	225/45 R17	CONTINENTAL	8 mm
	R/H Rear Tyre	225/45 R17	CONTINENTAL	8 mm
	L/H Rear Tyre	225/45 R17	CONTINENTAL	8 mm
<b>4. Description of Damages</b>				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.  DAMAGES SEE DETAILS.			
<b>5. General Information</b>				
	Accident Date	11/01/2023	Inspection Date	12/01/2023
	Survey held at	KGC WORKSHOP PTE LTD 176 SIN MING DRIVE, SIN MING AUTOCARE #02-04 SINGAPORE 575721		
<b>5a. Remarks</b>				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	