

KV



KGC WORKSHOP PTE LTD

Sincere • Secure • Satisfaction

Since 1987

NOT ADVISED
11/1/23 @ 3650/h
Returning After Paint

4 days

Date

No of Page

11/1/2023

1/1

Lump Sum
\$3,650.00

parts \$3,151.89
+ SINI \$340.00
+ Labor \$120.00
\$4611.89
20%

\$3689.51

LIM PECK S
11/1/23
Block F
Singapore

Registration N
Accident Date
Car Ref:

SMW 6428K
11-Jan-23
TP

Model : Volkswagen Golf A7 1.4
Chassis No: VVVZZZAUZFW015244
Engine Capacity 1.4

Item	Unit Price	Amount
1 Rear Bumper	\$ 895.50	\$ 895.50
2 Rear Lower Bumper	\$ 395.25	\$ 395.25
3 Rear Bumper inner center bracket	\$ 115.00	\$ 115.00
4 Rear Bumper inner side bracket RHS/LHS	\$ 47.20	\$ 94.40
5 Rear bumper retainer RHS/LHS	\$ 55.00	\$ 110.00
6 Rear Bumper reinforcement	\$ 495.80	\$ 495.80
7 Rear Bumper Reflector RH/LHS	\$ 85.70	\$ 171.40
8 Rear end panel	\$ 1,090.00	\$ 1,090.00
9 Rear end panel top garnish	\$ 245.20	\$ 245.20
10 Rear number plate lamp RHS.LHS	\$ 55.00	\$ 110.00
11 Rear tailgate	\$ 1,598.70	\$ 1,598.70
12 Rear tailgate lock	\$ 256.50	\$ 256.50
13 Tailgate LOGO	\$ 73.00	\$ 73.00
14 Rear Emblem "GOLF"	\$ 86.90	\$ 86.90
15 Rear Emblem "R"	\$ 50.70	\$ 50.70
16 Rear Emblem "TSI"	\$ 64.00	\$ 64.00
17 Rear Emblem "BLUEMOTION"	\$ 85.50	\$ 85.50
18 Rear Windscreen Moulding	\$ 137.50	\$ 137.50
		\$ 5,937.85
	-10%	\$ 593.79
	Total for spare parts	\$ 5,344.07

rear number plate and bracket

rear number plate and bracket

Rear Bumper Clips	\$ 50.00	\$ 50.00
Rear parking sensor	\$ 380.00	\$ 380.00
Rear windscreen sealant	\$ 50.00	\$ 50.00
Rear Panel sealant	\$ 50.00	\$ 50.00
Rear Panel clips	\$ 50.00	\$ 50.00
	Total for SP	\$ 580.00
	Sub-Total for Parts :	\$ 5,924.07

Not \$50.00 45 Jan

Not 50.00 2 Jan

Not 200.00 4 Jan

Not 50.00 X

Not 50.00 X

Not 50.00 X

\$340.00



KGC WORKSHOP PTE LTD

Since 1967

Sincere • Secure • Satisfaction

S.No	Items	Unit Price	Amount
1	To disassemble, replace, cut, weld, knock out dents to straighten accident parts and repair parts, inclusive of replacement parts.		1,200.00 ^{400/-}
2	To spray paint on all accident damage parts and other accident		1,200.00 ^{400/-}
3	Insurance (claimant bought coffee and prepare bring it to work place (on the way) unfortunately coffee spill in car floor due to the impact		250.00 ^{250/-} X
4	Labour to remove and refit rear tailgate windscreen (2man job)		180.00 ^{120/-}
5	To dismantle existing tailgate mechanism to new tailgate		200.00 ^{60/-}
6	To refit rear parking sensor and conduct safe distance setting		100.00 ^{50/-}
7	To install locking system to facilitate repair and refit the same		100.00 ^{20/-} 20
8	Apply roofing on the adjacent panels		100.00 ^{30/-}

TOTAL AMOUNT : 3,330.00
OVERALL COST : 9,254.07