

SNH 1229 T.

TP SMRT.

Toyota Noah 1787cc.

VERON.

ZWR900013340.

Rear Number Plate.	} NH NR	30(SN) X
Rear Number Plate Holder		30(SN) X
Rear Bumper	Dented	1389.70 /
Rear Bumper Clips.	NR	30(SN) 50(SN) /
Rear Bumper Side Holder x 2	Dented	45.5 x 2 = 91. /
Rear Bumper Reflector x 2	NH	124.1 x 2 = 248.20 X
Rear Bumper Top Moulding.	NR	250(SN) 280(SN) /
Rear Bumper Impact Bracket x 2.	NH NR	65.1 x 2 = 130.20 X
Reverse Sensor (4 piece set)	Damaged	400(SN) 350(SN) /
Rear End Panel.	Dented	785.40 /
Rear End Panel Top Garnish.	Dented	249.10 /
Rear End Panel Top Garnish Clips.	NR	20(SN) /
Rear End Panel Sealant.	NR	60(SN) /
Rear End Panel Antenna Sensor.	Damaged	198.40 /

SNH 1229 T.

Tailgate	Dented	1985.90	✓
Tailgate Lock	Dented	364.10	✓
Tailgate Weatherstripe	Int	338.40	✓
Tailgate Inner Trim Board	Crushed	685.90	✓
Tailgate Inner Trim Board clips	per	30(SN)	✓
Tailgate Emblem	per	59.40	✓
Tailgate Glass Moulding	per	184.40	✓
Tailgate Glass Sealant		60(SN)	✓
Rear Fender Inner Trim Board x 02	per	795.1 x 2 = 1590.20	✓
Rear Fender Inner Trim Board clips	per	60(SN) x	✓
Floor Panel Top Board	Deformed	694.50	✓

7026.20

5269.65

S.N: 800

SNA 1229T.

Panel Beating	1200 800
Spray Painting.	1200 800
Wiring.	50 30
To apply tuff coat.	150 60
To remove reverse sensor.	100 50
To remove rear camera.	100 50
To remove upholstery.	150 80
To remove tailgate glass	180 120
To transfer tailgate fittings.	150 60.

total: 8119.65

4/5: 6.5k

06 days

6.5k.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: