

C SG/AT S23 060405/T vy3

1/20/2023

[illegible]



Main Office : No. 22, Jalan Klang, Singapore 159419
Tel: 6476 3333 Fax: 6271 6891

Service Centre : Block 1008, Bukit Merah Lane 3,
#01-04/06/08/115, Singapore 159722
Tel: (65) 6476 3333 (8 Lines) Fax: (65) 6270 8314
www.mova.com.sg
GST Reg. No: M2-0088884-2

Mova Spray Centre
2K Oven Spray Painting System

Power-M Automotive Pte Ltd
Specialise In Car Air-con Services,
Car Audio & Hi-Fi System.

Hilton Car Rental Centre
Hilton Auto Trading
Dealing In New/Used Cars, Hire Purchase & Insurance.



INSURER:

Allianz Insurance Singapore Pte. Ltd. (HQ)

PARTICULARS OF CLAIM

Claim Type:	OD (Own Damage)	Ref. No:	
Policy No:	SP20002755290-001	Date of Loss:	09/01/2023
Vehicle Reg. No.:	SME6378R	Driveable?	
Driver Age/Info:		Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	ANG TENG CHANG		
Make/Model:	TOYOTA VIOS, 1.5 (A)	Vehicle Reg. Date:	10/10/2018
Vehicle Colour:	Red		
Engine No:	2NR5268541	Chassis No:	MR2B23F3701146968
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	7		
Present Location:	MOVA AUTOMOTIVE PTE LTD (BUKIT MERAH)		

COST OF CLAIMS	Amount
Parts	8,234.80
Miscellaneous Items	0.00
Labour	2,720.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (\$)	10,954.80
+ GST 8.00% (\$)	876.38
Nett Amount (\$)	11,831.18

This claim is handled by: ONG

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 10 Jan 2023)
 Parts: 143 TOYOTA VIOS 1.5 (A) (Catalogue:Merimen Singapore 1.0)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: Mova Automotive Pte Ltd/SME6378R/10/01/2023 16:04
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount	
1	1		*FRONT WINDSCREEN LAMINATED GLASS	0.00	0.00	*380.00 F	cu
2	1		*FRONT WINDSCREEN MOULDING	0.00	0.00	*52.00 F	na
3	1		*FRONT WINDSCREEN SEAL	0.00	0.00	*48.00 F	na
4	1		*FRONT WINDSCREEN SEALANT	0	0.00	*40.00 FS	na
5	1		*FRONT WINDSCREEN IU BRACKET	0	0.00	*20.00 FS	na
6	1		*FRONT WIPER AIR GRILLE	0.00	0.00	*320.00 F	de
7	1		*FRONT WIPER AIR GRILLE SIDE COVER LH	0.00	0.00	*55.00 F	mis
8	1		*FRONT WIPER AIR GRILLE SIDE COVER RH	0.00	0.00	*55.00 F	mis
9	1		*FRONT WIPER AIR GRILLE CLIPS	0	0.00	*30.00 FS	na
10	1		*FRONT BONNET	0.00	0.00	*395.00 F	bt
11	1		*FRONT BONNET HINGE LH	0.00	0.00	*48.00 F	bt
12	1		*FRONT BONNET HINGE RH	0.00	0.00	*48.00 F	bt
13	1		*FRONT BONNET LOCK	0.00	0.00	*65.00 F	bt
14	1		*FRONT BONNET LOCK STAY PANEL	0.00	0.00	*68.00 F	bt
15	1		*FRONT SUPPORT PANEL	0.00	0.00	*420.00 F	bt
16	1		*FRONT SUPPORT PANEL UPPER COVERING	0.00	0.00	*145.00 F	de
17	1		*FRONT SUPPORT PANEL UPPER COVERING CLIPS	0	0.00	*30.00 FS	na
18	1		*FRONT BUMPER	0.00	0.00	*240.00 F	de
19	1		*FRONT BUMPER SIDE RETAINER BRACKET LH	0.00	0.00	*58.00 F	de
20	1		*FRONT BUMPER SIDE RETAINER BRACKET RH	0.00	0.00	*58.00 F	de
21	1		*FRONT BUMPER CENTER GRILLE	0.00	0.00	*48.00 F	de
22	1		*FRONT BUMPER LOWER GRILLE	0.00	0.00	*125.00 F	de
23	1		*FRONT BUMPER FOG LAMP WIRING HARDNESS	0.00	0.00	*295.00 F	na
24	1		*FRONT DEFLECTOR COVER TOP LH	0.00	0.00	*68.00 F	de
25	1		*FRONT DEFLECTOR COVER LOWER LH	0.00	0.00	*65.00 F	de
26	1		*FRONT DEFLECTOR COVER TOP RH	0.00	0.00	*68.00 F	de
27	1		*FRONT DEFLECTOR COVER LOWER RH	0.00	0.00	*65.00 F	de
28	1		*FRONT HEADLAMP LH	0.00	0.00	*270.00 F	cu
29	1		*FRONT HEADLAMP RH	0.00	0.00	*270.00 F	cu
30	1		*FRONT HEADLAMP UPPER PANEL LH	0.00	0.00	*78.00 F	bt
31	1		*FRONT HEADLAMP UPPER PANEL RH	0.00	0.00	*78.00 F	bt
32	1		*FRONT GRILLE	0.00	0.00	*90.00 F	cu
33	1		*FRONT GRILLE EMBLEM	0.00	0.00	*48.00 F	na
34	1		*FRONT GRILLE CLIPS	0	0.00	*30.00 FS	na
35	1		*FRONT AIR CLEANER ASSY	0.00	0.00	*395.00 F	cu
36	1		*FRONT RADIATOR	0.00	0.00	*550.00 F	?
37	1		*FRONT RADIATOR FAN ASSY	0.00	0.00	*340.00 F	?
38	1		*FRONT RADIATOR FAN GUARD	0.00	0.00	*128.00 F	?
39	1		*FRONT RADIATOR COOLANT	0	0.00	*50.00 FS	?
40	1		*FRONT AIRCOND CONDENSOR	0.00	0.00	*560.00 F	bt
41	1		*FRONT AIRCOND LIQUID TUBE	0.00	0.00	*340.00 F	?
42	1		*FRONT AIRCOND PIPE	0.00	0.00	*372.00 F	?
43	1		*FRONT FENDER LH	0.00	0.00	*280.00 F	Rx
44	1		*FRONT FENDER RH	0.00	0.00	*280.00 F	bt
45	1		*FRONT FENDER INNER LINER CLIPS LH & RH	0	0.00	*40.00 FS	na
46	1		*FRONT DOOR RH / LH REPAIR	0.00	0.00		Rx

F=Franchise part, S=SpocNet.

Sub Total (\$\$)	7,508.00
+ Margin on L,N Items 10.00% (\$\$)	726.80
Total Parts (\$\$)	8,234.80

Mova Automotive Pte Ltd/SME6378R/10/01/2023 16:04. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No Particulars

		Lab.Type	Amount	
<u>Labour Items</u>				
1	TO REMOVE & REPLACE, REFIT FRONT WINDSCREEN GLASS, FRONT WINDSCREEN MOULDING, FRONT WINDSCREEN SEALANT & ETC	New	120.00	✓
2	TO REMOVE, REPLACE, REFIT FRONT RADIATOR, AIR COND CONDENSOR, AIRCOND PIPE, AIRCOND TUBING, RADIATOR FAN ASSY & ETC. TO EFFECT REPLACE OF FRONT SUPPORT PANEL	New	120.00	100
3	TO REMOVE & REPLACE FRONT FOG LAMP WIRING HARDNESS & ETC. BACK TO ORIGINAL OPERATION	New	100.00	50
4	TO REMOVE & REPLACE, REFIT, REPAIR & CHISEL FRONT ACCIDENT AREAS SUCH AS FRONT BONNET, FRONT SUPPORT PANEL, FRONT BUMPER, FRONT FENDER LH & RH, F/DOOR LH & RH & LH & ETC. BACK TO ORIGINAL CONDITIONS	New	800.00	600
5	TO SUPPLY PAINT & FURNISHING MATERIALS AT FRONT BONNET, FRONT SUPPORT PANEL, FRONT FENDER LH & RH, FRONT BUMPER, FRONT DOOR LH & RH & ETC	New	1,400.00	1200
6	TO REFILL AIRCOND GAS & VACUUM	New	100.00	✓
7	TO CHECK WIRING & ELECTRICAL SYSTEM	New	80.00	40
			Gross Labour Cost (S\$)	2,720.00

Mova Automotive Pte Ltd/SME6378R/10/01/2023 16:04. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Tanjim 97495749
 wpt 16/1/23 c 1030
 Not authorised Ex \$ 600
 Plf Remny before paint
 tanjim@khant.com
 7 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: