

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI23000408/AVP3Q2**Date:** 14/07/2023**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNA00138302201
Claimant Vehicle No :	SKQ228R	Insured Vehicle No :	XE6832R
Date of Loss:	07/01/2023	Nature of Claim:	TP
		Claim No:	SNM23D200306/C02/TOHHS

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKQ228R		
Make & Model:	MERCEDES-BENZ E250, 2.0 (A)	Engine No:	27492030063989
Reg. Date:	04/09/2014 (Man. Year: 2013)	Chassis No:	WDD2120362A804293
Colour:	Silver	Odometer:	227151 km
Engine Capacity:	1991 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	245/40 R18	Rear Tyre Size:	245/40 R18
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,019.00	6,901.10	3,117.90	31.12
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,050.00	1,230.00	820.00	40.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	12,069.00	8,131.10	3,937.90	32.63
Approved Total (Overridden) (S\$)		6,500.00		
Nett Amount (S\$)	12,069.00	6,500.00	5,569.00	46.14

INSPECTION

Date of Assignment:	11/01/2023		
Date Inspected:	12/01/2023	Inspected At:	1 KAKI BUKIT AVE 6 #01-27/01-45 SINGAPORE 417883 Repairer:Fong Motors (HQ)
Estimated Period of Repair:	3.0 days		

Adjuster: ADRIAN LING**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 14 Jul 2023)
Parts:	143	MERCEDES-BENZ E250 2.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKQ228R)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*HEAD LAMP	Cracked	6,043.00 F	*5,302.00 FL
2	1		*BUMPER SIDE RETAINER	Damaged	28.00 F	*28.00 FL
3	1		*BUMPER SENSOR	Damaged	313.00 F	*313.00 FL
4	1		*RH FRONT FENDER	Repair	1,251.00 F	*- FL
5	1		*FRONT BUMPER	Deformed	1,738.00 F	*1,738.00 FL
6	1		*BUMPER SPONGE	Not Necessary	358.00 F	*- FL
7	1		*FENDER UNDERGARNISH	Deformed	198.00 F	*198.00 FL
8	1		*FRONT BUMPER CLIP	Necessary	60.00 FS	*50.00 FS
9	1		*FENDER UNDER GARNISH CLIPS	Necessary	30.00 FS	*30.00 FS
					Sub Total (\$\$)	10,019.00 7,659.00
					- List Item Discount on L Items 0.00/10.00% (\$\$)	0.00 757.90
					Total Parts (\$\$)	10,019.00 6,901.10

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK AND KNOCK AFFECTED PARTS	New	800.00	500.00
2	TO SPRAY FENDER ,BUMPER AND ALL AFFECTED AREAS	New	800.00	500.00
3	TO REMOVE AND REFIT FRONT BUMPER SENSOR	New	200.00	50.00
4	WIRING	New	50.00	30.00
5	TO PERFORM DIANOGSTIC TEST	New	200.00	150.00
Gross Labour Cost (S\$)			2,050.00	1,230.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >