

TP Chinn.
Veron.

FONG MOTORS				
1 Kaki Bukit Ave 6 #01-27/45				
AutoBay@ Kaki Bukit, Singapore 417883				
Tel: 6748 5648, Email: fongmotors@gmail.com				
Estimate of Cost of Repairs				
		Date	3-Feb-2023	
		Vehicle No.	SKQ228R	
		Model	Mercedes E250	
		CHASSIS/ENG#	WDD2120362A804293	
PARTS				
S/N	Item	Quantity	Unit Price	Amount
1	Head Lamp <i>cracked.</i>	1	\$6,043.00	\$6,043.00 5302
2	Bumper Side Retainer <i>2nd</i>	1	\$28.00	\$28.00 ✓
3	Bumper Sensor <i>2nd</i>	1	\$313.00	\$313.00 ✓
4	RH Front Fender <i>Repair</i>	1	\$1,251.00	\$1,251.00 X.
5	Front Bumper <i>Dehnd.</i>	1	\$1,738.00	\$1,738.00 ✓
6	Bumper Sponge <i>new</i>	1	\$358.00	\$358.00 X
7	Fender Undergarnish <i>Dehnd</i>	1	\$198.00	\$198.00 ✓
			Sub-total 1	\$9,929.00
NETT ITEMS				
S/N	Item	Quantity	Unit Price	Amount
1	Front Bumper Clip <i>new</i>	1	\$60.00	\$60.00 30
	Fender undergarnish clips <i>new</i>	1	30	30 ✓
			Sub-total 2	\$60.00
LABOUR				
1	To change and knock affected parts		\$800.00	500
2	To spray fender, bumper and all affected areas		\$800.00	500
3	To remove and refit r <i>front bumper sensor</i>		\$200.00	X 50.
4	<i>wiring</i>	30		
5	<i>To perform diagnostic test</i>	150		
			Labour Total	\$1,800.00
			Parts & Labour Total	\$11,789.00

7579
6821.10

80

1230.

total: 8731.10.

?? c/s: 6.5k.

03 Days.

6.5k

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:

Signature:

Date: