

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD (TP) WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: SMJ 4139B
 at Workshop m/s: Spendwell 2
 of _____
 Insured: SA 8618C
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)
 Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 659k
 IDAC Accident Rpt: _____ Consistent?: Yes or No
 GIA / PR Seen: _____ Consistent?: Yes or No
 Est. Repairs: 7 days Res.: Yes or No
 Lum Sum: 20 % 3 Val.: Yes or No
 CA / REV / REP. / 24 HRS 0841
 Date: _____ Person Contacted: LIA 610729
 Vehicle: IN / OUT

Veh No: SMJ 4139B Yr Regn: 04/03/19
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or GA
 Make: 121A STONICORP c.c. 998
 Colour: Silver A/C: Insured / Std / NI / NA
 Sp. Reading: 27236 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: KNAD 6811VK 6243225
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Modi: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 185/65 R15
 R: _____
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or
 Front R/Bal. 7 mm Rear R/Bal. 7 mm
 L/Bal. 7 mm L/Bal. 7 mm
 D.O.A. 11/01/23 D.O.I. 12/1/23
 Survey held at _____
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
Rear
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>22/1/23 22/1/23 21/1/23 21/1/23</u>
<u>1/2/23</u>	<u>4/5 @ 6800 insured ker.</u>

Date/Time, File Pass to? : Preli. Report
 : Final Report
 1) _____
 Date/Time, File Return to? _____

Days Of Repair: _____
 Resurvey No. of Trip: _____

Add Fee: : Site Insp (\$ _____)
 : Interview (\$ _____)
 : Tech. Invs (\$ _____)
 : Weekend (\$ _____)

Survey Fee: _____
 Transportation: _____ S + RS, SI
 Photos _____
 Others _____
 TOTAL _____

Report Format : _____
 Lump Sum / I.B.I: (\$ _____)

MS: A0 Tony

not Admitt
dln
17/1/23
2/5 @ 6800/
Tony

SPEEDWERKZ PRIVATE LIMITED

1 KAKI BUKIT AVENUE 6 , #01-73 , AUTOBAY , SINGAPORE 417883

Tel: 96195936 / info@speedwerkz.biz

VEHICLE NUMBER: SMJ4139B
MAKE & MODEL: KIA STONIC
DOA: 11/1/2023
CLAIM TYPE: TP CLAIM

ESTIMATION QUOTE

PARTS	QTY	PRICE (\$)	REMARKS
REAR TAIL GATE	1	\$1,366.00	Body PD ✓
REAR TAIL GATE EMBLEM (TGDI)	48 1	\$78.00	neu ✓
REAR TAIL GATE EMBLEM (STONIC)	52 1	\$62.50	neu ✓
REAR TAIL GATE LOGO	1	\$65.00	neu ✓
REAR TAIL GATE LAMP @469.30	2	\$938.60	11 X
REAR TAIL GATE LOCK	106 1	\$321.70	Twi ✓
REAR TAIL GATE LOCK CATCH	1	\$62.50	11 X
REAR TAIL GATE INNER BOARD	336 1	\$489.20	del/tra ✓
REAR TAIL GATE HINGE @99.30	2	\$198.60	11 X
REAR TAIL GATE ABSORBER @369.50	2	\$739.00	11 X
REAR TAIL GATE STOPPER @29.50	2	\$59.00	11 X
REAR NUMBER PLATE LAMP @77.30	2	\$154.60	11 X
REAR TAIL GATE WEATHER STRIP	1	\$341.70	11 X
END PANEL	345 1	\$925.00	Body PD ✓
END PANEL TOP GARNISH	208 1	\$786.00	Twi ✓
TAIL LAMP @1386.20	240 X 2 = 480 2	\$2,772.40	one ✓
TAIL LAMP PANEL @327.00	2	\$654.00	R X
REAR FENDER @1429	2	\$2,858.00	R X
REAR FENDER ARCH GARNISH @195.20	2	\$390.40	11 X
REAR FENDER INNER TRIM @366	2	\$732.00	11 X
REAR WINDSCREEN MOULDING	110. 1	\$210.30	neu ✓
REAR AIR VENT	1	\$101.50	11 X
REAR BUMPER	741 1	\$1,486.00	Dis ✓
REAR BUMPER SIDE BRACKET	1	\$85.70	neu ✓
REAR BUMPER DIFFUSER	385 1	\$425.00	Dis ✓
REAR BUMPER REINFORCEMENT	415 1	\$782.30	neu ✓
REAR BUMPER REINFORCEMENT BRACKET @78	2	\$156.00	neu ✓
REAR BUMPER SPONGE	1	\$183.50	neu ✓
REAR CORNER BUMPER @185	152 X 2 = 304 2	\$370.00	neu ✓
REAR BUMPER PARKING SENSOR @197	189 X 2 = 378 4	\$788.00	short spec
REAR BUMPER REFLECTOR @165	135 X 2 = 270 2	\$330.00	neu ✓
REAR BUMPER PARKING SENSOR HARDNESS WIRE	1	\$189.00	11 X
REAR BUMPER LOWER COVER <i>Towing</i>	30 1	\$78.80	neu ✓
REAR LUGGAGE PANEL	557 1	\$686.00	crumpled/buc ✓
REAR EXHAUST SILENCER	1	\$896.00	11 X
REAR EXHAUST CHROME PIPE @185.30	2	\$370.60	11 X
REAR EXHAUST RUBBER @29.30	2	\$58.60	11 X

\$21,191.50

Less 10 %

\$2,119.15

Sub Total

\$19,072.35

SPECIAL NETT ITEMS	QTY	PRICE (\$)	REMARKS
REAR WINDSCREEN GLASS SEALANT	1	\$150.00	neu 40
REAR NUMBER PLATE (RED PLATE) INCLUDE INSPECTION	1	\$160.00	neu 50
REAR END PANEL SEALANT	1	\$350.00	neu 50
REAR FENDER COWLING CLIPS @5.00	20	\$100.00	11 X
REAR BUMPER LOWER CLIPS @ 5	30 1 set	\$50.00	neu 30

Sub Total

\$810.00

LABOUR CHARGE	QTY	PRICE (\$)	REMARKS
TO CHECK WIRING		\$200.00	20
TUFF KOTE		\$200.00	90
REMOVE AND REFIX UPHOLTERY AND ROOF LINING		\$260.00	80
REMOVE AND REPLACE EXHAUST PIPE		\$160.00	11 X
REMOVE AND REFIX REAR WINDSCREEN GLASS		\$150.00	120
REMOVE AND REFIX REVERSING SENSOR		\$150.00	50
TO REMOVE AND REPLACE SPARE PARTS AND PANEL BEATING		\$2,000.00	1100
TO SPRAY PAINTING AND ETC		\$1,800.00	1100

Sub Total \$4,920.00

Grand Total \$24,802.35

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

2-6435-70
 102
 5792-13
 170
 2560
 8522-13
 6817