

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

		Affiliated to Federation Inter	rnationale Des Experts En A	utomo	hile oosus	
	AXA INSURANCE			Ref:	U33/A3	M22006017/ 000017/Rty3
	8 SHENTON WAY			ote:		05/01/2023
	AXA TOWERSING		D	ale.	<del>2-1/00/202</del> 2	00/01/2020
			C	Code:	ASM	
		Policy Particul	ars :- (THIRD PARTY C	CLAIN	1)	
	Insured Veh.	SHC 3193 X	Veh. Inspected		FBS 4503R	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	S2M03ZM0	Excess (\$)		0.00	
	Assign_From	NYI (SEAH ONG)	Assign Date		2 <del>4/00/2022</del>	05/01/2023
•		Vehicle F	Particulars & Condition	n		
	Make & Model		c.c		0	
	Engine No.	HIDDEN	Year of Reg.			
	Chassis No.		Colour			
	Odometer	-	Steering			
	Brakes		Modification			
	General					
		Co	nditions of Tyres			
		Size	Make		Balance	
	R/H Front Tyre				mm	
	L/H Front Tyre				mm	
	R/H Rear Tyre				mm	
	L/H Rear Tyre				mm	
•		Desc	ription of Damages			
	General Information					
	Accident Date	24/06/2022	Inspection Date		24/06/2022	
	Survey held at	SERVE YOU MOTOR SER	RVICE			
	BLK 5033 ANG MO KIO IND PK 2 #01-265 SINGAPORE 569536					
a.			Remarks			
	B) THE REPAIR E	ON WAS CONDUCTED ON A STIMATE WAS NOT PRESE VAS TOLD TO PREPARE TH EASE FIND DAMAGED VEH	ENTED AT THE TIME OF II HE ESTIMATE.	E" BAS INSPE	IS. CTION.	