

Vehicle Damage Assessment Report for [SMM3952K]

Estimate Created: 10/03/2023 15:17 by Insurlogic 4 (Insurlogic_Pte_Ltd)

Owned: 10/03/2023 15:54 by Insurlogic 4 (Insurlogic_Pte_Ltd)

General Information

Insurance Company	ERGO	Claim Number
Claim Type	TP	
Workshop	LKK_Auto_Consultants_Pte_Ltd	Reference Number

Vehicle Information

Brand	Kia	Model	Cerato
Engine Type			
License Plate Number	SMM3952K	VIN (or Chassis #)	

Vehicle Condition

Damaged Diagram	Odometer	0.00 Km
	Tyres Condition	
	Front Left	mm
	Front Right	mm
	Rear Left	mm
	Rear Right	mm

Comments

- FINAL REVIEW BASED ON INFORMATION PROVIDED BY LKK:
CONCLUDED THE COST OF REPAIR AT \$6,300.00 WITH 6 WORKING
DAYS

Insurlogic 4 (10/03/2023 15:54)

Parts

Description	Number/Type	Qty	Cost	Markup/Disc.%	Sum
LH headlamp HID		1	2210.00	-10.00 %	1,989.00
LH headlamp bottom retainer		1	53.00	-10.00 %	47.70
LH headlamp clips		1	10.00	-10.00 %	9.00
front bumper		1	872.00	-10.00 %	784.80
LH front bumper side retainer		1	39.00	-10.00 %	35.10
front bumper clips		1	30.00	-10.00 %	27.00
front bumper badge		1	58.00	-10.00 %	52.20
front bumper reinforcement		1	460.00	-10.00 %	414.00
front bumper sponge		1	129.00	-10.00 %	116.10
front bumper lower garnish skirt		1	712.00	-10.00 %	640.80
LH front bumper signal lamp		1	152.00	-10.00 %	136.80
LH front bumper side garnish		1	139.00	-10.00 %	125.10
LH front bumper sensor (original)		1	195.00	-10.00 %	175.50
LH front bumper sensor holder		1	46.00	-10.00 %	41.40
LH front fender		1	471.00	-10.00 %	423.90
LH front fender inner shield		1	156.00	-10.00 %	140.40
LH front fender inner shield clips		1	30.00	-10.00 %	27.00
LH front lower arm		1	385.00	-10.00 %	346.50
LH front knuckle arm		1	392.00	-10.00 %	352.80
LH front wheel bearing		1	165.00	-10.00 %	148.50

Parts Subtotal 6,033.60

Materials

Description	Number/Type	Qty	Cost	Markup/Disc.%	Sum
LH front wheel spot rim		1.0	500.00	0.00 %	500.00

Materials Subtotal 500.00

Labor**Replace/RnR**

Description	Type	Cost	Markup/Disc %	Price
-------------	------	------	---------------	-------

Panel beating	RnR	500.00	0.00 %	500.00
Checking wiring	RnR	30.00	0.00 %	30.00
Anti rush	RnR	30.00	0.00 %	30.00
Remove and install front under carriage	RnR	150.00	0.00 %	150.00
To check four wheel alignment	RnR	80.00	0.00 %	80.00
To reset and erase fault code system sensor	RnR	100.00	0.00 %	100.00

Paint

Description	Paint Type	Cost	Markup/Disc %	Price
Spray painting	Full spray	500.00	0.00 %	500.00
Labor Rate	S\$ 50 / Hour			
			General Labor Subtotal	890.00
			Paint Labor Subtotal	500.00
			Labor Subtotal	1,390.00

Summary

Repair Cost	7,923.60
Discount(20 %)	(1,584.72)
	6,338.88
Excess	(0.00)
GST(0.00 %)	0.00
Grand Subtotal	6,338.88