

ASM. - PS by STAVE
 - Rasul PRS.



LEE APPRAISAL SERVICES

220A Sumang Lane #06-75 (S)821220 Business Reg. No.: 53387981K
 Tel: 9101 7844 Fax: 6996 6442 Email: dylanlee.as@gmail.com

Loss Adjuster, Automotive Inspection, Evaluation & Consultation

Our Reference : TP/2206/FBT2305D/CKM

ASSESSMENT FOR REPAIR : FBT2305D

Qty	Description	Condition	Repairer's Estimate	Our Assessment	
1 pc	Handle bar	Usable	98.00	~ X	nn
1 pc	Lever LH	Usable	28.00	~ X	nn
1 pc	Lever RH	Cut	28.00	28.00	✓
1 set	Mirror	RH Grazed	110.00	110.00	✓
1 pc	: Front cover complete	Cut	112.00	112.00	✓
1 pc	Front stay	Bent	65.00	65.00	X nn
2 pcs	Fork assy @377.00	Bent	754.00	754.00	✓ X local repair #100 (SN)
1 pc	Fork under bracket	Bent	194.00	194.00	✓ X SIC
1 pc	Front fender complete	Cut	123.00	123.00	✓
1 pc	Inner shield	Deformed	108.00	108.00	✓
2 pcs	Leg shield side cover assy @139.00	Grazed / Cracked	278.00	278.00	✓
1 pc	Front board RH	Cut	83.00	83.00	✓
1 set	Floor mat RH	Necessary	32.00	32.00	✓
1 pc	Floor board side mole RH	Cut	68.00	68.00	✓
1 pc	Pillion footrest RH	Cut	45.00	45.00	✓
2 pcs	Rear side cover complete @82.00	Cut / Come in a set	164.00	164.00	✓
2 pcs	Rear shock absorber @211.00	Distorted / Sounded	422.00	422.00	X nn
1 pc	Exhaust muffler assy	Dented	485.00	485.00	✓
1 pc	Exhaust muffler gasket	Necessary	14.00	14.00	✓
1 pc	Muffler protector	Cut	86.00	86.00	✓
			3,297.00	3,171.00	2684
		Less 10%	329.70	317.10	-10%
			2,967.30	2,853.90	2415.60

Special Nett Items

1 set	Steering cone & bearing	Necessary	100.00	80.00	✓
1 pc	Battery, Yuasa YTZ6V	Unable to recharge	59.00	59.00	X nn
1 pc	Rear top box	Cut	255.00	255.00	220 ✓ 150 wear and tear
1 pc	Rear rack	Bent	150.00	120.00	100 ✓ X 11
			564.00	514.00	400

Total Parts

3,531.30 3,367.90

Labour Charges

1	Towing fee	80.00	60.00	✓ 40
2	Align steering components	100.00	80.00	✓ 60
3	Renew damaged parts & repair affected areas	450.00	400.00	300 ✓
		630.00	540.00	

3255.60

440

L/S - 2604.48
 = 2600

4 days