



Your Ref: 23.30366

Date: 28<sup>th</sup> March 2023

Our Ref: CS3/ASM22005987/Rqp3m4-1

**M/s HSBC Life (Singapore) Pte Ltd**

C/o Seah Ong & Partners LLP  
36 Robinson Road #12-03 City House  
Singapore 068877  
(The Motor Claims Department)

Dear Sir / Madam,

**EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: FBT 2305D  
INSURED VEHICLE: SHA 5220Z  
ACCIDENT DATE: 20/06/2022**

We thank you for your instruction on 06/01/2023.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of FBT 2305D from Lee Appraisal Services.
- b) Singapore Accident Statement of Vehicles FBT 2305D and SHA 5220Z.
- c) Police Report of Vehicles FBT 2305D.
- d) Final Repair Bill of FBT 2305D from M/s Check Kong Motor Co.
- e) Colour damaged vehicle photographs of FBT 2305D.

Pre-Repair Inspection Date: 23/06/2022 at M/s Check Kong Motor, 387B Woodlands Road, Yew Tee Industrial Estate, Singapore 677948.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number : FBT 2305D  
Make & Model : Yamaha Aerox 155 Connected  
Year of Registration : 2021  
Chassis Number : MH3SG6410MJ038661  
Engine Capacity : 155 cc

2. We recommend that the repairs of the entire damage require about 4 (Four) working days to complete.
3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.