

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
 GST:201001158E RCB NO:201001158E

SKK1788R
 TP/SMRT

M/S : SMRT AUTOMOTIVE SERVICES PTE LTD
 60 WOODLANDS INDUSTRIAL PARK E4
 SINGAPORE 757705

Estimate No: ES2300040/YISHUN
 Date: 12 Jan 2023
 Policy No: 5123902353-01
 Veh Reg No: SKK1788R
 Make/Model: TOYOTA TOYOTA VIOS
 J AUTO
 Chassis No: MR053HY9305081831
 Engine No: 1NZX808177
 Reg. Date: 10/12/2008

TEL: 64823888 FAX: 63687421
 ATTN: Motor Claim Department *Not within*

WS Ref: TP/SMRT *6/1/2023*
 Claim Type: Third Party *Money After Repair*
 Accident Date: 30/12/2022 *9 days*
 TP Veh Reg No: SMB3592Z

Estimate Repair Cost to Vehicle No :SKK1788R

Description	U/Price	Quantity	List Price	Amount
			S\$	S\$
List Price				
1 FRONT LH DOOR	1,188.20	1 PC	<i>R</i> 1,188.20	<i>✓</i>
2 FRONT LH DOOR BLACK TAPE	63.20	1 PC	<i>M</i> 63.20	<i>✓</i>
3 FRONT LH DOOR OUTER HANDLE	<i>Not in it</i> 196.10	1 PC	<i>.</i> 196.10	<i>✓</i>
4 FRONT LH DOOR OUTER HANDLE KNOB	48.80	1 PC	<i>M</i> 48.80	<i>✓</i>
5 FRONT LH DOOR OUTER HANDLE KNOB GASKET	19.80	1 PC	<i>M</i> 19.80	<i>✓</i>
6 FRONT LH DOOR GLASS OUTER MOULDING	118.90	1 PC	<i>Not in it</i> 118.90	<i>✓</i>
7 FRONT LH DOOR GLASS REGULATOR	248.70	1 PC	248.70	<i>?</i>
8 FRONT LH DOOR INNER LOCK	388.20	1 PC	388.20	<i>?</i>
9 LH CENTRE PILLAR	512.30	1 PC	<i>R</i> 512.30	<i>X</i>
10 REAR LH DOOR BLACK TAPE	67.80	1 PC	<i>M</i> 67.80	<i>✓</i>
11 REAR LH DOOR OUTER HANDLE	192.80	1 PC	<i>M</i> 192.80	<i>✓</i>
12 REAR LH DOOR GLASS OUTER MOULDING	129.10	1 PC	<i>Bu</i> 129.10	<i>✓</i>
13 REAR LH DOOR GLASS REGULATOR	221.80	1 PC	221.80	<i>?</i>
14 REAR LH DOOR GLASS REGULATOR MOTOR	324.80	1 PC	324.80	<i>?</i>
15 REAR LH DOOR INNER LOCK	339.80	1 PC	339.80	<i>?</i>
16 REAR LH FENDER	999.40	1 PC	<i>Bu/Bu</i> 999.40	<i>✓</i>
17 REAR WINDSCREEN GLASS MOULDING	79.40	1 PC	<i>M</i> 79.40	<i>✓</i>
18 REAR BUMPER	503.20	1 PC	<i>Bu/M</i> 503.20	<i>✓</i>
19 REAR BUMPER CLIPS	3.50	6 PCS	<i>M</i> 21.00	<i>✓</i>
20 REAR BUMPER LH RETAINER	89.70	1 PC	<i>Bu</i> 89.70	<i>X</i>
21 REAR LH DOOR	1,021.70	1 PC	<i>R</i> 1,021.70	<i>✓</i>
			6,774.70	
		Less 25%	1,693.68	5,081.03
Special Net				
22 REAR LH DOOR SUN VISOR	120.00	1 PC	<i>M</i> 120.00	<i>Done</i>
23 REAR WINDSCREEN GLASS SEALANT	40.00	1 PC	<i>M</i> 40.00	<i>✓</i>
24 LH SIDE SKIRT	320.00	1 PC	<i>R</i> 320.00	<i>X</i>
			480.00	480.00

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
 GST:201001158E RCB NO:201001158E

M/S : SMRT AUTOMOTIVE SERVICES PTE LTD
 60 WOODLANDS INDUSTRIAL PARK E4
 SINGAPORE 757705

TEL: 64823888 FAX: 63687421
 ATTN: Motor Claim Department

WS Ref: TP/SMRT
 Claim Type: Third Party
 Accident Date: 30/12/2022
 TP Veh Reg No: SMB3592Z

Estimate No: ES2300040/YISHUN
 Date: 12 Jan 2023
 Policy No: 5123902353-01
 Veh Reg No: SKK1788R
 Make/Model: TOYOTA TOYOTA VIOS
 J AUTO
 Chassis No: MR053HY9305081831
 Engine No: 1NZX808177
 Reg. Date: 10/12/2008

Estimate Repair Cost to Vehicle No :SKK1788R

Description	U/Price	Quantity	List Price S\$	Amount S\$
Labour				
25 REMOVE AND REFIX REAR WINDSCREEN GLASS	120.00	1 LA	120.00	✓
26 REMOVE & INSTALL MID INTERIOR TRIMS,GARNISHES,SEATS AND CARPET, ETC	120.00	1 LA	120.00	100
27 REMOVE LH MID DAMAGED DOORS,REAR BUMPER,CUT OUT LH CENTRE PILLAR,REAR FENDER. PANEL BEAT & REPAIR LH PILLAR INNER PANEL,LH REAR INNER WHEEL HOUSE. REPAIR REAR BUMPER,REALIGN,REPLACE & WELDING BODY PANELS,TRANSFER BOTH LH DOORS PARTS	1,400.00	1 LA	1,400.00	1000
28 SPRAY PAINTING - BOTH LH DOORS,OUTER HANDLE & KNOBS,CENTRE PILLAR,LH REAR FENDER,FUEL TANK DOOR,REAR BUMPER & INNER PANELS,LH SIDE SKIRT	1,400.00	1 LA	1,400.00	1200
29 REPAIR AND RESPRAY LH REAR ALLOY WHEEL RIM	100.00	1 LA	100.00	800
30 RUSTPROOFING	100.00	1 LA	100.00	90
			3,240.00	3,240.00
			Total	S\$ 8,801.03
			Add GST @ 8%	704.08
			Total Amount Payable	S\$ 9,505.11

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before ~~after~~ spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE

SC1122CU005 / CHENG HOE MOTOR PTE LTD(768761)
 DATE & TIME: 30/12/2022 18:18 (SGT)
 SUBMITTED BY: CHIONG BENG CHOON
 SESSION: 1 (30/12/2022 18:18 (SGT))

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission 30/12/2022 18:18 (SGT)
 Reported by Driver
 Date of Accident 30/12/2022 10:40 (SGT)
 Exact Location of Accident Singapore
 Additional Location Information EUNOS ROAD 2
 Country/State of Loss Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number SKK1788R

INSURED/POLICYHOLDER

Is company? No
 Name Of Registered Owner ANG NGOH ENG
 NRIC No SXXXX873A
 Email Address angteckgee@gmail.com
 Mobile Phone No (Phone) +65-98585999
 Alternative Phone No -

VEHICLE PARTICULARS

Manufacturer Toyota
 Model VIOS J AUTO
 Variant -
 Exact purpose for which vehicle was being used at time of accident Private use
 Are you claiming under your own insurance policy for repair to your vehicle? No - Claiming third party
 Vehicle Category Private car
 Transmission Auto
 CC 1497

INSURANCE COMPANY

Name of Insurance Company Income Insurance Limited
 Policy Number / Cover Note Number 5123902353-01

DRIVER


Name of Driver ZHONG YONGHUI
 NRIC No SXXXX484H
 Date Of Birth 25/06/1992
 Occupation Indoor

Circumstance of the Accident

NOTE PLEASE TAKE NOTE THAT YOUR INSURER HAVE 14DAYS TIME FRAME for you to submit OWN DAMAGE Claim under your Own Comprehensive policy. Pls check your policy for more information.

- () Claim Own Policy (/) Claim Third party () Reporting Only
- () Claim OD/ TP at other workshop ()

Sketch Plan



DOA: 30/12/22 10.40am

I was having driving tuition with my instructor (Mr Ang Teck Gee) seated beside me. I was going straight (Eunos Road 2), SMB3592Z dashed out from bus interchange without stopping & collided onto left portion of my car.

Declaration

I/We declare the foregoing particulars are true in every respect.

Zhang Yonghu

Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

(YS) Ong 30/12/22
 Witnessed by Reporting Centre Personnel
 (Name as in NRIC/ID card)