

MY CAR CONSULTANT PTE LTD

Reg no.: 201605878Z

Address: NO:60 JALAN LAM HUAT CARROS CENTRE #05-68 5737869

HP: 98888885

Estimation

Date:

2/2/2023

Vehicle:

SND9061C

Make / Model:

HYUNDAI IONIQ

Chassis No:

No.	Description	Unit	Unit Price	Amount
Parts Replacement:				
1	REAR BUMPER	1	\$ 798.00	\$ 798.00
2	REAR BUMPER SIDE RETAINER RH	1	\$ 112.00	\$ 112.00
3	REAR FENDER RH	1	\$ 512.00	\$ 512.00
4	REAR DOOR RH	1	\$ 1,259.00	\$ 1,259.00
				\$ 2,681.00
			Less 20%	\$ 536.20
			Total	\$ 2,144.80
S/Nett items:				
1	REAR BUMPER CLIPS SET	1	\$ 50.00	\$ 50.00
2	REAR DOOR INNER TRIM CLIPS SET	1	\$ 50.00	\$ 150.00
				\$ 200.00
Labour to:				
1	TO CHECK ELECTRICAL WIRING	1	\$ 150.00	\$ 150.00
2	REMOVE AND REFIX FRONT DOOR MECHANISM	2	\$ 150.00	\$ 300.00
3	APPLY ANTI RUST ON AFFECTED AREAS	1	\$ 100.00	\$ 100.00
4	SPRAY PAINTING ON AFFECTED AREAS	1	\$ 600.00	\$ 600.00
5	PANEL BEATING ON AFFECTED AREAS	1	\$ 600.00	\$ 600.00
				\$ 1,750.00
Parts Replacement Amount				\$ 2,344.80
Total Amount for Labour				\$ 1,750.00
Total Amount				\$ 4,094.80

107460
?X
Pent.
XVNV
972
444
194.4
77.60
XVNV
XVNV
XVNV
XVNV
400
400

1577.60
27 = 315.52
3 days = 1262.08
L/S
2/2/23
1130 am
90097659

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: