

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI23000428/UNP3Q2**Date:** 30/01/2023**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMB1SNW00004172200		
Claimant Vehicle No :	FBG361Y	Insured Vehicle No :	PC7821X		
Date of Loss:	30/12/2022	Nature of Claim:	TP	Claim No:	SNM23D200022/C02/KHONGLH

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	FBG361Y		Engine No:	KC11E2015543
Make & Model:	HONDA CBF150, 149cc (M)		Chassis No:	LALKC11A2A3462043
Reg. Date:	24/02/2012 (Man. Year: 2010)		Odometer:	19999 km
Colour:	Black			
Engine Capacity:	149 cc			
Market Value/New Car Price:	N/A			
Sum Insured (S\$):	Market Value/New Car Price			

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	90-80-18	Rear Tyre Size:	3.60-18
Front Left Side:	Vee Rubber 7 mm	Rear Left Side:	Vee Rubber 7 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,817.00	2,117.70	699.30	24.82
Miscellaneous Items	0.00	0.00	0.00	
Labour	470.00	300.00	170.00	36.17
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	3,287.00	2,417.70	869.30	26.45
Approved Total (Overridden) (S\$)		1,900.00		
Nett Amount (S\$)	3,287.00	1,900.00	1,387.00	42.20

INSPECTION

Date of Assignment:	12/01/2023		
Date Inspected:	12/01/2023	Inspected At:	FT FASTTRACK (HQ) 25 KAKI BUKIT RD 4 #01-77 S417800 Singapore 417800
Estimated Period of Repair:	4.0 days		

Adjuster: MARCUS CHUA**Manager:** HUEY YON

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 30 Jan 2023)	
Parts:	N/A	HONDA CBF150 149cc (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for FBG361Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*HANDLE BAR	Bent	130.00 FL	*130.00 FL
2	1		*BALANCER (RH)	Scratched	30.00 FL	*30.00 FL
3	1		*BRAKE LEVER	Scratched	35.00 FL	*35.00 FL
4	1		*MIRROR (RH)	Cut	48.00 FL	*48.00 FL
5	1		*VISOR	Cracked	62.00 FL	*62.00 FL
6	1		*HEADLAMP	Cracked	175.00 FL	*175.00 FL
7	1		*HEADLAMP BRACKET	Repair	175.00 FL	*- FL
8	1		*COVER(LH)	Cracked	165.00 FL	*165.00 FL
9	1		*COVER(RH)	Cut	165.00 FL	*165.00 FL
10	2		*FRONT SIGNAL LAMP (LH)&(RH)	Cracked	96.00 FL	*96.00 FL
11	1		*FRONT FENDER	Cut	97.00 FL	*97.00 FL
12	1		*METER ASSY }	Cracked	399.00 FL	*399.00 FL
13	1		*METER PANEL }		75.00 FL	*- FL
14	1		*SIDE COVER (RH)	Cut	115.00 FL	*115.00 FL
15	1		*BODY COVER (RH)	Cut	68.00 FL	*68.00 FL
16	1		*FRONT & REAR FOOTREST (RH)	O/S Torn	84.00 FL	*42.00 FL
17	1		*BRAKE PEDAL	Bent	48.00 FL	*48.00 FL
18	1		*EXHAUST PIPE	Dented/ Bent	420.00 FL	*420.00 FL
19	1		*EXHAUST COVER	Scratched	58.00 FL	*58.00 FL
20	1		*TOP BOX	Cut	220.00 FL	*200.00 FL
21	1		*TANK	Repair	465.00 FL	*- FL

F=Franchise part. L=ListItemDisc.

Sub Total (S\$)	3,130.00	2,353.00
- List Item Discount on L Items 10.00/10.00% (S\$)	313.00	235.30
Total Parts (S\$)	2,817.00	2,117.70

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TRANSPORT FEE (2 WAY)	New	90.00	0.00
2	LABOUR CHARGE	New	380.00	300.00
Gross Labour Cost (S\$)			470.00	300.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >