

F.T.FASTTRACK

25 KAKI BUKIT ROAD 4 #01-77 SYNERGY @ KB SINGAPORE 417800

TEL : 6749 1002

FAX : 6385 2138

RCB REG NO.: 50233100C

Email : freddietan2010@gmail.com

CHINA TAIPING INSURANCE SINGAPORE PTE LTD

3 ANSON ROAD

#16-00 SPRINGLEAF TOWER

SINGAPORE 079909

TEL : 6389 6111

FAX: 6389 6153

ATTN : CLAIM DEPT

DATE : 10/01/2023

REF NO : SF0C23160002

VEH NO.: FBG361Y

HONDA CBF150

Claim Ref: SNM23D200022/Khuong LH
orc - Lynn Khong

RE : ESTIMATION FOR ACCIDENT INVOLING VEH NO. FBG361Y / PC7821X ON 30/12/2022.

ITEM	QTY	DESCRIPTION	PRICE(S\$)
1	1	HANDLE BAR <i>Best</i>	130.00
2	1	BALANCER (RH) <i>Scr</i>	30.00
3	1	BRAKE LEVER <i>Scr</i>	35.00
4	1	MIRROR (RH) <i>cu7</i>	48.00
5	1	VISOR <i>one</i>	62.00
6	1	HEADLAMP <i>cu7</i>	175.00
7	1	HEADLAMP BRACKET <i>R</i>	175.00
8	1	COVER (LH) <i>one</i>	165.00
9	1	COVER (RH) <i>cu7</i>	165.00
10	2	FRONT SIGNAL LAMP (LH)&((RH))@\$48.00 <i>cu7</i>	96.00
11	1	FRONT FENDER <i>cu7</i>	97.00
12	1	METER ASSY <i>cu7</i>	399.00
13	1	METER PANEL <i>compute</i>	75.00
14	1	SIDE COVER (RH) <i>cu7</i>	115.00
15	1	TANK <i>220 120 R</i>	465.00
16	1	BODY COVER (RH) <i>cu7</i>	68.00
17	2	FRONT & REAR FOOTREST (RH)@\$42.00 <i>0/5/10m</i>	84.00
18	1	BRAKE PEDAL <i>341</i>	48.00
19	1	EXHAUST PIPE <i>20/24</i>	420.00
20	1	EXHAUST COVER <i>scr</i>	58.00
21	1	TOP BOX <i>cu7</i>	220.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

TOTAL PARTS 3,130.00
LESS 10% 313.00
TOTAL 2,817.00

LABOUR & MISC

TRANSPORT FEE (2 WAY) *117* 90.00

LABOUR CHARGE 380.00

GRAND TOTAL : 3,287.00



AUTHORISED SIGNATURE

not Allowed
12/1/23
who 2nd After 12/1
4 hrs

1/5 \$1900

2353