

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG23000436/RVP3E2**Date:** 04/05/2023**REFERENCE**

Insured/Claimant: JACQUELINE EMMA D/O CHARLES CHRISTIAN

Policy No: 7210063619

Date of Loss: 10/01/2023

Nature of Claim: OD Claim No: 3361991185SG

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SNA4150C**

Make & Model: AUDI A3, 1.5 SEDAN TFSI S TRONIC (18") (A)

Engine No: DFY263535

Reg. Date: 22/06/2021 (Man. Year: 2021)

Chassis No: WAUZZZGYXMA089991

Colour: Blue

Odometer: 20169 km

Engine Capacity: 1498 cc

Market Value/New Car Price: S\$143,000.00

Price:

Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/45 R17

Rear Tyre Size: 225/45 R17

Front Left Side: Pirelli 6 mm

Rear Left Side: Pirelli 6 mm

Front Right Side: Pirelli 6 mm

Rear Right Side: Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	35,192.00	13,231.60	21,960.40	62.40
Miscellaneous Items	0.00	0.00	0.00	
Labour	29,652.00	12,187.00	17,465.00	58.90
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	64,844.00	25,418.60	39,425.40	60.80
- Excess (S\$)	400.00	400.00	0.00	0.00
(S\$)	64,444.00	25,018.60	39,425.40	61.18
+ GST 8.00/8.00% (S\$)	5,155.52	2,001.49	3,154.03	61.18
Nett Amount (S\$)	69,599.52	27,020.09	42,579.43	61.18

INSPECTION

Date of Assignment: 13/01/2023

Date Inspected: 12/01/2023 Inspected At:

24 Benoi Sector

Repairer: Premium Automobiles Pte Ltd

Estimated Period of Repair: 16.0 days

Adjuster: MOHD RASUL**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FENDER	Not Necessary	1,313.00 FS	*- FS
2	3		*FRONT FENDER RIVET	Not Necessary	12.00 FS	*- FS
3	1		*FRONT FENDER CLOSING ELEMENT - RH	Not Necessary	34.00 FS	*- FS
4	1		*FRONT FENDER INSULATION - RH	Not Necessary	51.00 FS	*- FS
5	1		*FRONT FENDER CLOSING ELEMENT - RH	Not Necessary	39.00 FS	*- FS
6	1		*FRONT WHEEL HOUSING LINER - RH	Not Necessary	198.00 FS	*- FS
7	1		*FRONT SIDE PANEL - RH	Bent	3,886.00 FS	*3,108.80 FS
8	1		*FRONT DATA TAG	Not Necessary	545.00 FS	*- FS
9	1		*FRONT TYRE PRESSURE DATA PLATE	Not Necessary	45.00 FS	*- FS
10	1		*REAR WINDOW HEATED	Necessary	850.00 FS	*679.60 FS
11	1		*REAR QUARTER WINDOW - RH	Necessary	653.00 FS	*522.00 FS
12	2		*WINDOW PRIMER	Necessary	47.00 FS	*37.60 FS
13	1		*REAR FUEL FILLER FLAP	Not Necessary	102.00 FS	*- FS
14	1		*REAR WHEEL HOUSING LINER - RH	Not Necessary	281.00 FS	*- FS
15	1		*REAR WHEEL SPOILER - RH	Not Necessary	34.00 FS	*- FS
16	1		*FRONT DOOR - RH	Buckled	3,269.00 FS	*2,615.20 FS
17	1		*FRONT DOOR OUTER SEAL - RH	Necessary	189.00 FS	*150.80 FS
18	1		*FRONT DOOR ATTACHMENT PARTS	Not Necessary	361.00 FS	*- FS
19	1		*FRONT DOOR CATCH	Not Necessary	99.00 FS	*- FS
20	1		*FRONT DOOR HINGE HALF UPPER PART - RH UPPER	Not Necessary	51.00 FS	*- FS
21	1		*FRONT DOOR HINGE HALVES - RH UPPER	Not Necessary	56.00 FS	*- FS
22	1		*FRONT DOOR HINGE HALF UPPER PART - RH LOWER	Not Necessary	54.00 FS	*- FS
23	1		*FRONT DOOR HINGE HALF LOWER PART - RH LOWER	Not Necessary	57.00 FS	*- FS
24	1		*FRONT DOOR INNER SELA	Not Necessary	189.00 FS	*- FS
25	1		*FRONT DOOR OUTER HANDLE WITH SENSOR - RH	Not Necessary	187.00 FS	*- FS
26	1		*FRONT DOOR HANDLE TRIM PLATE - RH	Necessary	246.00 FS	*196.80 FS
27	1		*FRONT DOOR CAP - RH	Scratched	39.00 FS	*30.48 FS
28	1		*FRONT DOOR LOCK CYLINDER HOUSING - RH	Not Necessary	543.00 FS	*- FS
29	1		*FRONT DOOR UNDERLAY - RH FRONT	Necessary	7.00 FS	*5.04 FS
30	1		*FRONT DOOR UNDERLAY - RH REAR	Necessary	8.00 FS	*6.08 FS
31	1		*FRONT DOOR MOUNTING BAR - RH	Not Necessary	180.00 FS	*- FS
32	1		*FRONT DOOR BOWDEN CABLE	Not Necessary	64.00 FS	*- FS
33	1		*FRONT EXTERIOR WING MIRROR MOUNTING - RH	Scratched	726.00 FS	*580.40 FS
34	1		*FRONT WING MIRROR GLASS - RH	Not Necessary	811.00 FS	*- FS
35	1		*FRONT WING MIRROR CAP - RH	Scratched	190.00 FS	*152.00 FS
36	1		*FRONT DOOR CORNER TRIM - RH	Not Necessary	58.00 FS	*- FS
37	1		*FRONT WINDOW SLOT SEAL TRIM STRIP - RH OUTER	Not Necessary	274.00 FS	*- FS
38	1		*FRONT WINDOW GUIDE TRIM STRIP - RH	Not Necessary	314.00 FS	*- FS
39	1		*FRONT WINDOW GUIDE - RH	Not Necessary	314.00 FS	*- FS
40	1		*FRONT PILLAR B TRIM - RH	Not Necessary	133.00 FS	*- FS
41	1		*FRONT WINDOW APERTURE SEAL - RH INNER	Not Necessary	106.00 FS	*- FS
42	1		*FRONT DOOR WINDOW - RH	Cut	175.00 FS	*139.60 FS
43	1		*FRONT DOOR LOCK - RH	Not Necessary	490.00 FS	*- FS
44	1		*FRONT DOOR STRIKER	Not Necessary	117.00 FS	*- FS
45	1		*FRONT WINDOW REGULATOR - RH	Not Necessary	266.00 FS	*- FS
46	1		*FRONT WINDOW REGULATOR MOTOR - RH	Not Necessary	354.00 FS	*- FS
47	1		*FRONT DOOR CONTROL UNIT - RH	Not Necessary	449.00 FS	*- FS
48	1		*FRONT DOOR TRIM - RH	Not Necessary	2,279.00 FS	*- FS
49	1		*SET FRONT DOOR WIRING	Not Necessary	648.00 FS	*- FS
50	1		*FRONT DOOR TRIM PANEL WIRING HARNESS	Not Necessary	169.00 FS	*- FS
51	1		*REAR DOOR	Buckled	2,609.00 FS	*2,087.20 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
52	1		*REAR DOOR OUTER SEAL - RH	Necessary	189.00 FS	*150.80 FS
53	1		*REAR DOOR ATTACHMENT PARTS	Not Necessary	283.00 FS	*- FS
54	1		*REAR DOOR CATCH	Not Necessary	99.00 FS	*- FS
55	1		*REAR DOOR HINGE HALF UPPER PART - RH UPPER	Not Necessary	51.00 FS	*- FS
56	1		*REAR DOOR HINGE HALVES - RH UPPER	Not Necessary	51.00 FS	*- FS
57	1		*REAR DOOR HINGE HALF UPPER PART - RH LOWER	Not Necessary	54.00 FS	*- FS
58	1		*REAR DOOR HINGE HALF LOWER PART - RH LOWER	Not Necessary	57.00 FS	*- FS
59	1		*REAR DOOR INNER SEAL	Not Necessary	189.00 FS	*- FS
60	1		*REAR OUTER DOOR HANDLE WITH SENSOR - RH	Not Necessary	187.00 FS	*- FS
61	1		*REAR DOOR HANDLE TRIM PLATE - RH	Cut	246.00 FS	*149.20 FS
62	1		*REAR DOOR HOUSING - RH	Not Necessary	59.00 FS	*- FS
63	1		*REAR DOOR HANDLE BASE - RH	Not Necessary	183.00 FS	*- FS
64	1		*REAR DOOR BOWDEN CABLE	Not Necessary	96.00 FS	*- FS
65	1		*REAR DOOR LOCK - RH	Not Necessary	703.00 FS	*- FS
66	1		*REAR DOOR STRIKER	Not Necessary	117.00 FS	*- FS
67	1		*REAR WINDOW REGULATOR - RH	Bent	266.00 FS	*212.40 FS
68	1		*REAR WINDOW REGULATOR MOTOR - RH	Not Necessary	332.00 FS	*- FS
69	1		*REAR DOOR CONTROL UNIT	Not Necessary	471.00 FS	*- FS
70	1		*REAR WINDOW GUIDE - RH	Not Necessary	314.00 FS	*- FS
71	1		*REAR WINDOW GUIDE TRIM STRIP	Not Necessary	180.00 FS	*- FS
72	1		*REAR WINDOW SLOT SEAL TRIM STRIP	Not Necessary	333.00 FS	*- FS
73	1		*REAR QUARTER WINDOW GUIDE RAIL - RH	Not Necessary	55.00 FS	*- FS
74	1		*REAR WINDOW APERTURE SEAL - RH INNER	Not Necessary	106.00 FS	*- FS
75	1		*REAR PILLAR B TRIM - RH	Not Necessary	139.00 FS	*- FS
76	1		*REAR PILLAR C TRIM - RH	Not Necessary	168.00 FS	*- FS
77	1		*REAR DOOR TRIM - RH	Not Necessary	2,207.00 FS	*- FS
78	1		*SET REAR DOOR WIRING	Not Necessary	220.00 FS	*- FS
79	1		*REAR DOOR TRIM PANEL WIRING HARNESS	Not Necessary	103.00 FS	*- FS
80	1		*REAR DOOR WINDOW - RH	Not Necessary	158.00 FS	*- FS
81	1		*REAR ALUMINIUM RIM	Scratched	1,519.00 FS	*1,215.20 FS
82	1		*REAR ALUMINIUM RIM RUBBER VALVE	Necessary	4.00 FS	*3.04 FS
83	1		*ACRYLIC SEALANT	Necessary	180.00 FS	*180.00 FS
84	1		*CAVITY WAX	Necessary	140.00 FS	*140.00 FS
85	1		*STONE CHIP	Necessary	180.00 FS	*180.00 FS
86	1		*METAL FILLER POWDER	Necessary	280.00 FS	*280.00 FS
87	1		*REAR WINDSCREEN SEALANT	Necessary	200.00 FS	*200.00 FS
88	1		*1/4 GLASS SEALANT	Necessary	100.00 FS	*100.00 FS
89	1		*SUNDRIES	Necessary	700.00 FS	*28.72 FS
90	1		*REAR BUMPER GUIDE - RH (Supplementary)	Deformed	66.00 FS	*52.40 FS
91	1		*DOOR BOARD UPPER COVER - RH (Supplementary)	Cracked	36.00 FS	*28.24 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$)	35,192.00	13,231.60
---------------------------	------------------	------------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND REINSTALL REAR PARKING AID AND REAR LID KICK SENSOR. CHECK FUNCTION	New	360.00	0.00
2	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	0.00
3	TO RENEW REAR WINDSCREEN AND RHS REAR 1/4 GLASS TO FACILITATE RENEWAL OF RHS REAR FENDER	New	600.00	600.00
4	TO INSTALL SOLAR FILM FOR ALL THE AFFECTED GLASSES	New	400.00	400.00
5	TO CARRY OUT WATER SEEPAGE FOR REAR WINDSCREEN	New	200.00	150.00
6	TO DISLodge AND REINSTALL REAR WIRE HARNESS FOR LIGHTS, BATTERY MANAGER, FUSE AND RELAY TRAYS, ELECTRICAL AND AUDIO EQUIPMENT. INSPECT FOR DAMAGE AND RENEW WHERE NECESSARY	New	1,400.00	1,400.00
7	TO REMOVE AND REINSTALL REAR SEAT, BACK REST, HAT TRAY, CD PILLAR TRIMS, LUGGAGE COMPARTMENT TRIMS. DISLodge ROOF LINER AND DISENGAGE CURTAIN AIRBAG ETC	New	1,400.00	1,400.00
8	TO REMOVE AND REINSTALL RHS FRONT SEAT ASSY, AB PILLAR TRIMS, SILL TRIMS, FLOOR CARPETS, ELECTRONIC COMPONENTS AND FUSE TRAYS	New	1,800.00	0.00
9	TO REMOVE AND TRANSFER RHS FRONT DOOR AND RHS REAR DOORS MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPCET FOR DAMAGES	New	700.00	700.00
10	TO CARRY OUT FIRST MEASUREMENT ON CAR-O-LINER	New	800.00	0.00
11	TO SETUP THE VEHICLE ON CAR-O-LINER TO FACILITATE THE REPAIR	New	2,400.00	0.00
12	TO DISMANTLE AND REINSTALL REAR BUMPER AND FRONT BUMPER. TO RENEW RHS FRONT FENDER, RHS FRONT DOOR AND RHS REAR DOOR. TO CUT OUT AND WELD RHS A-PILLAR, RHS B-PILLAR, RHS SILL PANEL AND RHS REAR FENDER. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	11,900.00	4,000.00
13	TO RESPRAY RHS FRONT FENDER, RHS FRONT DOOR, RHS REAR DOOR, DOOR HINGES, RHS WING MIRROR COVER, 2 DOOR HANDLES, RHS A-PILLAR, RHS B-PILLAR, RHS SILL PANEL, RHS REAR FENDER, RHS SILL PANEL, ROOF CHANNEL, DRAIN CHANNEL, DOOR ENTRANCES AND REAR END PANELLING	New	6,500.00	3,025.00
14	TO RENEW RHS REAR RIM. TO CARRY OUT PRE/POST WHEEL ALIGNMENT	New	520.00	320.00
15	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (\$)			29,652.00	12,187.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >