

55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS  
WORKSHOP : UBI ROAD 1  
CONTACT NO : 6366 2323  
FAX NO : 6841 1183  
REFERENCE : PA/OD/0032/2023/EQ  
DATE : 11-Jan-23  
WIP : 58498

**VEHICLE IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 12/1/2023**

**AIG Asia Pacific Insurance Pte Ltd**

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Motor Claims Dept

**Tel: 6880 4602 - Fax: 6880 4838**

OWNER'S NAME : MS JACQUELINE EMMA D/O CHARLES CHRISTIAN  
ADDRESS : 198 DEPOT ROAD  
#12-37  
SINGAPORE 109693  
TELEPHONE : HP +65 94377266  
TYPE OF CLAIM : OWN DAMAGE CLAIM  
POLICY NO : 7210063619-01  
VEHICLE NO : SNA 4150 C  
MODEL CODE : AUDI A3 SEDAN 1.5 TFSI  
MODEL YEAR : 22/6/2021  
ENGINE NO : DFY 263535  
CHASSIS NO : WAUZZZGYXMA089991  
MILEAGE : 20,169  
DATE IN : 10-Jan-23  
ESTIMATED BY : JOHNNY BOO / ALLAN WU  
ACCIDENT DATE : 10-Jan-23  
PLACE OF ACCIDENT : KPE TOWARDS CITY BEFORE EXIT 9A

55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

**ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SNA 4150 C**

| S/N                         | NATURE OF JOBS                                                                                                                                                               |        | ESTIMATED<br>CHARGES  | SURVEYOR'S<br>RECOMMENDATIONS |
|-----------------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------|-----------------------|-------------------------------|
| 1                           | TO REMOVE AND REINSTALL REAR PARKING AID AND REAR LID KICK SENSOR. CHECK FUNCTION.                                                                                           | S/N \$ | 360.00                | X n                           |
| 2                           | TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.                             | S/N \$ | 480.00                | X n n                         |
| 3                           | TO RENEW REAR WINDSCREEN AND RHS REAR 1/4 GLASS TO FACILITATE RENEWAL OF RHS REAR FENDER.                                                                                    | S/N \$ | 600.00                | / ✓                           |
| 4                           | TO INSTALL SOLAR FILM FOR ALL THE AFFECTED GLASSES.                                                                                                                          | S/N \$ | 400.00                | / ✓                           |
| 5                           | TO CARRY OUT WATER SEEPAGE FOR REAR WINDSCREEN.                                                                                                                              | S/N \$ | <del>200.00</del> 150 | / ✓                           |
| 6                           | TO DISLODGE AND REINSTALL REAR WIRE HARNESS FOR LIGHTS, BATTERY MANAGER, FUSE AND RELAY TRAYS, ELECTRICAL AND AUDIO EQUIPMENT. INSPECT FOR DAMAGE AND RENEW WHERE NECESSARY. | S/N \$ | 1,400.00              | / ✓                           |
| <b>TOTAL LABOUR CHARGES</b> |                                                                                                                                                                              | :      | \$ <b>3,440.00</b>    | 2550                          |

# PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

## ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SNA 4150 C

| S/N                  | NATURE OF JOBS                                                                                                                                                                                                                                                                  | ESTIMATED CHARGES     | SURVEYOR'S RECOMMENDATIONS |
|----------------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------------------|----------------------------|
| 7                    | TO REMOVE AND REINSTALL REAR SEAT, BACK REST, HAT TRAY, CD PILLAR TRIMS, LUGGAGE COMPARTMENT TRIMS. DISLODGE ROOF LINER AND DISENGAGE CURTAIN AIRBAG ETC.                                                                                                                       | S/N \$ 1,400.00       | ✓                          |
| 8                    | TO REMOVE AND REINSTALL RHS FRONT SEAT ASSY, AB PILLAR TRIMS, SILL TRIMS, FLOOR CARPETS, ELECTRONIC COMPONENTS AND FUSE TRAYS.                                                                                                                                                  | S/N \$ 1,800.00       | X <sup>na</sup>            |
| 9                    | TO REMOVE AND TRANSFER RHS FRONT DOOR AND RHS REAR DOOR'S MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES.                                                                                                                                                      | S/N \$ 700.00         | ✓                          |
| 10                   | TO CARRY OUT FIRST MEASUREMENT ON CAR-O-LINER.                                                                                                                                                                                                                                  | S/N \$ 800.00         | X <sup>na</sup>            |
| 11                   | TO SETUP THE VEHICLE ON CAR-O-LINER TO FACILITATE THE REPAIR.                                                                                                                                                                                                                   | S/N \$ 2,400.00       | X <sup>na</sup>            |
| 12                   | TO DISMANTLE AND REINSTALL REAR BUMPER AND FRONT BUMPER. TO RENEW RHS FRONT FENDER, RHS FRONT DOOR AND RHS REAR DOOR. TO CUT OUT AND WELD RHS A-PILLAR, RHS B-PILLAR, RHS SILL PANEL AND RHS REAR FENDER. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED. | 500X8<br>\$ 11,900.00 | 4000 ✓                     |
| TOTAL LABOUR CHARGES |                                                                                                                                                                                                                                                                                 | : \$ 19,000.00        | 8650                       |

55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

**ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SNA 4150 C**

| S/N                         | NATURE OF JOBS                                                                                                                                                                                                                                                   | ESTIMATED CHARGES       | SURVEYOR'S RECOMMENDATIONS |
|-----------------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------------------|----------------------------|
| 13                          | TO RESPRAY RHS FRONT FENDER, RHS FRONT DOOR, RHS REAR DOOR, DOOR HINGES, RHS WING MIRROR COVER, 2 DOOR HANDLES, RHS A-PILLAR, RHS B-PILLAR, RHS SILL PANEL, RHS REAR FENDER, RHS SILL PANEL, ROOF CHANNEL, DRAIN CHANNEL, DOOR ENTRANCES AND REAR END PANELLING. | @550X5.5<br>\$ 6,500.00 | 3025 ✓                     |
| 14                          | TO RENEW RHS REAR RIM. TO CARRY OUT PRE/POST WHEEL ALIGNMENT.                                                                                                                                                                                                    | S/N \$ 520.00           | 320 ✓                      |
| 15                          | TO CARRY OUT DIAGNOSTIC CHECK.                                                                                                                                                                                                                                   | S/N \$ 192.00           | ✓                          |
| <b>TOTAL LABOUR CHARGES</b> |                                                                                                                                                                                                                                                                  | <b>\$ 29,652.00</b>     | 3537                       |



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

## MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SNA 4150 C

|                       |                                                         |     | DAMAGED PARTS & PRICES |                |
|-----------------------|---------------------------------------------------------|-----|------------------------|----------------|
| S/N                   | PARTS DESCRIPTION                                       | QTY | S/NETT                 | REMARKS        |
| 1                     | FRONT FENDER <i>Xm</i>                                  | 1   | \$ 1,313.00            |                |
| 2                     | FRONT FENDER RIVET <i>Xm</i>                            | 3   | \$ 12.00               |                |
| 3                     | FRONT FENDER CLOSING ELEMENT - RH <i>Xm</i>             | 1   | \$ 34.00               |                |
| 4                     | FRONT FENDER INSULATION - RH <i>Xm</i>                  | 1   | \$ 51.00               |                |
| 5                     | FRONT FENDER CLOSING ELEMENT - RH <i>Xm</i>             | 1   | \$ 39.00               |                |
| 6                     | FRONT WHEEL HOUSING LINER - RH <i>Xm</i>                | 1   | \$ 198.00              |                |
| 7                     | FRONT SIDE PANEL - RH <i>64-</i>                        | 1   | \$ 3,886.00            | <i>3108.80</i> |
| 8                     | FRONT DATA TAG <i>Xm</i>                                | 1   | \$ 545.00              |                |
| 9                     | FRONT TYRE PRESSURE DATA PLATE <i>Xm</i>                | 1   | \$ 45.00               |                |
| 10                    | <i>rear</i> FRONT WINDOW HEATED <i>new</i>              | 1   | \$ 850.00              | <i>679.60</i>  |
| 11                    | <i>rear</i> FRONT QUARTER WINDOW - RH <i>new</i>        | 1   | \$ 653.00              | <i>528</i>     |
| 12                    | WINDOW PRIMER <i>new</i>                                | 2   | \$ 47.00               | <i>27.60</i>   |
| 13                    | REAR FUEL FILLER FLAP <i>? Xm</i>                       | 1   | \$ 102.00              |                |
| 14                    | <i>rear</i> FRONT WHEEL HOUSING LINER - RH <i>? Xm</i>  | 1   | \$ 281.00              |                |
| 15                    | <i>rear</i> FRONT WHEEL SPOILER - RH <i>Xm</i>          | 1   | \$ 34.00               |                |
| 16                    | FRONT DOOR - RH <i>bus</i>                              | 1   | \$ 3,269.00            | <i>2615.20</i> |
| 17                    | FRONT DOOR OUTER SEAL - RH <i>new</i>                   | 1   | \$ 189.00              | <i>150.80</i>  |
| 18                    | FRONT DOOR ATTACHMENT PARTS <i>? Xm</i>                 | 1   | \$ 361.00              |                |
| 19                    | FRONT DOOR CATCH <i>? Xm</i>                            | 1   | \$ 99.00               |                |
| 20                    | FRONT DOOR HINGE HALF UPPER PART - RH UPPER <i>? Xm</i> | 1   | \$ 51.00               |                |
| SUB TOTAL SPARE PARTS |                                                         |     | \$ 12,059.00           | <i>7114</i>    |

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

## MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SNA 4150 C

|                       |                                                     |     |        | DAMAGED PARTS & PRICES |          |
|-----------------------|-----------------------------------------------------|-----|--------|------------------------|----------|
| S/N                   | PARTS DESCRIPTION                                   | QTY | S/NETT | REMARKS                |          |
| 21                    | FRONT DOOR HINGE HALVES - RH UPPER ? Xnn            | 1   | \$     | 56.00                  |          |
| 22                    | FRONT DOOR HINGE HALF UPPER PART - RH LOWER ? Xnn   | 1   | \$     | 54.00                  |          |
| 23                    | FRONT DOOR HINGE HALF LOWER PART - RH LOWER ? Xnn   | 1   | \$     | 57.00                  |          |
| 24                    | FRONT DOOR INNER SEAL Xnn                           | 1   | \$     | 189.00                 |          |
| 25                    | FRONT DOOR OUTER HANDLE WITH SENSOR - RH ? Xnn      | 1   | \$     | 187.00                 |          |
| 26                    | FRONT DOOR HANDLE TRIM PLATE - RH n/                | 1   | \$     | 246.00                 | 196.80   |
| 27                    | FRONT DOOR CAP - RH SW/                             | 1   | \$     | 39.00                  | 30.48    |
| 28                    | FRONT DOOR LOCK CYLINDER HOUSING - RH ? Xnn         | 1   | \$     | 543.00                 |          |
| 29                    | FRONT DOOR UNDERLAY - RH FRONT n/                   | 1   | \$     | 7.00                   | 5.04     |
| 30                    | FRONT DOOR UNDERLAY - RH REAR n/                    | 1   | \$     | 8.00                   | 6.08     |
| 31                    | FRONT DOOR MOUNTING BAR - RH ? Xnn                  | 1   | \$     | 180.00                 |          |
| 32                    | FRONT DOOR BOWDEN CABLE ? X nn                      | 1   | \$     | 64.00                  |          |
| 33                    | FRONT EXTERIOR WING MIRROR MOUNTING - RH SW/        | 1   | \$     | 726.00                 | 580.40   |
| 34                    | FRONT WING MIRROR GLASS - RH X nn                   | 1   | \$     | 811.00                 |          |
| 35                    | FRONT WING MIRROR CAP - RH SW/                      | 1   | \$     | 190.00                 | 152      |
| 36                    | FRONT DOOR CORNER TRIM - RH X nn                    | 1   | \$     | 58.00                  |          |
| 37                    | FRONT WINDOW SLOT SEAL TRIM STRIP - RH OUTER ? X nn | 1   | \$     | 274.00                 |          |
| 38                    | FRONT WINDOW GUIDE TRIM STRIP - RH ? X nn           | 1   | \$     | 314.00                 |          |
| 39                    | FRONT WINDOW GUIDE - RH ? X nn                      | 1   | \$     | 314.00                 |          |
| 40                    | FRONT PILLAR B TRIM - RH X nn                       | 1   | \$     | 133.00                 |          |
| SUB TOTAL SPARE PARTS |                                                     |     | :      | \$                     | 4,450.00 |

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
SPARE PARTS ARE SPECIAL NETT.

9708



55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

## MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SNA 4150 C

|                         |                                                                       |     | DAMAGED PARTS & PRICES |         |
|-------------------------|-----------------------------------------------------------------------|-----|------------------------|---------|
| S/N                     | PARTS DESCRIPTION                                                     | QTY | S/NETT                 | REMARKS |
| 41                      | FRONT WINDOW APERTURE SEAL - RH INNER ? <del>nn</del>                 | 1   | \$ 106.00              |         |
| 42                      | FRONT DOOR WINDOW - RH ? <del>nn</del> ✓                              | 1   | \$ 175.00              | 139.60  |
| 43                      | FRONT DOOR LOCK - RH ? <del>nn</del>                                  | 1   | \$ 490.00              |         |
| 44                      | FRONT DOOR STRIKER <del>nn</del>                                      | 1   | \$ 117.00              |         |
| 45                      | FRONT WINDOW REGULATOR - RH ? <del>nn</del>                           | 1   | \$ 266.00              |         |
| 46                      | FRONT WINDOW REGULATOR MOTOR - RH ? <del>nn</del>                     | 1   | \$ 354.00              |         |
| 47                      | FRONT DOOR CONTROL UNIT - RH ? <del>nn</del>                          | 1   | \$ 449.00              |         |
| 48                      | FRONT DOOR TRIM - RH ? <del>nn</del>                                  | 1   | \$ 2,279.00            |         |
| 49                      | FRONT DOOR WIRING SET ? <del>nn</del>                                 | 1   | \$ 648.00              |         |
| 50                      | FRONT DOOR TRIM PANEL WIRING HARNESS ? <del>nn</del>                  | 1   | \$ 169.00              |         |
| 51                      | REAR DOOR <del>nn</del> ✓                                             | 1   | \$ 2,609.00            | 2087.00 |
| 52                      | REAR DOOR OUTER SEAL - RH <del>nn</del> ✓                             | 1   | \$ 189.00              | 150.80  |
| 53                      | REAR DOOR ATTACHMENT PARTS ? <del>nn</del>                            | 1   | \$ 283.00              |         |
| 54                      | REAR DOOR CATCH ? <del>nn</del>                                       | 1   | \$ 99.00               |         |
| 55                      | REAR DOOR HINGE HALF UPPER PART - RH UPPER ? <del>nn</del>            | 1   | \$ 51.00               |         |
| 56                      | REAR DOOR HINGE HALVES - RH UPPER ? <del>nn</del>                     | 1   | \$ 51.00               |         |
| 57                      | REAR DOOR HINGE HALF UPPER PART - RH LOWER ? <del>nn</del>            | 1   | \$ 54.00               |         |
| 58                      | REAR DOOR HINGE HALF LOWER PART - RH LOWER ? <del>nn</del>            | 1   | \$ 57.00               |         |
| 59                      | REAR DOOR INNER SEAL <del>nn</del> X <del>nn</del>                    | 1   | \$ 189.00              |         |
| 60                      | REAR OUTER DOOR HANDLE WITH SENSOR - RH <del>nn</del> ? <del>nn</del> | 1   | \$ 187.00              |         |
| SUB TOTAL SPARE PARTS : |                                                                       |     | \$ 8,822.00            | 2377.60 |

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

## MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SNA 4150 C

|                       |                                                      |     |        | DAMAGED PARTS & PRICES |        |
|-----------------------|------------------------------------------------------|-----|--------|------------------------|--------|
| S/N                   | PARTS DESCRIPTION                                    | QTY | S/NETT | REMARKS                |        |
| 61                    | REAR DOOR HANDLE TRIM PLATE - RH <i>repair ✓ cut</i> | 1   | \$     | 246.00                 | 149.00 |
| 62                    | REAR DOOR HOUSING - RH ? <i>X n</i>                  | 1   | \$     | 59.00                  |        |
| 63                    | REAR DOOR HANDLE BASE - RH ? <i>X n</i>              | 1   | \$     | 183.00                 |        |
| 64                    | REAR DOOR BOWDEN CABLE ? <i>X n</i>                  | 1   | \$     | 96.00                  |        |
| 65                    | REAR DOOR LOCK - RH ? <i>X n</i>                     | 1   | \$     | 703.00                 |        |
| 66                    | REAR DOOR STRIKER <i>X n</i>                         | 1   | \$     | 117.00                 |        |
| 67                    | REAR WINDOW REGULATOR - RH ? <i>X n</i>              | 1   | \$     | 266.00                 | 212.40 |
| 68                    | REAR WINDOW REGULATOR MOTOR - RH ? <i>✓ X n</i>      | 1   | \$     | 332.00                 |        |
| 69                    | REAR DOOR CONTROL UNIT ? <i>X n</i>                  | 1   | \$     | 471.00                 |        |
| 70                    | REAR WINDOW GUIDE - RH ? <i>X n</i>                  | 1   | \$     | 314.00                 |        |
| 71                    | REAR WINDOW GUIDE TRIM STRIP ? <i>X n</i>            | 1   | \$     | 180.00                 |        |
| 72                    | REAR WINDOW SLOT SEAL TRIM STRIP ? <i>X n</i>        | 1   | \$     | 333.00                 |        |
| 73                    | REAR QUARTER WINDOW GUIDE RAIL - RH ? <i>X n</i>     | 1   | \$     | 55.00                  |        |
| 74                    | REAR WINDOW APERTURE SEAL - RH INNER ? <i>X n</i>    | 1   | \$     | 106.00                 |        |
| 75                    | REAR PILLAR B TRIM - RH <i>X n</i>                   | 1   | \$     | 139.00                 |        |
| 76                    | REAR PILLAR C TRIM - RH <i>X n</i>                   | 1   | \$     | 168.00                 |        |
| 77                    | REAR DOOR TRIM - RH ? <i>X n</i>                     | 1   | \$     | 2,207.00               |        |
| 78                    | REAR DOOR WIRING SET ? <i>X n</i>                    | 1   | \$     | 220.00                 |        |
| 79                    | REAR DOOR TRIM PANEL WIRING HARNESS ? <i>X n</i>     | 1   | \$     | 103.00                 |        |
| 80                    | REAR DOOR WINDOW - RH ? <i>X n</i>                   | 1   | \$     | 158.00                 |        |
| SUB TOTAL SPARE PARTS |                                                      |     | :      | \$ 6,456.00            | 361.60 |

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

## MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SNA 4150 C

| S/N                         | PARTS DESCRIPTION                          | QTY | DAMAGED PARTS & PRICES |                |
|-----------------------------|--------------------------------------------|-----|------------------------|----------------|
|                             |                                            |     | S/NETT                 | REMARKS        |
| 81                          | REAR ALUMINIUM RIM <i>3co /</i>            | 1   | \$ 1,519.00            | <i>1215.20</i> |
| 82                          | REAR ALUMINIUM RIM RUBBER VALVE <i>m /</i> | 1   | \$ 4.00                | <i>3.04</i>    |
| 83                          | ACRYLIC SEALANT <i>m /</i>                 | S/N | \$ 180.00              | <i>180</i>     |
| 84                          | CAVITY WAX <i>m /</i>                      | S/N | \$ 140.00              | <i>140</i>     |
| 85                          | STONE CHIP <i>m /</i>                      | S/N | \$ 180.00              | <i>180</i>     |
| 86                          | METAL FILLER POWDER <i>m /</i>             | S/N | \$ 280.00              | <i>280</i>     |
| 87                          | REAR WINDSCREEN SEALANT <i>m /</i>         | S/N | \$ 200.00              | <i>200</i>     |
| 88                          | 1/4 GLASS SEALANT <i>m /</i>               | S/N | \$ 100.00              | <i>100</i>     |
| 89                          | SUNDRIES <i>7 ✓ m /</i>                    |     | \$ 700.00              | <i>287.2</i>   |
| <b>TOTAL SPARE PARTS</b>    |                                            | :   | \$ 35,090.00           |                |
| <b>TOTAL LABOUR CHARGES</b> |                                            | :   | \$ 29,652.00           |                |
| <b>GRAND TOTAL</b>          |                                            | :   | \$ 64,742.00           | <i>2326.96</i> |

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
SPARE PARTS ARE SPECIAL NETT.

# PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME

SURVEYED DATE

AUTHORISED DATE

EXCESS COST

LIABILITY

REMARKS

2nd - HP90010068

12/01/23 @ 1545

16 days

EXCESS: TBA

Revert

Resy before paint

PLEASE NOTE

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,  
PREMIUM AUTOMOBILES PTE LTD

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO  
BODY REPAIR MANAGER

ALLAN WU  
CLAIMS CONSULTANT

# PREMIUM AUTOMOBILES

55 Ubi Road 1, Singapore 408699

Tel: 6366 2323 Fax: 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg



## Supplementary Estimate-1

GST Reg No. 19-9902271-W

**AIG Asia Pacific Insurance Pte Ltd**

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 / Fax: 6256 4315

**Estimate No.**

**Date**

**Service Advisor**

**Pages**

**Regn No**

**Model No**

PA/OD/0032/2023/EQ

1-Feb-23

CHANG

1 of 1

SNA 4150 C

AUDI A3 SEDAN 1.5 TFSI

| Quantity           | Description                 | Unit Price | Amount                 |
|--------------------|-----------------------------|------------|------------------------|
| <b>Parts</b>       |                             |            |                        |
| 1                  | REAR BUMPER GUIDE - RH      | \$ 66.00   | de - 53.40             |
| 2                  | DOOR BOARD UPPER COVER - RH | \$ 36.00   | cur - 28.24            |
| <b>GRAND TOTAL</b> |                             |            | <b>\$ 102.00</b> 80.64 |

For Premium Automobiles Pte Ltd



Authorised Signature

21/2/23 Spw