

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG23000439/ANP3M4**Date:** 03/05/2023**REFERENCE**

Insured/Claimant:	NORMALIS BINTE ALWI	Policy No:	7210059193	
Date of Loss:	06/01/2023	Nature of Claim:	OD	Claim No: 4671524498SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SNA2262B		
Make & Model:	AUDI A3 SPORTBACK, 1.5 TFSI S TRONIC (A)	Engine No:	DFY268691
Reg. Date:	12/06/2021 (Man. Year: 2021)	Chassis No:	WAUZZZGY7MA095134
Colour:	Grey	Odometer:	25928 km
Engine Capacity:	1498 cc		
Market Value/New Car Price:	S\$145,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/45R17	Rear Tyre Size:	225/45R17
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	22,306.00	6,982.64	15,323.36	68.70
Miscellaneous Items	0.00	0.00	0.00	
Labour	18,832.00	5,532.00	13,300.00	70.62
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	41,138.00	12,514.64	28,623.36	69.58
+ GST 8.00/8.00% (S\$)	3,291.04	1,001.17	2,289.87	69.58
Nett Amount (S\$)	44,429.04	13,515.81	30,913.23	69.58

INSPECTION

Date of Assignment:	13/01/2023		
Date Inspected:	12/01/2023	Inspected At:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	7.0 days		

Adjuster: ADRIAN LING**Manager:** HUEY YON

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Distorted	2,026.00 FS	*1,620.80 FS
2	1		*REAR BUMPER FIXING PARTS	Not Necessary	348.00 FS	*- FS
3	2		*REAR BUMPER LOCKING MECHANISM - LH / RH	Not Necessary	34.00 FS	*- FS
4	1		*REAR BUMPER TRIM - RH	Missing	76.00 FS	*60.32 FS
5	1		*REAR PARKING AID SENSOR SUPPORT - RH OUTER	Necessary	30.00 FS	*23.36 FS
6	1		*REAR BUMPER SPOILER	Cut	239.00 FS	*191.20 FS
7	1		*REAR BUMPER REFLECTOR - RH	Cut	39.00 FS	*31.20 FS
8	1		*REAR OUTER TAIL LIGHT - RH	Not Necessary	1,110.00 FS	*- FS
9	1		*REAR OUTER TAIL LIGHT TRIM - RH	Not Necessary	36.00 FS	*- FS
10	1		*REAR INNER TAIL LIGHT - RH	Cut	823.00 FS	*658.40 FS
11	1		*REAR INNER TAIL LIGHT TRIM - RH	Not Necessary	32.00 FS	*- FS
12	1		*REAR AERIAL KEY ACCESS	Not Necessary	80.00 FS	*- FS
13	1		*REAR BUMPER REINFORCEMENT BEAM	Not Necessary	636.00 FS	*- FS
14	1		*REAR BUMPER BRACKET - RH	Not Necessary	34.00 FS	*- FS
15	1		*REAR BUMPER GUIDE SECTION - RH	Damaged	66.00 FS	*52.40 FS
16	1		*REAR PARKING AID SENSOR - OUTER	Damaged	286.00 FS	*228.40 FS
17	1		*REAR PARKING AID SENSOR - INNER	Not Necessary	272.00 FS	*- FS
18	1		*REAR PARKING AID SENSOR - OUTER	Not Necessary	272.00 FS	*- FS
19	4		*REAR PARKING AID SEAL RING	Not Necessary	54.00 FS	*- FS
20	1		*SET REAR BUMPER WIRING	Not Necessary	203.00 FS	*- FS
21	1		*REAR LID	Dented	3,180.00 FS	*2,544.00 FS
22	1		*REAR LID ATTACHMENT PARTS	Not Necessary	567.00 FS	*- FS
23	1		*REAR LID SEAL	Not Necessary	186.00 FS	*- FS
24	1		*REAR LID LOCK	Not Necessary	248.00 FS	*- FS
25	1		*REAR LID FLAP LOCK COVER CAP	Not Necessary	6.00 FS	*- FS
26	1		*PACKING ADHESIVE	Necessary	22.00 FS	*16.88 FS
27	1		*AUDI EMBLEM	Necessary	152.00 FS	*121.60 FS
28	1		*A3 INSCRIPTION	Necessary	110.00 FS	*87.60 FS
29	1		*REAR WINDOW HEATED	Necessary	769.00 FS	*614.80 FS
30	1		*WINDOW PRIMER	Necessary	24.00 FS	*18.80 FS
31	2		*REAR SPOILER - LH / RH	Necessary	360.00 FS	*287.20 FS
32	1		*ADHESIVE TAPES	Necessary	146.00 FS	*116.40 FS
33	1		*ATTACHMENT PARTS	Not Necessary	152.00 FS	*- FS
34	1		*FOAM STRIPS	Not Necessary	121.00 FS	*- FS
35	1		*REAR SIDE PANEL - RH	Repair	4,706.00 FS	*- FS
36	1		*REAR QUARTER WINDOW	Not Necessary	653.00 FS	*- FS
37	1		*WINDOW PRIMER	Not Necessary	24.00 FS	*- FS
38	1		*REAR FUEL FILLER FLAP	Not Necessary	102.00 FS	*- FS
39	1		*REAR VENT TRIM	Not Necessary	81.00 FS	*- FS
40	1		*REAR WHEEL HOUSING LINER - RH	Not Necessary	281.00 FS	*- FS
41	1		*REAR CROSS PANEL	Not Necessary	486.00 FS	*- FS
42	1		*REAR CROSS PANEL REINFORCEMENT	Not Necessary	1,492.00 FS	*- FS
43	2		*REAR CROSS PANEL CONNECTING PLATE - LH / RH	Not Necessary	102.00 FS	*- FS
44	1		*ACRYLIC SEALANT	Not Necessary	180.00 FS	*- FS
45	1		*CAVITY WAX	Not Necessary	140.00 FS	*- FS
46	1		*STONE CHIP	Not Necessary	180.00 FS	*- FS
47	1		*METAL FILLER POWDER	Not Necessary	280.00 FS	*- FS
48	1		*REAR WINDSCREEN SEALANT	Necessary	200.00 FS	*200.00 FS
49	1		*1/4 GLASS SEALANT	Not Necessary	100.00 FS	*- FS
50	1		*REAR NUMBER PLATE	Not Necessary	60.00 FS	*- FS
51	1		*SUNDRIES	Necessary	500.00 FS	*109.28 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) 22,306.00 6,982.64

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND TRANSFER REAR PARKING AID. CHECK FUNCTION	New	280.00	280.00
2	TO REMOVE AND TRANSFER REAR LIDS CONVENIENCE LOCK SYSTEM, WIRE HARNESS FOR TAIL LIGHTS AND REAR LID WIPER ASSY	New	480.00	480.00
3	TO RENEW REAR WINDSCREEN TO FACILITATE RENEWAL OF REAR LID	New	480.00	480.00
4	TO RENEW RHS REAR 1/4 GLASS TO FACILITATE RENEWAL OF RHS REAR FENDER	New	300.00	0.00
5	TO INSTALL SOLAR FILM FOR ALL THE AFFECTED GLASSES	New	400.00	0.00
6	TO CARRY OUT WATER SEEPAGE FOR REAR WINDSCREEN	New	200.00	150.00
7	TO DISLODGE AND REINSTALL REAR WIRE HARNESS FOR LIGHTS, BATTERY MANAGER, FUSE AND RELAY TRAYS, ELECTRICAL AND AUDIO EQUIPMENT. INSPECT FOR DAMAGE AND RENEW WHERE NECESSARY	New	1,400.00	0.00
8	TO REMOVE AND REINSTALL REAR SEAT, BACK REST, HAT TRAY, CD PILLAR TRIMS, LUGGAGE COMPARTMENT TRIMS. DISLODGE ROOF LINER AND DISENGAGE CURTAIN AIRBAG ETC	New	1,400.00	0.00
9	TO DISMANTLE AND RENEW REAR BUMPER AND REAR LID. TO CUT OUT AND WELD RHS REAR FENDER AND REAR END PANELLING. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	7,700.00	1,750.00
10	TO RESPRAY REAR BUMPER, REAR LID, RHS REAR FENDER, RHS SILL PANEL, ROOF CHANNEL, DRAIN CHANNEL, DOOR ENTRANCES AND REAR END PANELLING	New	6,000.00	2,200.00
11	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (S\$)			18,832.00	5,532.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >