

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0030/2023/EQ
DATE : 11-Jan-23
WIP : 58090

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 12/1/2023

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

Hi Adrian

7 days exclude 1 Sunday

Johnny Boo 24 Mar 23

OWNER'S NAME : MS NORMALIS BINTE ALWI
ADDRESS : BLK 404 WOODLANDS STREET 41
#11-74
SINGAPORE 730404
TELEPHONE : HP +65 97521115
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 7210059193
VEHICLE NO : **SNA 2262 B**
MODEL CODE : AUDI A3 SPORTBACK 1.5 TFS
MODEL YEAR : 12/6/2021
ENGINE NO : DFY 268691
CHASSIS NO : WAUZZZGY7MA095134
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 6-Jan-23
PLACE OF ACCIDENT : TPE NEAR PUNGGOL ROAD

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SNA 2262 B

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANSFER REAR PARKING AID. CHECK FUNCTION.	S/N \$	280.00	\$ 280.00
2	TO REMOVE AND TRANSFER REAR LID'S CONVENIENCE LOCK SYSTEM, WIRE HARNESS FOR TAIL LIGHTS AND REAR LID WIPER ASSY.	S/N \$	480.00	\$ 480.00
3	TO RENEW REAR WINDSCREEN TO FACILITATE RENEWAL OF REAR LID.	S/N \$	480.00	\$ 480.00
4	TO RENEW RHS REAR 1/4 GLASS TO FACILITATE RENEWAL OF RHS REAR FENDER.	S/N \$	300.00	
5	TO INSTALL SOLAR FILM FOR ALL THE AFFECTED GLASSES	S/N \$	400.00	\$ 400.00
6	TO CARRY OUT WATER SEEPAGE FOR REAR WINDSCREEN	S/N \$	200.00	\$ 150.00
TOTAL LABOUR CHARGES		:	\$ 2,140.00	\$ 1,790.00

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SNA 2262 B

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
	<i>c/f</i>		\$ 1,790.00
7	TO DISLODGE AND REINSTALL REAR WIRE HARNESS FOR LIGHTS, BATTERY MANAGER, FUSE AND RELAY TRAYS, ELECTRICAL AND AUDIO EQUIPMENT. INSPECT FOR DAMAGE AND RENEW WHERE NECESSARY.	S/N \$ 1,400.00	
8	TO REMOVE AND REINSTALL REAR SEAT, BACK REST, HAT TRAY, CD PILLAR TRIMS, LUGGAGE COMPARTMENT TRIMS. DISLODGE ROOF LINER AND DISENGAGE CURTAIN AIRBAG ETC.	S/N \$ 1,400.00	
9	TO DISMANTLE AND RENEW REAR BUMPER AND REAR LID. TO CUT OUT AND WELD RHS REAR FENDER AND REAR END PANELLING. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 7,700.00	\$ 1,750.00
10	TO RESPRAY REAR BUMPER, REAR LID , RHS REAR FENDER, RHS SILL PANEL, ROOF CHANNEL, DRAIN CHANNEL, DOOR ENTRANCES AND REAR END PANELLING.	\$ 6,000.00	\$ 2,200.00
11	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	\$ 192.00
TOTAL LABOUR CHARGES		: \$ 18,832.00	\$ 5,932.00

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SNA 2262 B

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
1	REAR BUMPER	1	\$ 2,026.00	\$	1,620.80
2	REAR BUMPER FIXING PARTS	1	\$ 348.00		
3	REAR BUMPER LOCKING MECHANISM - LH / RH	2	\$ 34.00		
4	REAR BUMPER TRIM - RH	1	\$ 76.00	\$	60.32
5	REAR PARKING AID SENSOR SUPPORT - RH OUTER	1	\$ 30.00	\$	23.36
6	REAR BUMPER SPOILER	1	\$ 239.00	\$	191.20
7	REAR BUMPER REFLECTOR - RH	1	\$ 39.00	\$	31.20
8	REAR OUTER TAIL LIGHT - RH	1	\$ 1,110.00		
9	REAR OUTER TAIL LIGHT TRIM - RH	1	\$ 36.00		
10	REAR INNER TAIL LIGHT - RH	1	\$ 823.00	\$	658.40
11	REAR INNER TAIL LIGHT TRIM - RH	1	\$ 32.00		
12	REAR AERIAL KEY ACCESS	1	\$ 80.00		
13	REAR BUMPER REINFORCEMENT BEAM	1	\$ 636.00		
14	REAR BUMPER BRACKET - RH	1	\$ 34.00		
15	REAR BUMPER GUIDE SECTION - RH	1	\$ 66.00	\$	52.40
16	REAR PARKING AID SENSOR - OUTER	1	\$ 286.00	\$	228.40
17	REAR PARKING AID SENSOR - INNER	1	\$ 272.00		
18	REAR PARKING AID SENSOR - OUTER	1	\$ 272.00		
19	REAR PARKING AID SEAL RING	4	\$ 54.00		
20	REAR BUMPER WIRING SET	1	\$ 203.00		
SUB TOTAL SPARE PARTS		:	\$ 6,696.00	\$	2,866.08

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APROVED
 SPARE PARTS ARE SPECIAL NETT.

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SNA 2262 B

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
		<i>c/f</i>		<i>\$</i>	<i>2,866.08</i>
21	REAR LID	1	\$ 3,180.00	<i>\$</i>	<i>2,544.00</i>
22	REAR LID ATTACHMENT PARTS	1	\$ 567.00		
23	REAR LID SEAL	1	\$ 186.00		
24	REAR LID LOCK	1	\$ 248.00		
25	REAR LID FLAP LOCK COVER CAP	1	\$ 6.00		
26	PACKING ADHESIVE	1	\$ 22.00	<i>\$</i>	<i>16.88</i>
27	AUDI EMBLEM	1	\$ 152.00	<i>\$</i>	<i>121.60</i>
28	"A3" INSCRIPTION	1	\$ 110.00	<i>\$</i>	<i>87.60</i>
29	REAR WINDOW HEATED	1	\$ 769.00	<i>\$</i>	<i>614.80</i>
30	WINDOW PRIMER	1	\$ 24.00	<i>\$</i>	<i>18.80</i>
31	REAR SPOILER - LH / RH	2	\$ 360.00	<i>\$</i>	<i>287.20</i>
32	ADHESIVE TAPES	1	\$ 146.00	<i>\$</i>	<i>116.40</i>
33	ATTACHMENT PARTS	1	\$ 152.00		
34	FOAM STRIPS	1	\$ 121.00		
35	REAR SIDE PANEL - RH	1	\$ 4,706.00		
36	REAR QUARTER WINDOW	1	\$ 653.00		
37	WINDOW PRIMER	1	\$ 24.00		
38	REAR FUEL FILLER FLAP	1	\$ 102.00		
39	REAR VENT TRIM	1	\$ 81.00		
40	REAR WHEEL HOUSING LINER - RH	1	\$ 281.00		
SUB TOTAL SPARE PARTS		:	\$ 11,890.00	<i>\$</i>	<i>6,673.36</i>

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SNA 2262 B

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
		<i>c/f</i>		<i>\$ 6,673.36</i>
41	REAR CROSS PANEL	1 \$	486.00	
42	REAR CROSS PANEL REINFORCEMENT	1 \$	1,492.00	
43	REAR CROSS PANEL CONNECTING PLATE - LH / RH	2 \$	102.00	
44	ACRYLIC SEALANT	S/N \$	180.00	
45	CAVITY WAX	S/N \$	140.00	
46	STONE CHIP	S/N \$	180.00	
47	METAL FILLER POWDER	S/N \$	280.00	
48	REAR WINDSCREEN SEALANT	S/N \$	200.00	<i>\$ 200.00</i>
49	1/4 GLASS SEALANT	S/N \$	100.00	
50	REAR NUMBER PLATE	S/N \$	60.00	
51	SUNDRIES	\$	500.00	<i>\$ 109.28</i>
TOTAL SPARE PARTS			\$ 22,306.00	<i>\$ 6,982.64</i>
TOTAL LABOUR CHARGES			\$ 18,832.00	<i>\$ 5,932.00</i>
GRAND TOTAL			\$ 41,138.00	<i>\$ 12,914.64</i>

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED

SPARE PARTS ARE SPECIAL NETT.

bl-15/03/23

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT