

# PREMIUM AUTOMOBILES

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg



## Supplementary Estimate-1

GST Reg No. 19-9902271-W


**AIG Asia Pacific Insurance Pte Ltd**  
78 Shenton Way  
#07-16 AIG Building  
Singapore 079120  
Attn: Mr. Adrian Ling - Motor Claims Dept  
Tel: 6841 0055 / Fax: 6256 4315

**Estimate No.**  
**Date**  
**Service Advisor**  
**Pages**  
**Regn No**  
**Model No**

PA/OD/0027/2023/EQ  
31-Jan-23  
CHANG  
1 of 1  
SMS 7605 E  
AUDI A4 2.0 TFSI

| Quantity           | Description                                                                                                    | Unit Price         | Amount |
|--------------------|----------------------------------------------------------------------------------------------------------------|--------------------|--------|
| <b>Labours</b>     |                                                                                                                |                    |        |
| 1                  | TO REPAIR LHS FRONT FENDER.                                                                                    | \$ 700.00          | X      |
| 2                  | TO RESPRAY LHS FRONT FENDER.                                                                                   | \$ 1,400.00        | 550.   |
| 3                  | TO DISLODGE AND REINSTALL FRONT LOCK CARRIER TO FACILITATE RENEWAL OF FRONT BUMPER REINFORCEMENT BEAM BRACKET. | S/N \$ 480.00      | ✓      |
| <b>GRAND TOTAL</b> |                                                                                                                | <b>\$ 2,580.00</b> |        |

For Premium Automobiles Pte Ltd



Authorised Signature

Total add  
2 days.

Adrian Ling

Add 1 day for spray painting  
of front fender.

Add 1 day for the partial  
dislodging of lock carrier to  
replace bumper reinforcement  
bracket.

# PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

## ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMS 7605 E

| S/N                         | NATURE OF JOBS                                                                                                                                                                         | ESTIMATED CHARGES            | SURVEYOR'S RECOMMENDATIONS |
|-----------------------------|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------------------------------|----------------------------|
| 1                           | TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.                                       | S/N \$ 480.00                | ✓                          |
| 2                           | TO REMOVE AND TRANSFER LHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.                                                                                                                  | S/N \$ <del>350.00</del> 150 |                            |
| 3                           | TO REMOVE AND RENEW AIRCON CONDENSER, CHARGED AIR COOLER AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM.                                              | S/N \$ 1,400.00              | X                          |
| 4                           | TO CARRY OUT VACUUM AND REGAS FOR R1234.                                                                                                                                               | S/N \$ 1,200.00              | X                          |
| 5                           | TO DISMANTLE AND RENEW FRONT BUMPER, BONNET AND LHS HEADLIGHT. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANIZE CRASH MANAGEMNT COMPONENTS. REINSTALL ALL PARTS REMOVED. | \$ <del>4,200.00</del> 1000  |                            |
| 6                           | TO RESPRAY FRONT BUMPER AND BONNET.                                                                                                                                                    | \$ <del>2,000.00</del> 1100  |                            |
| 7                           | TO CARRY OUT DIAGNOSTIC CHECK.                                                                                                                                                         | S/N \$ 192.00                | ✓                          |
| <b>TOTAL LABOUR CHARGES</b> |                                                                                                                                                                                        | <b>: \$ 9,822.00</b>         |                            |

# PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699  
TEL: 6366 2323 FAX: 6841 1183  
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

WIP: 52448

Kiam/Hong

Benwi



## MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMS 7605 E

OK  
18/01

|                       |                                                            | DAMAGED PARTS & PRICES |        |          |               |
|-----------------------|------------------------------------------------------------|------------------------|--------|----------|---------------|
| S/N                   | PARTS DESCRIPTION                                          | QTY                    | S/NETT | REMARKS  |               |
| 1                     | FRONT BUMPER <i>Rehd</i>                                   | 1                      | S      | 2,515.00 | ✓             |
| 2                     | FRONT BUMPER FIXING PARTS <i>Meu</i>                       | 1                      | S      | 416.00   | +             |
| 3                     | FRONT BUMPER SECURING STRIP - LH / RH                      | 2                      | S      | 84.00    | ?             |
| 4                     | FRONT BUMPER GRILLE <i>Meu</i>                             | 1                      | S      | 231.00   | +             |
| 5                     | FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE <i>Meu</i>     | 1                      | S      | 310.00   | +             |
| 6                     | FRONT BUMPER AIR GUIDE - LH / RH <i>Meu</i>                | 2                      | S      | 166.00   | +             |
| 7                     | FRONT BUMPER CLOSING ELEMENT - UPPER CENTRE <i>Cracked</i> | 1                      | S      | 310.00   | ? <i>h.s.</i> |
| 8                     | FRONT BUMPER AIR GUIDE GRILLE - LH / RH <i>Meu</i>         | 2                      | S      | 318.00   | +             |
| 9                     | FRONT BUMPER TRIM - LH / RH <i>Meu</i>                     | 2                      | S      | 114.00   | +             |
| 10                    | RADIATOR GRILLE <i>Cracked</i>                             | 1                      | S      | 1,861.00 | ✓             |
| 11                    | FRONT BUMPER FOAM FILLER PIECE <i>Cracked</i>              | 1                      | S      | 224.00   | ✓             |
| 12                    | FRONT BUMPER REINFORCEMENT BEAM <i>Best</i>                | 1                      | S      | 953.00   | ✓             |
| 13                    | FRONT BUMPER GUIDE SECTION - LH / RH <i>Meu</i>            | 2                      | S      | 86.00    | +             |
| 14                    | FRONT BUMPER TOP COVER <i>Cracked</i>                      | 1                      | S      | 151.00   | ✓             |
| 15                    | CAUTION SIGN STICKER <i>3</i>                              | 1                      | S      | 17.00    | ✓             |
| 16                    | AIR CONDITIONER STICKER                                    | 1                      | S      | 9.00     | ✓             |
| 17                    | FRONT BUMPER BRACKET <i>Cracked</i>                        | 1                      | S      | 163.00   | ✓             |
| 18                    | FRONT BUMPER SUPPORT - LH / RH <i>Rehd</i>                 | 2                      | S      | 68.00    | 2 <i>h.s.</i> |
| 19                    | FRONT PARKING AID SENSOR - INNER <i>3</i>                  | 2                      | S      | 543.00   | +             |
| 20                    | FRONT PARKING AID SENSOR - OUTER <i>3</i>                  | 2                      | S      | 543.00   | +             |
| SUB TOTAL SPARE PARTS |                                                            | :                      | \$     | 9,082.00 |               |

ALL CHARGES ARE NOT INCLUSIVE OF GST  
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
SPARE PARTS ARE SPECIAL NETT.

# PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699  
TEL: 6366 2323 FAX: 6841 1183  
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

## MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMS 7605 E

|                       |                                             |     |        |           | DAMAGED PARTS & PRICES          |  |
|-----------------------|---------------------------------------------|-----|--------|-----------|---------------------------------|--|
| S/N                   | PARTS DESCRIPTION                           | QTY | S/NETT | REMARKS   |                                 |  |
| 21                    | FRONT PARKING AID SEAL RING                 | 4   | \$     | 11.00     | x                               |  |
| 22                    | FRONT BUMPER WIRING SET                     | 1   | \$     | 648.00    | x                               |  |
| 23                    | HORN HIGH TONE - LH                         | 1   | \$     | 142.00    | x                               |  |
| 24                    | HORN BRACKET - LH                           | 1   | \$     | 35.00     | x                               |  |
| 25                    | BONNET                                      | 1   | \$     | 3,489.00  | ✓                               |  |
| 26                    | BONNET IMPACT PROTECTION - CENTER / LH / RH | 3   | \$     | 101.00    | ✓                               |  |
| 27                    | BONNET STRIKER - LH                         | 1   | \$     | 60.00     | x                               |  |
| 28                    | BONNET LOCK                                 | 1   | \$     | 241.00    | x                               |  |
| 29                    | BONNET BOWDEN CABLE                         | 1   | \$     | 67.00     | x                               |  |
| 30                    | BONNET RELEASE LEVER                        | 1   | \$     | 16.00     | x                               |  |
| 31                    | BONNET BOWDEN CABLE - CENTER                | 1   | \$     | 67.00     | x                               |  |
| 32                    | BONNET RELEASE CABLE COVER                  | 1   | \$     | 12.00     | x                               |  |
| 33                    | HEADLIGHT COVER - LH                        | 1   | \$     | 52.00     | x                               |  |
| 34                    | HEADLIGHT - LH                              | 1   | \$     | 8,666.00  | ✓ (Crack inside, proceed order) |  |
| 35                    | LIFT CYLINDER - LH / RH                     | 2   | \$     | 488.00    | +                               |  |
| 36                    | LIFT CYLINDER CORRUGATED PIPE               | 1   | \$     | 111.00    | x                               |  |
| 37                    | OUTSIDE TEMPERATURE SENSOR BRACKET          | 1   | \$     | 22.00     | ✓                               |  |
| 38                    | LOCK CARRIER                                | 1   | \$     | 1,569.00  | x                               |  |
| 39                    | LOCK CARRIER SUPPORT                        | 1   | \$     | 45.00     | x                               |  |
| 40                    | A/C CONDENSER                               | 1   | \$     | 724.00    | +                               |  |
| SUB TOTAL SPARE PARTS |                                             |     | \$     | 16,566.00 |                                 |  |

ALL CHARGES ARE NOT INCLUSIVE OF GST  
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
SPARE PARTS ARE SPECIAL NETT.

# PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699  
TEL : 6366 2323 FAX : 6841 1183  
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

## MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMS 7605 E

|     |                                      |        | DAMAGED PARTS & PRICES |         |
|-----|--------------------------------------|--------|------------------------|---------|
| S/N | PARTS DESCRIPTION                    | QTY    | S/NETT                 | REMARKS |
| 41  | A/C CONDENSER REFRIGERANT LINE       | 1 \$   | 197.00                 | x       |
| 42  | A/C CONDENSER REFRIGERANT LINE       | 1 \$   | 405.00                 | x       |
| 43  | A/C CONDENSER REFRIGERANT LINE       | 1 \$   | 293.00                 | +       |
| 44  | CHARGE AIR COOLER                    | 1 \$   | 692.00                 | x       |
| 45  | CHARGE AIR COOLER PRESSURE PIPE - LH | 1 \$   | 495.00                 | +       |
| 46  | READY-MIX COOLANT                    | 6 \$   | 326.00                 | +       |
| 47  | RADIATOR AIR GUIDE - LH INNER        | 1 \$   | 38.00                  | +       |
| 48  | RADIATOR AIR GUIDE (LH/RH) OUTER     | 2 \$   | 50.00                  | ✓ H.S.  |
| 49  | RADIATOR AIR GUIDE - UPPER           | 1 \$   | 25.00                  | +       |
| 50  | RADIATOR AIR GUIDE - LOWER           | 1 \$   | 38.00                  | +       |
| 51  | FRONT BUMPER BRACKET - LH            | 1 \$   | 269.00                 | ✓ H.S.  |
| 52  | FRONT NO PLATE                       | S/N \$ | 60.00                  | -       |
| 53  | SUNDRIES                             | \$     | 400.00                 | ?       |