

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/00/2023/EQ
DATE : 11-Jan-23
WIP : 58448

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 12/1/2023

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

Hi Adrian

6 days exclude 1 Sunday

Johnny Boo 14 Mar 23

OWNER'S NAME : MR LEE ZHOU RUI AARON
ADDRESS : BLK 28A DOVER CRESCENT
#12-11
SINGAPORE 131028
TELEPHONE : HP +65 94242010
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : -
VEHICLE NO : **SMS 7605 E**
MODEL CODE : AUDI A4 2.0 TFSI S-TRONIC
MODEL YEAR : 21/7/2022
ENGINE NO : DEM 033860
CHASSIS NO : WAUZZZF45MA080873
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 6-Jan-23
PLACE OF ACCIDENT : AYE EXIT

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMS 7605 E

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$ 480.00	\$ 480.00
2	TO REMOVE AND TRANSFER LHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$ 350.00	\$ 250.00
3	TO REMOVE AND RENEW AIRCON CONDENSER, CHARGED AIR COOLER AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM.	S/N \$ 1,400.00	
4	TO CARRY OUT VACUUM AND REGAS FOR R1234.	S/N \$ 1,200.00	
5	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET AND LHS HEADLIGHT. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANIZE CRASH MANAGEMNT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 4,200.00	\$ 1,000.00
6	TO RESPRAY FRONT BUMPER AND BONNET.	\$ 2,000.00	\$ 1,100.00
7	ADD LABOUR	\$ 210.00	\$ 210.00
8	ADD LABOUR	\$ 2,580.00	\$ 1,030.00
9	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	\$ 192.00
TOTAL LABOUR CHARGES		: \$ 12,612.00	\$ 4,262.00

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMS 7605 E

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
1	FRONT BUMPER	1	\$ 2,515.00	\$	2,012.00
2	FRONT BUMPER FIXING PARTS	1	\$ 416.00		
3	FRONT BUMPER SECURING STRIP - LH / RH	2	\$ 84.00		
4	FRONT BUMPER GRILLE	1	\$ 231.00		
5	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	1	\$ 310.00	\$	247.60
6	FRONT BUMPER AIR GUIDE - LH / RH	2	\$ 166.00		
7	FRONT BUMPER CLOSING ELEMENT - UPPER CENTRE	1	\$ 310.00		
8	FRONT BUMPER AIR GUIDE GRILLE - LH / RH	2	\$ 318.00		
9	FRONT BUMPER TRIM - LH / RH	2	\$ 114.00		
10	RADIATOR GRILLE	1	\$ 1,861.00	\$	1,488.80
11	FRONT BUMPER FOAM FILLER PIECE	1	\$ 224.00	\$	178.80
12	FRONT BUMPER REINFORCEMENT BEAM	1	\$ 953.00	\$	762.00
13	FRONT BUMPER GUIDE SECTION - LH / RH	2	\$ 86.00		
14	FRONT BUMPER TOP COVER	1	\$ 151.00	\$	120.40
15	CAUTION SIGN STICKER	1	\$ 17.00	\$	13.28
16	AIR CONDITIONER STICKER	1	\$ 9.00	\$	7.12
17	FRONT BUMPER BRACKET	1	\$ 163.00	\$	130.00
18	FRONT BUMPER SUPPORT - LH / RH	2	\$ 68.00	\$	54.00
19	FRONT PARKING AID SENSOR - INNER	2	\$ 543.00		
20	FRONT PARKING AID SENSOR - OUTER	2	\$ 543.00		
SUB TOTAL SPARE PARTS		:	\$ 9,082.00	\$	5,014.00

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMS 7605 E

					DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS		
		C/F			\$	5,014.00
21	FRONT PARKING AID SEAL RING	4	\$	11.00		
22	FRONT BUMPER WIRING SET	1	\$	648.00		
23	HORN HIGH TONE - LH	1	\$	142.00		
24	HORN BRACKET - LH	1	\$	35.00		
25	BONNET	1	\$	3,489.00	\$	2,791.20
26	BONNET IMPACT PROTECTION - CENTER / LH / RH	3	\$	101.00	\$	80.00
27	BONNET STRIKER - LH	1	\$	60.00		
28	BONNET LOCK	1	\$	241.00		
29	BONNET BOWDEN CABLE	1	\$	67.00		
30	BONNET RELEASE LEVER	1	\$	16.00		
31	BONNET BOWDEN CABLE - CENTER	1	\$	67.00		
32	BONNET RELEASE CABLE COVER	1	\$	12.00		
33	HEADLIGHT COVER - LH	1	\$	52.00		
34	HEADLIGHT - LH	1	\$	8,666.00	\$	6,932.80
35	LIFT CYLINDER - LH / RH	2	\$	488.00		
36	LIFT CYLINDER CORRUGATED PIPE	1	\$	111.00		
37	OUTSIDE TEMPERATURE SENSOR BRACKET	1	\$	22.00	\$	17.36
38	LOCK CARRIER	1	\$	1,569.00		
39	LOCK CARRIER SUPPORT	1	\$	45.00		
40	A/C CONDENSER	1	\$	724.00		
SUB TOTAL SPARE PARTS		:	\$	16,566.00	\$	14,835.36

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMS 7605 E

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
		C/F		\$	14,835.36
41	A/C CONDENSER REFRIGERANT LINE	1	\$	197.00	
42	A/C CONDENSER REFRIGERANT LINE	1	\$	405.00	
43	A/C CONDENSER REFRIGERANT LINE	1	\$	293.00	
44	CHARGE AIR COOLER	1	\$	692.00	
45	CHARGE AIR COOLER PRESSURE PIPE - LH	1	\$	495.00	
46	READY-MIX COOLANT	6	\$	326.00	
47	RADIATOR AIR GUIDE - LH INNER	1	\$	38.00	
48	RADIATOR AIR GUIDE - LH / RH OUTER	2	\$	50.00	\$ 39.84
49	RADIATOR AIR GUIDE - UPPER	1	\$	25.00	
50	RADIATOR AIR GUIDE - LOWER	1	\$	38.00	
51	FRONT BUMPER BRACKET - LH	1	\$	269.00	\$ 215.20
52	FRONT NO PLATE	S/N	\$	60.00	\$ 60.00
53	SUNDRIES		\$	400.00	\$ 3.20
TOTAL SPARE PARTS		:	\$	28,936.00	\$ 15,153.60
TOTAL LABOUR CHARGES		:	\$	12,612.00	\$ 4,262.00
GRAND TOTAL		:	\$	41,548.00	\$ 19,415.60

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Supplementary Estimate-1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 / Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/0027/2023/EQ 31-Jan-23 CHANG 1 of 1 SMS 7605 E AUDI A4 2.0 TFSI
Quantity	Description	Unit Price	Amount
<u>Labours</u>			
1	TO REPAIR LHS FRONT FENDER.	\$ 700.00	
2	TO RESPRAY LHS FRONT FENDER.	\$ 1,400.00	\$ 550.00
3	TO DISLODGE AND REINSTALL FRONT LOCK CARRIER TO FACILITATE RENEWAL OF FRONT BUMPER REINFORCEMENT BEAM BRACKET.	S/N \$ 480.00	\$ 480.00
GRAND TOTAL		\$ 2,580.00	\$ 1,030.00

For Premium Automobiles Pte Ltd

 Authorised Signature



Supplementary Estimate-2

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 / Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/0027/2023/EQ 31-Jan-23 GEORGE WONG 1 of 1 SMS 7605 E AUDI A4 2.0 TFSI	
Quantity	Description		Unit Price	Amount
<u>Labours</u>				
1	TO RE-COAT FOR AFFECTED AREA (SUPPLY BY OWNER)		\$ 210.00	\$ 210.00
GRAND TOTAL			\$ 210.00	\$ 210.00

For Premium Automobiles Pte Ltd

Authorized Signature

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF
THE AFFECTED VEHICLE. SHOULD WE REQUIRE
FURTHER LABOUR CHARGES AND SPARE PARTS IN THE
PROGRESS OF REPAIR, WE SHALL INFORM YOU
ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO
MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR
APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT