

TAX/01/23/2024

COMFORTDELGRO
ENGINEERING**ComfortDelGro Engineering Pte Ltd**
59 Loyang Drive Singapore 508969Our Ref : 305542341

Via Fax

Date : 13.01.23

Your Insured

Time of Fax : _____

Date of Acc

Attn: Motor Claims Department

STRIDES

Dear Sirs

SURVEY OF CLIENT'S DAMAGED VEHICLE REG NO. SH A 7449T

Our client has engaged us to repair the above vehicle and submit claims against the other party/parties involved in the accident.

In accordance to the motor claims framework, we hereby request your presence at 59 Loyang Drive, Singapore 508969 to survey our client's damaged vehicle.

Enclosed, please find:

- I) Our initial estimate of repairs of the damaged vehicle;
- II) Accident report made by our client.

I would appreciate it if you could call us to arrange for the survey of the vehicle:

◆ Lim Kwok Eng	Tel: 6214 8355 or HP: 9824 0811
◆ Jumani Bin Masudin	Tel: 6214 8315 or HP: 9635 5305
◆ Lim Tien Siong	Tel: 6214 8398 or HP: 9635 8546
◆ <u>Chiang Liat Choon</u>	<u>Tel: 6214 8314 or HP: 9296 8006</u>

chlanglc@cdge.com.sg
Fax no. 6546 8156

If we do not hear from you within the next 48 hours, we shall deem that you have waived your rights to survey our client's vehicle and we shall proceed to engage Independent surveyor without further reference to you. We henceforth reserve our rights to claim for Loss of Use and Loss of Rental during any delayed period of this survey arrangement.

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a Motor Surveyor appointed by the Insurance company.

Thank you.

Yours faithfully


 For Vice President
 Taxi Accident Repair

COMFORT DELGRO ENGINEERING PTE LTD**REPAIR ESTIMATE***VEHICLE NO **SHA7449T**

12.01.2023

MAKE **REG. 29.04.2021****CHIANG/STRIDES**MODEL **IONIQ G 2**

Qty	Parts Description/ Labour	Type	Amount
1	REAR BUMPER		\$459.40
1	REAR BUMPER CENTRE MOULDING		\$451.25
1	REAR BUMPER REINFORCEMENT		\$394.80
1	REAR BUMPER UNDER MOULDING		\$155.00
1	REAR BUMPER BRACKET LH / RH		\$55.80
10	REAR BUMPER COVER CLIPS		\$2.20
1	REAR FOG LAMP		\$201.50
1	BOOTLID		\$2,549.70
1	BOOTLID EMBLEM HYBIRD		\$24.30
1	BOOTLID EMBLEM IONIQ		\$31.30
1	REAR NUMBER PLATE LAMP		\$85.30
1	REAR BUMPER REFLECTOR RH		\$41.45
1	REAR BLIND SPOT RADAR RH		\$1,784.40
	SUB TOTAL		\$6,397.30
	20.00%		\$1,278.46
	DISCOUNTED TOTAL		\$5,117.84
1	BOOTLID COMFORT/TEL NUMBER STICKER		\$60.00
1	BOOTLID LID COMFORT APP STICKER		\$40.00
1	BOOTLID ADVERTISEMENT LOGO		\$80.00
2	REAR FENDER ADVERTISEMENT LH/RH		\$100.00
1	REAR BUMPER MAT		\$50.00
1	REAR NUMBER PLATE W/HOLDER		\$55.00
1	REAR REVERSE SENSOR		\$180.00
			\$665.00
	Labour Charge		
	Panel Beating		\$900.00
	Spray Painting Charge		\$800.00
	Remove/Refix Rear Windscreen Upper/ Lower		\$190.00
	Reset/ Diagnose		\$240.00
	Tuff Kote		\$90.00
	Remove/refix Reverse sensor		\$60.00
	TOTAL LABOUR		\$2,280.00
	ESTIMATE TOTAL		\$8,062.84
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will			
be prepared after the vehicle is surveyed by a motor Surveyor appointed by the Insurance company.			