



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile | | | | |
|---|--|--|---|--------------------|
| STRIDES AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4SINGAPORE 757705 | | | Ref: CS/SMR23000442/Svy3e2 Date: 01/02/2023 Code: SMR | |
| 1. Policy Particulars :- THIRD PARTY CLAIM | | | | |
| | Insured Veh. | SHD 6213Y | Veh. Inspected | SHA 7449T |
| | Policy No. | | Coverage (\$) | 0.00 |
| | Claim No. | TAX/01/23/2024 | Excess (\$) | 0.00 |
| | Assign From | ANA MAGNAYE | Assign Date | 13/01/2023 |
| 2. Vehicle Particulars & Condition | | | | |
| | Make & Model | HYUNDAI IONIQ | c.c | 1580 |
| | Engine No. | HIDDEN | Year of Reg. | 2021 |
| | Chassis No. | KMHC851CVLU192956 | Colour | BLUE |
| | Odometer | 291586 KM | Steering | IN ORDER |
| | Brakes | IN ORDER | Modification | STANDARD ALLOY RIM |
| | General | GOOD | | |
| 3. Conditions of Tyres | | | | |
| | | Size | Make | Balance |
| | R/H Front Tyre | 195/65 R15 | WEST LAKE | 5 mm |
| | L/H Front Tyre | 195/65 R15 | WEST LAKE | 6 mm |
| | R/H Rear Tyre | 195/65 R15 | WEST LAKE | 6 mm |
| | L/H Rear Tyre | 195/65 R15 | WEST LAKE | 6 mm |
| 4. Description of Damages | | | | |
| | THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS. | | | |
| 5. General Information | | | | |
| | Accident Date | 12/01/2023 | Inspection Date | 13/01/2023 |
| | Survey held at | COMFORTDELGRO ENGINEERING PTE LTD 59 LOYANG DRIVE SINGAPORE 508969 | | |
| 5a. Remarks | | | | |
| | A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. | | | |
| 5b. Estimate Days of Repair | | | | |
| | ESTIMATED NORMAL PERIOD FOR REPAIR: | | 3 Working Days | |