

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO SHA7449T
MAKE REG. 29.04.2021
MODEL IONIQ G 2

12.01.2023
CHIANG/STRIDES

Qty	Parts Description/ Labour	Type	Amount	
1	REAR BUMPER	Dent	\$459.40	Dent
1	REAR BUMPER CENTRE MOULDING	Scr	\$451.25	Scr
1	REAR BUMPER REINFORCEMENT	?	\$394.80	?
1	REAR BUMPER UNDER MOULDING	Scr	\$155.00	Scr
1	REAR BUMPER BRACKET LH / RH	? x	\$111.60	?
10	REAR BUMPER COVER CLIPS	Nec	\$22.00	Nec
1	REAR FOG LAMP	? x	\$201.50	?
1	BOOTLID	Scr	\$2,549.70	R
1	BOOTLID EMBLEM HYBIRD		\$24.30	Nec
1	BOOTLID EMBLEM IONIQ		\$31.30	Nec
1	REAR NUMBER PLATE LAMP		\$170.60	XNN
1	REAR BUMPER REFLECTOR RH		\$41.45	Scr
1	REAR BLIND SPOT RADAR RH		\$1,784.40	?
SUB TOTAL			\$6,397.30	932.6
20.00%			\$1,278.46	186.53
DISCOUNTED TOTAL			\$5,117.84	
1	BOOTLID COMFORT/TEL NUMBER STICKER		\$60.00	Nec
1	BOOTLID LID COMFORT APP STICKER		\$40.00	Nec
1	BOOTLID ADVERTISEMENT LOGO		\$80.00	Nec
2	REAR FENDER ADVERTISEMENT LH/RH		\$200.00	Nec
1	REAR BUMPER MAT		\$50.00	Nec
1	REAR NUMBER PLATE W/HOLDER		\$55.00	Scr
1	REAR REVERSE SENSOR		\$180.00	Scr
			\$665.00	
Labour Charge				
Panel Beating				
Spray Painting Charge				
Remove/Refix Rear Windscreen Upper/Lower				
Reset/ Diagnose				
Tuff Kote				
Remove/refix Reverse sensor				
TOTAL LABOUR			\$2,280.00	
ESTIMATE TOTAL			\$8,062.84	
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Date:

11am 13/1/23
P/P 3pm 3 days

T = 2541.12