

ICON MOTOR APPRAISER PTE LTD

Motor Appraiser and Insurance Loss Adjustor
Blk 361 Yung An Road #12-105 Singapore 610361
Mobile: +65 9232 0012 Email: iconappraiser@gmail.com
UEN. : 202006885Z

INSPECTION REPORT

To : ANIMAL ARTS ACADEMY PTE LTD

Our ref. : 20221209/00194/CCE

Date : 09 Dec 2022

REFERENCE

Assign by : ANIMAL ARTS ACADEMY PTE LTD
3rd party Veh. : **SMN7385R**
Inspection on : 31 Oct 2022
Accident on : 26 Oct 2022
Workshop name : Cheng Chuan Enterprise Pte Ltd
Inspection at : 2 Kaki Bukit Avenue 2 #02-20/26/30/31
Kaki Bukit Autohub
Singapore 417921

PARTICULARS OF DAMAGED VEHICLE

Registration no.	: GBD6085X	Odometer	: 188333 km
Make / Model	: NISSAN NV200 DX 1.6 AT	Chassis no.	: VM20058735
Regn. date	: 2015	Engine no.	: HR16004489D
Body colour	: Grey	Engine cap.	: 1597 cc

PRE-ACCIDENT CONDITION OF VEHICLE (STATIC CHECK ONLY)

Steering	: In order	Paintwork	: Fair
Footbrake	: In order	Undercarriage	: Serviceable
Handbrake	: In order	Gen. condition	: Fair

TYRE CONDITION ON VEHICLE


	Make	Size	Tread depth	Type of road wheel
Front N/S	: Roadking	175/70R14	70%	Steel
Front O/S	: Roadking	175/70R14	70%	Steel
Rear N/S	: Roadking	175/70R14	70%	Steel
Rear O/S	: Roadking	175/70R14	70%	Steel

NOTE: Tread depth percentages represents the visually estimated remaining life of tyre treads.

Note: This report is confidential and solely for the use of the client. The survey was conducted on a "Without Prejudice" basis.

POINT OF IMPACT

The damages was found on the right rear portion.



RECOMMENDATION

The estimated cost of repair submitted by the repairer Cheng Chuan Enterprise Pte Ltd as per schedule attached has been revised and scrutinised, and in our opinion, we consider it to be fair and reasonable. The repairer have agreed to undertake the repairs at our recommendation.

Our adjusted cost of repair is SGD 5,300.00 to carry out the repairs.
Kindly refer to parts and labour portion for a detailed account of the cost estimates.

REMARKS

However, for your information, under normal circumstances, the repair normally would take approximately 6 (Six) working days to complete.

We have **NOT AUTHORISED** the repair to the damaged vehicle.
The survey was conducted strictly on a "**WITHOUT PREJUDICE**" basis.

We are pleased to advise that the inspection work was carried out accordingly, and hereby submit our final report, which includes material damages photographs.

Yours faithfully,
ICON Motor Appraiser Pte Ltd

Patrick Ng
Motor Vehicle Appraiser

A circular blue ink stamp. The outer ring contains the text 'ICON MOTOR APPRAISER PTE LTD'. The inner circle contains 'UEN No. 202006885Z'. A signature is written across the stamp.

Note: This report is confidential and solely for the use of the client. The survey was conducted on a "Without Prejudice" basis.

ICON MOTOR APPRAISER PTE LTD

List items					
S/N	Parts description	QTY	Condition	Repairer's Estimate	Our Recommendation
1	Rear windscreen moulding	1	Necessary	\$ 115.00	\$ 115.00
2	Tailgate	1	Damaged	\$ 1,373.00	\$ 1,373.00
3	Tailgate dampers	2	Re-use	--	--
4	Tailgate lock	1	Re-use	--	--
5	Tailgate lock catch	1	Re-use	--	--
6	Tailgate "NISSAN" logo	1	Necessary	\$ 55.00	\$ 55.00
7	Tailgate "NV200" emblem	1	Necessary	\$ 32.00	\$ 32.00
8	Tailgate weatherstrip	1	Deformed	\$ 136.00	\$ 136.00
9	Tailgate side stopper sockets	2	Necessary	\$ 68.00	\$ 68.00
10	Taillamp o/s	1	Damaged	\$ 448.00	\$ 448.00
11	Taillamp panel o/s	1	Repair	--	--
12	Taillamp connector o/s	1	Re-use	--	--
13	End panel	1	Buckled	\$ 469.00	\$ 469.00
14	End panel inner member	1	Repair	--	--
15	Rear side panel o/s	1	Damaged	\$ 996.00	\$ 996.00
16	Rear bumper	1	Damaged	\$ 665.00	\$ 665.00
17	Rear bumper lower bracket	4	Bent	\$ 144.00	\$ 144.00
18	Rear bumper side retainer	2	Damaged	\$ 138.00	\$ 138.00
Subtotal				\$ 4,639.00	\$ 4,639.00
Discount (less 10.00%)				\$ -	\$ 463.90
Total				\$ 4,639.00	\$ 4,175.10

Special nett items					
No.	Parts description	QTY	Condition	Repairer's Estimate	Our Recommendation
1	Rear windscreen sealant	1	Necessary	\$ 100.00	\$ 60.00
2	Rear tyre o/s	1	Torn	\$ 150.00	\$ 120.00
3	Tailgate "70km/h" sticker	1	Necessary	\$ 20.00	\$ 15.00
4	Rear side panel sealant o/s	1	Necessary	\$ 100.00	\$ 60.00
5	End panel sealant	1	Necessary	\$ 80.00	\$ 50.00
6	End panel top garnish clips	1	Not necessary	\$ 60.00	--
7	Rear bumper clips	1	Necessary	\$ 80.00	\$ 50.00
8	Tailgate inner trim clips	1	Necessary	\$ 60.00	\$ 30.00
9	Sundries	1	Necessary	\$ 60.00	\$ 50.00
Total				\$ 710.00	\$ 435.00

Labour				
No.	Description	QTY	Repairer's Estimate	Our Recommendation
1	To dismantle / renew the accident damaged portion. To panel beat, reshape, straighten, orientate and align repair / replacement parts.	1	\$ 1,200.00	\$ 1,000.00
2	To disconnect rear wire harness of electrical components to facilitate repairs, reconnect and check functions including taillamp lightings.	1	\$ 50.00	\$ 30.00
3	To remove, refit tailgate components to replace tailgate, check and re-adjust close gap, alignment and water seepage.	1	\$ 100.00	\$ 50.00
4	To remove and replace o/s rear tyre. To perform tyre balancing.	1	\$ 50.00	\$ 30.00
5	To remove and refit rear windscreen to facilitate repair work.	1	\$ 150.00	\$ 120.00
6	Supply spray paint material and necessary items to respray affected area / panel.	1	\$ 1,000.00	\$ 800.00
7	To rust proof all affected portions after repair.	1	\$ 100.00	\$ 50.00
Total labour			\$ 2,650.00	\$ 2,080.00

Estimate Grand Total	\$ 7,999.00	\$ 6,690.10
-----------------------------	--------------------	--------------------

ICON MOTOR APPRAISER PTE LTD


Our Ref: 20221209/00194/CCE
Your Ref: SMN7385R



Note: This report is confidential and solely for the use of the client. The survey was conducted on a "Without Prejudice" basis.

ICON MOTOR APPRAISER PTE LTD

Our Ref: 20221209/00194/CCE
Your Ref: SMN7385R



Note: This report is confidential and solely for the use of the client. The survey was conducted on a "Without Prejudice" basis.

ICON MOTOR APPRAISER PTE LTD

Our Ref: 20221209/00194/CCE
Your Ref: SMN7385R



Note: This report is confidential and solely for the use of the client. The survey was conducted on a "Without Prejudice" basis.

ICON MOTOR APPRAISER PTE LTD

Our Ref: 20221209/00194/CCE
Your Ref: SMN7385R



Note: This report is confidential and solely for the use of the client. The survey was conducted on a "Without Prejudice" basis.

ICON MOTOR APPRAISER PTE LTD



Our Ref: 20221209/00194/CCE
Your Ref: SMN7385R



Note: This report is confidential and solely for the use of the client. The survey was conducted on a "Without Prejudice" basis.

ICON MOTOR APPRAISER PTE LTD

Our Ref: 20221209/00194/CCE
Your Ref: SMN7385R



Note: This report is confidential and solely for the use of the client. The survey was conducted on a "Without Prejudice" basis.

ICON MOTOR APPRAISER PTE LTD

Our Ref: 20221209/00194/CCE
Your Ref: SMN7385R



Note: This report is confidential and solely for the use of the client. The survey was conducted on a "Without Prejudice" basis.



CHENG CHUAN MOTOR SERVICES

Blk 2 Kaki Bukit Avenue 2 #02-26 /02-31

Auto Hub

Singapore - 417921

Mobile no: 96641110/96411066 Phone no: 6742 2607 Fax no: 67428992

Email: chengchuan@live.com.sg

Customer Details

ANIMAL ARTS ACADEMY PTE LTD

Singapore

Phone no:

Fax no:

ATTN: Notes

Tax Invoice No:

58475

Dated:

January 10, 2023

Make:

NISSAN

Terms of Payment:

Due upon receipt

Model:

NV200

Chassis Car Plate No:

GBD6085X

S.No	Product	Description	Qty	Price (SGD)	Amount (SGD)
1	LUMP SUM REPAIR AND LABOR COST		1	5,300.00	5,300.00
2	LOSS OF USE		8	150.00	1,200.00
			9		6,500.00
Total (SGD)					6,500.00

Amount in words :

Six Thousand Five Hundred Singapore Dollar (SGD)

Declaration:

We declare that this Tax Invoice shows the actual price of the goods described and that all particulars are true and correct.

For CHENG CHUAN MOTOR SERVICES



Handwritten signature

Authorized Signatory

Remarks:

- CHEQUE SHOULD BE MADE PAYABLE TO "CHENG CHUAN MOTOR SERVICES"
- PLEASE QUOTE OUR INVOICE NUMBER(S) AT THE BACK OF CHEQUE(S) WHEN MAKING PAYMENT
- UEN No : 46588900W

Receiver Chop & Sign



RECORD MANAGEMENT CENTRE

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

9 Temasek Boulevard, Suntec City Tower Two #42-01B
Singapore 038989

E-mail: gears-support@shift-technology.com

GST Registration: M400017735

TAX INVOICE

Date of Request: 31/10/2022

Your Ref No: JLC/2022/4520/PD

Dear Sir/Madam,

Date of Accident: 26/10/2022 00:00 (SGT)

Vehicle No: GBD6085X

Place of Accident: PIE, Singapore

With reference to your application for the accident report, we have attached the following accident report as requested:

DOCUMENTS	ACCIDENT LOCATION	PER DOC (\$)	QTY	AMOUNT (\$)
SMN7385R	PIE, Singapore	(31.00)	1	(28.97)
GST Amount				(2.03)
Total Amount Due (GST Inclusive)				(31.00)

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

Thank you.

This is a computer generated document and requires no signature.



Thank you

You have successfully logged out.
Your last login date and time was 27 Oct 2022, 16:42:41.
To return to ONE MOTORING, please click [here](#).
For security reasons, please CLEAR YOUR CACHE after each session.

Session Transaction History

S/No.	Asset Type	Asset ID	Transaction Type	Transaction Amount(S\$)	Log Date/Time
1	Vehicle	SMN7385R	18.19 Enquire Veh Owner Info (Others) by Law Firm	7.49	27 Oct 2022 / 16:49:38

Please do not use your browser's Back or Forward buttons as this may result in information loss.