


Company Reg No: 202136904Z

E-mail: hdperfectautowork@gmail.com



**HD PERFECT
AUTOWORK PTE LTD**

DATE : 13.01.2023

TO : **SOMPO** MOTOR CLAIMS DEPTS
VEHICLE NO : **SNG9244B**
MODEL : CITROEN C4 PICASSO
DATE OF ACCIDENT : 13.01.2023
TIME OF ACCIDENT : 09:30 HOURS

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

CLAIM DETAIL : PARTS

CLAIM DETAIL : PARTS				
S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	FRONT BUMPER <i>Behind</i>	1	\$ 1,770.70	\$ 1,770.70
2	FRONT BUMPER UPPER GRILLE (CENTER) <i>could not</i>	1	\$ 855.30	\$ 855.30
3	FRONT BUMPER LOWER GRILLE (CENTER) <i>could</i>	1	\$ 488.90	\$ 488.90
4	FRONT BUMPER LOWER (SIDE) RH <i>could</i>	1	\$ 235.75	\$ 235.75
5	FRONT BUMPER FOGLAMP RH <i>3 per</i>	1	\$ 432.14	\$ 432.14
6	FRONT BUMPER FOGLAMP GARNISH RH	1	\$ 165.30	\$ 165.30
7	FRONT BUMPER FOGLAMP CHROME RH <i>new</i>	1	\$ 148.20	\$ 148.20
8	FRONT BUMPER SIDE RETAINER <i>RH 12yd</i>	2	\$ 85.60	\$ 171.20
9	FRONT BUMPER TOP SUPPORT GARNISH <i>could</i>	1	\$ 788.50	\$ 788.50
10	FRONT BUMPER INNER CORNER SUPPORT <i>Not a 21cm</i>	2	\$ 216.20	\$ 432.40
11	FRONT BUMPER SIDE LAMP CHROME RH <i>could</i>	1	\$ 151.60	\$ 151.60
12	FRONT BUMPER SIDE LAMP (LED) <i>could RH</i>	2	\$ 481.30	\$ 962.60
13	FRONT BUMPER TOP CHROME WITH BASE <i>could</i>	1	\$ 980.50	\$ 980.50
14	FRONT BUMPER TOP COVER GARNISH <i>new</i>	1	\$ 265.30	\$ 265.30
15	FRONT BUMPER REINFORCEMENT <i>new</i>	1	\$ 958.60	\$ 958.60
16	FRONT ENGINE UNDER COVER <i>new</i>	1	\$ 481.70	\$ 481.70
17	HEAD LAMP <i>could RH</i>	2	\$ 900.70	\$ 1,801.40
18	HEAD LAMP BRACKET RH <i>could</i>	1	\$ 125.60	\$ 125.60
19	FRONT FENDER RH <i>Backed</i>	1	\$ 833.70	\$ 833.70
20	FRONT FENDER INNER GARNISH RH <i>new</i>	1	\$ 116.70	\$ 116.70
21	FRONT FENDER INNER COWLING RH <i>Behind</i>	1	\$ 183.50	\$ 183.50

TO : **SOMPO** MOTOR CLAIMS DEPTS
 VEHICLE NO : **SNG9244B**
 MODEL : **CITROEN C4 PICASSO**
 DATE OF ACCIDENT : 13.01.2023
 TIME OF ACCIDENT : 09:30 HOURS

22	FRONT FENDER GLASS RH <i>Not m</i>	1	\$	465.80	\$	465.80	+
23	FRONT DOOR RH <i>Repair</i>	1	\$	1,866.40	\$	1,866.40	+
24	FRONT DOOR FRONT INNER GARNISH RH <i>Not m</i>	1	\$	108.60	\$	108.60	+
25	FRONT ABS SENSOR RH <i>Not m</i>	1	\$	489.70	\$	489.70	+
26	FRONT SPORT RIM RH <i>Not m</i>	1	\$	1,495.60	\$	1,495.60	+
27	FRONT WHEEL HOUSE PANEL RH <i>Repair</i>	1	\$	1,355.60	\$	1,355.60	+
28	FRONT RADIATOR SPARE TANK <i>Not m</i>	1	\$	86.40	\$	86.40	+
29	FRONT AIR-CON PIPE	1	\$	351.80	\$	351.80	+
30	FRONT KNUCKLE ARM RH	1	\$	799.80	\$	799.80	+
31	FRONT LOWER ARM RH	1	\$	675.30	\$	675.30	+
32	FRONT KNUCKLE ARM BEARING RH	1	\$	257.60	\$	257.60	+
33	FRONT STABILIZER BAR LINKAGE RH	1	\$	138.40	\$	138.40	+
34	FRONT SUPPORT PANEL (TOP)	1	\$	366.70	\$	366.70	+
35	FRONT UPPER SUPPORT PANEL RH	1	\$	182.40	\$	182.40	+
36	FRONT LOWER SUPPORT PANEL RH	1	\$	248.40	\$	248.40	+
37	FRONT SHOCK ABSORBER RH	1	\$	686.20	\$	686.20	+
38	FRONT STEERING RACK AND PINION	1	\$	5,851.30	\$	5,851.30	+
39	FRONT TURBO COOLER <i>Dented</i>	1	\$	1,527.00	\$	1,527.00	+
40	FRONT TURBO COOLER AIR DUCT <i>Crushed</i>	1	\$	155.20	\$	155.20	+
41	FRONT TURBO COOLER BRACKET <i>Crushed</i>	2	\$	186.10	\$	372.20	+
42	FRONT TURBO COOLER BRACKET MOUNTING <i>2nd</i>	2	\$	38.00	\$	76.00	+
43	FRONT TURBO COOLER HOSE <i>Not m</i>	2	\$	244.60	\$	489.20	+

8994.85
 7915.36

TOTAL PRICE \$ 30,395.19
 LESS 10% \$ 3,039.52
SUB TOTAL PRICE \$ 27,355.67

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	FRONT NUMBER PLATE (OFF PEAK PLATE) <i>Not m</i>	1	\$ 120.00	\$ 120.00
2	FRONT BUMPER CLIP (SET) <i>New</i>	1	\$ 80.00	\$ 80.00
3	FRONT BUMPER TOP SUPPORT GARNISH CLIP (SET) <i>Not m</i>	1	\$ 80.00	\$ 80.00
4	FRONT BUMPER TOP COVER GARNISH CLIP (SET) <i>Not m</i>	1	\$ 80.00	\$ 80.00
5	FRONT ENGINE UNDER COVER CLIP (SET) <i>Not m</i>	1	\$ 60.00	\$ 60.00
6	FRONT FENDER GLASS SEALANT RH <i>Not m</i>	1	\$ 80.00	\$ 80.00
7	FRONT FENDER GLASS INNER SHIELD RH <i>Not m</i>	1	\$ 80.00	\$ 80.00
8	FRONT FENDER INNER COWLING CLIP (SET) <i>New</i>	1	\$ 50.00	\$ 50.00

TO : **SOMPO** MOTOR CLAIMS DEPTS
 VEHICLE NO : **SNG9244B**
 MODEL : **CITROEN C4 PICASSO**
 DATE OF ACCIDENT : 13.01.2023
 TIME OF ACCIDENT : 09:30 HOURS

9	FRONT SUPPORT PANEL TOP GARNISH CLIP (SET)	1	\$ 50.00	\$ 50.00	x
10	FRONT WHEEL TYRE LH	1	\$ 450.00	\$ 450.00	x
11	WHEEL CAP (SET)	1	\$ 120.00	\$ 120.00	x
12	BRAKE OIL	1	\$ 60.00	\$ 60.00	x
13	COOLANT	1	\$ 120.00	\$ 120.00	x 50

130 TOTAL \$ 1,430.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (FRONT)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	PANEL BEATING, REMOVING AND REPLACING PARTS	\$ 1,400.00	800
2	SPRAY PAINTING TO AFFECTED AREA	\$ 1,000.00	700
3	REFOCUS HEADLAMP BEAM	\$ 60.00	x
4	WIRING CHECK	\$ 180.00	30
5	TUFF COAT	\$ 250.00	50
6	REMOVE AND REFIX FRONT UNDERCARRIAGE	\$ 650.00	x
7	TO PRESS FRONT WHEEL BEARING	\$ 40.00	x
8	FOUR WHEEL ALIGNMENT	\$ 120.00	x
9	REMOVE AND REFIX POWER STEERING RACK AND PINION AND PROGRAMMING	\$ 750.00	x
10	REMOVE AND REFIX AIR-CON CONDENSER	\$ 120.00	60
11	REMOVE AND REFIX RADIATOR	\$ 120.00	60
12	REMOVE AND REFIX TURBO COOLER	\$ 120.00	60

TO : **SOMPO** MOTOR CLAIMS DEPTS
VEHICLE NO : **SNG9244B**
MODEL : **CITROEN C4 PICASSO**
DATE OF ACCIDENT : 13.01.2023
TIME OF ACCIDENT : 09:30 HOURS

13	REMOVE AND REFIX FENDER GLASS	\$ 100.00	60
14	RESET ABS LIGHT	\$ 350.00	x
15	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 180.00	x

TOTAL \$ 5,440.00

ESTIMATE REPORT

TOTAL PARTS COST : \$ 28,785.67
TOTAL LABOUR COST : \$ 5,440.00
TOTAL REPAIR COST : \$ 34,225.67

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS. EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.

PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

IRENE

SERVICE ADVISOR

IRENE

HP : 8297 9787

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian L
L/s 13/01/23

07 Days

Total: 9865.36

L/s: 7.91K

7.9K