



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SBD 4488E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	TAILGATE	BENT	1,300.00	1,072.00
1	TAILGATE WEATHERSTRIP	NOT NECESSARY	160.00	-
1	TAILGATE LOCK	NOT NECESSARY	260.00	-
1	REAR BUMPER	DEFORMED	1,080.00	926.60
1	REAR BUMPER SIDE RETAINER LH	NOT NECESSARY	50.00	-
1	REAR BUMPER SIDE RETAINER RH	NOT NECESSARY	50.00	-
10	REAR BUMPER CLIP	NECESSARY	50.00	30.00
	LESS 20% DISCOUNT		-590.00	-405.72
			2,360.00	1,622.88
<u>SPECIAL NETT ITEMS</u>				
1	NUMBER PLATE & HOLDER (SN)	NOT NECESSARY	50.00	-
1	BODY SEALANT (SN)	NOT NECESSARY	50.00	-
1	REAR BUMPER SENSOR (SN)	NOT WORKING	400.00	200.00
1	WINDSCREEN SEALANT (SN)	NECESSARY	50.00	50.00
			550.00	250.00
<u>LABOUR</u>				
	TO REMOVE, REFIT & REPAIR AFFECTED DAMAGED PARTS, INCLUDING TO KNOCK-OUT, WELD & STRAIGHTEN ON THE AFFECTED PARTS.		800.00	400.00
	TO REMOVE & REFIT REAR GLASS.		120.00	100.00
	TO CHECK & RECONNECT ALL NECESSARY WIRING.		200.00	40.00
	TO REMOVE & REFIT ALL SENSOR.		80.00	30.00
	TO APPLY ANTI RUST COATING.		80.00	30.00
	TO SPRAY PAINT ON THE AFFECTED AREAS.		800.00	450.00
			2,080.00	1,050.00
GRAND TOTAL			4,990.00	2,922.88



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			2,300.00
---	--	--	----------

Report Ref No. CS/FCI23000457/Tvy3e2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.