

ASS. REC. BY: T. J. Smith

REF:

CS/PCI 23000457/Try3

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: **GBK 9307A**

Policy No. _____

Claims No. **D23000208MFCV**

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \$50k.

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: **SB04488E** Yr Regn: **2016, June**

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: **Honda Shuttle** c.c. **1496**

Colour: **Blue** A/C: Insured / Std / NI / NA

Sp. Reading: **83971** T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: **GBK1005073**

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: **205/50R16**

R: **205/50R16**

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front _____ Rear _____

R/Bal. **6** mm R/Bal. **6** mm

L/Bal. **6** mm L/Bal. **6** mm

D.O.A. **12/1/2023** D.O.I. **08/02/23 5pm**

Survey held at **MRM wheel/paver**

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
21/4/23	Lump Sum \$2300 confirmed by email (Red 2690, 53%)

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2) **21/4/23-typist**

Days Of Repair: **4**

Resurvey No. of Trip: **1**

Add Fee: ☐ : Site Insp (\$ _____)

☐ : Interview (\$ _____)

☐ : Tech. Invs (\$ _____)

☐ : Weekend (\$ _____)

Survey Fee:

Transportation:

\$ + RS. \$ _____

Photos

Others

TOTAL

Report Format: **TP**

Lump Sum / LB. / **\$2300**

MBM WHEELPOWER PTE. LTD.

YOUR REF.: GBK9307A

OUR REF.: SBD4488E

TO: FIRST CAPITAL

CC: MOTOR CLAIMS DEPARTMENT

FAX:

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

DATE: 16/1/2023
FROM: Lee Shirley
FAX: 64525333
CONTACT: 86865188
MAKE & MODEL: HONDA SHUTTLE 1.5G CVT
CHASSIS NO.: GK81005073
ENGINE NO.: L15B3535915
YEAR MADE: 2016
ACCIDENT DATE: 12 January 2023

ESTIMATE FOR VEHICLE NO.: SBD4488E

NO.	DESCRIPTION	PART NO.	QTY.	LIST PRICE
1	TAILGATE		1	\$ 1,300.00 1072
2	TAILGATE WEATHERSTRIP		1	\$ 160.00
3	TAILGATE LOCK		1	\$ 260.00
4	REAR BUMPER		1	\$ 1,080.00 926.60
5	REAR BUMPER SIDE RETAINER LH		1	\$ 50.00
6	REAR BUMPER SIDE RETAINER RH		1	\$ 50.00
7	REAR BUMPER CLIP		10	\$ 50.00
TOTAL:				\$ 2,950.00
LESS 20%:				\$ (590.00)
PARTS TOTAL:				\$ 2,360.00

SPECIAL NETT

NUMBER PLATE & HOLDER
BODY SEALANT
REAR BUMPER SENSOR
WINDSCREEN SEALANT

1	\$	50.00
1	\$	50.00
1	\$	400.00
1	\$	50.00

LABOUR

TO REMOVE, REFIT & REPAIR AFFECTED DAMAGED PARTS, INCLUDING TO KNOCK-OUT, WELD & STRAIGHTEN ON THE AFFECTED PARTS
TO REMOVE & REFIT REAR GLASS
TO CHECK & RECONNECT ALL NECESSARY WIRING
TO REMOVE & REFIT ALL SENSOR
TO APPLY ANTI RUST COATING
TO SPRAY PAINT ON THE AFFECTED AREAS

\$	400	800.00
\$	✓	120.00 100/
\$	40	200.00
\$	30	80.00
\$	20	80.00
\$	450	800.00

TOTAL: \$ 4,990.00

7% GST: \$ 349.30

GRAND TOTAL: \$ 5,339.30

Tanjim 97495749
in 8/2/23 5pm
1/5 Resurvey after repair
Tanjim e lkhanda.com
04 days

2922.88
1/5 \$2300
04 days

MBM WHEELPOWER PTE. LTD.
160 SIN MING DRIVE, #06-02
SIN MING AUTOCITY
t 6262 8888 f 6452 5333
COMPANY REG. NO.: 200204110W