



Your Ref: S2M040QZ

Date: 08<sup>th</sup> May 2023

Our Ref: CS3/ASM22004465/Twp3m4-1

**M/s HSBC Life (Singapore) Pte Ltd**

10 Marina Boulevard  
#48-01 Marina Bay Financial Centre Tower 2  
Singapore 018983  
(The Motor Claims Department)

Attn: Ang Yvonne

Dear Sir / Madam,

**EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: GBH 34L  
INSURED VEHICLE: SHA 980X  
ACCIDENT DATE: 10/05/2022**

We thank you for your instruction on 12/01/2023.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of GBH 34L from Impact Analysis Consulting Pte Ltd.
- b) Singapore Accident Statement of Vehicles GBH 34L, SHA 980X, SMF 5394U and XE 5254R.
- c) Police Report of Vehicles GBH 34L and XE 5254R.
- d) Final Repair Bill of GBH 34L from M/s Garage 13 Pte Ltd.
- e) Colour damaged vehicle photographs of GBH 34L.

Pre-Repair Inspection Date: 12/05/2022 at M/s Garage 13 Pte Ltd, 8 Kaki Bukit Ave 4 #03-46 Premier Singapore, 415875.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number : GBH 34L  
Make & Model : Toyota Dyna 150 5MT  
Year of Registration : 2017  
Chassis Number : JTFAT35Y10K209612  
Engine Capacity : 2982 cc

2. We recommend that the repairs of the entire damage require about 4 (Four) (Front), 6 (Six) (Rear) working days to complete.
3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.