



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no.: 6631 1188



TOYOTA

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

ESTIMATE

Account Details	Account No.	Acknowledged by Repairer Signature:	Customer Details
THIRD PARTY CLAIM	S1000020 / TPCLAIM	Date:	M/S Grab Rentals Pte Ltd
	Document No. 0		3 Media Close #01-03/06 Singapore 138498
	Document Date 13/01/2023		Work: 65703925

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2021	NHP170R	MWXNB H1	30/08/2021	SNB5789Z	0	19633	75/DS/SNB5789Z

Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On
JTDZZ9H380L000780	1NZ9305301	60	Ng Mei Yen	--/--/----	0.00 --/--/---- 0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	Z	BP-GRAB-DS SUNDRIES - FLASH ARRIVE: DD/MM/YY 0000HR TP VEH NO.:PC2410G ACC DATE:13/01/23 DRIVE IN:13/01/23 EXCESS: DATE-IN: DATE SURVEY: NO OF REPAIR DAYS: BY: AUTHORISED ON:				50 100.00
2	B	BP-LAB2 CHECK WIRING AND CONDUCT LEAK TEST				198.00
3	B	BP-ECU2 TO RESET ECU AND REPROGRAMME				198.00
4	B	BP-LAB2 REPL ACC AFF AREA STRAIGHTEN AND PANEL BEAT ACC AFF AREA				1584 3168.00
5	B	BP-RES2 RESPRAY ACC AFF AREA				1312 204.00
6	1	T52119-5A967 COVER, FR BUMPER	1.00	381.60		381.60
7	2	T52161-16010 PIECE, RR BUMPER	10.00	5.40		54.00
8	3	T52126-52070 BRACKET, FOG LAMP	1.00	58.30		58.30
9	4	T52611-52350 ABSORBER, FR BUMPER	1.00	96.10		96.10
10	5	T53101-52670 GRILLE SUB-ASSY,	1.00	986.60		986.60
11	6	T53812-52480 PANEL, FR FENDER, LH	1.00	696.90		696.90
12	7	T53828-52180 PROTECTOR, FR FENDER	1.00	103.30		103.30
13	8	T53876-52330 LINER, FR FENDER, LH	1.00	207.30		207.30
14	9	T81170-52M90 UNIT ASSY, HEADLAMP,	1.00	1222.10		1222.10

For & on behalf of	Customer's Signature	Charge Summary	Total
Borneo Motors (Singapore) Pte Ltd			10,094.20
	Please acknowledge receipt of vehicle	Parts 3,806.20 Labour 6,288.00 Sublet 0.00 Lubrication/Fluid 0.00 Others 0.00	GST 8.00% 807.54
			Less 0.00
			Amount Due 10,901.74

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	200G
Vehicle Details	
Vehicle No.:	SNB5789Z
Vehicle to be Exported:	No
Intended Deregistration Date:	16 Jan 2023
Vehicle Make:	TOYOTA
Vehicle Model:	SIENTA HYBRID STANDARD (AUTO)
Primary Colour:	Yellow
Manufacturing Year:	2021
Engine No.:	1NZ9305301
Chassis No.:	JTDZZ9H380L000780
Maximum Power Output:	73.0 kW (97 bhp)
Open Market Value:	\$24,907.00
Original Registration Date:	30 Aug 2021
First Registration Date:	30 Aug 2021
Transfer Count:	0
Actual ARF Paid:	\$11,870.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	29 Aug 2031
PARF Rebate Amount:	\$8,902.00
Intended COE Rebate Details	
COE Expiry Date:	29 Aug 2031
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$45,600.00
COE Rebate Amount:	\$39,299.00
Total Rebate Amount:	\$48,201.00

The information contained herein is correct as at 16 Jan 2023

Toyota Sienta Hybrid 1.5A X

Overview

Financial

Accessories

Similar

Research

Photos

Map



CAR CHOICE
SINGAPORE

The Best Buying Experience



Price

\$120,988

Depreciation

\$13,090 /yr

[View models with similar depre](#)

Reg Date

16-Nov-2021

(8yrs 9mths 30days COE left)

Mileage

68 km (0.1k /yr)

Manufactured

2021

Road Tax

N.A.

Transmission

Auto

Dereg Value

\$55,500 as of today ([change](#))

Fuel Type

Petrol-Electric

COE

\$53,709

OMV

\$24,090

Engine Cap

1,496 cc

ARF

\$10,726

Curb Weight

N.A.

Power

73.0 kW (97 bhp)