

(08/11/23)

AR

ASS. REC. BY: John

REF:

CS/AIS 23000478/RVJB

C
7782**ASSIGNMENT**

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MVTo inspect Vehicle No: SHA 3030Eat Workshop m/s CYCLE & CARRIAGEof 188, Pinner Lane

Insured:

ALSPolicy No. SP2003907937Claims No. 202332004529

Sum Insured:


Excess:

700

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

280k

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

REPAIR LIMIT - 114k

26/5/23 Final fig \$24,670.50 confirmed by email (red 3745.66, 13%)

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2) 26/5/23-typist

Report Format : Merimen

Lump Sum / I.B.I: (\$24,670.50)

Veh No:

SHA 3030E

Yr Regn:

2022 / NOVType: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

MERCEDES BENZ E300E AV c.c.

Colour

BLUE

A/C:

Insured / Std / NI / NA

Sp. Reading

2577

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

WIK2130532B 048273Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: NII / S/Rim / STD A/Rim or

Tyre Size:

F:

245/40R19

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

R/Bal.

L/Bal.

L/Bal.

D.O.A.

D.O.I.

Survey held at

CYCLE & CARRIAGE (PC)Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop orO/S REAR

The U/C / Chassis frame / Body Structure affected due to collision.

Days Of Repair: 11Resurvey No. of Trip: 1

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

Allianz Insurance Singapore Pte. Ltd.

CERTIFICATE OF INSURANCE

ROAD TRANSPORT ACT 1987 (MALAYSIA)
 MOTOR VEHICLES (THIRD-PARTY RISKS) RULES 1959 (FEDERATION OF MALAYSIA)
 MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CAP.189 OF THE REVISED EDITION) (REPUBLIC OF SINGAPORE)
 MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) RULES 1996 (REPUBLIC OF SINGAPORE)
 MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) RULES, 1960
 OR ANY AMENDMENT, ACT OR ACTS PASSED IN SUBSTITUTION THEREOF

Certificate Number	: SP2003907937
Date of Issue	: 27 December 2022
Coverage	: COMPREHENSIVE - AUTHORISED WORKSHOP
Policyholder	: MERCEDES-BENZ FLEET MANAGEMENT SINGAPORE PTE. LTD.
Finance Company	: -
Period of Insurance	: 01 January 2023 To 31 December 2023 (both dates inclusive)
Registration Number	: SGA3030E
Chassis Number of Vehicle	: W1K2130532B048273

Persons or Classes of Persons Entitled to Drive*:

- (a) The Policyholder.
 - (b) Any other person who is driving on the Policyholder's order or with his/her permission or to whom the vehicle is hired.
- * Provided that the person driving is permitted in accordance with the licensing or other laws or regulation to drive the Motor Vehicle or has been permitted and is not disqualified by order of Court of Law or by reason of any enactment or regulations in that behalf from driving the Motor Vehicle. And provided further that the Motor Vehicle is registered under the Road Traffic Act (Cap 276) (Republic of Singapore) and such registration has not been cancelled at the time of accident loss or damage.

Limitation as to Use*:

- (a) Use for carriage of passengers or goods in connection with the Policyholder's business.
 - (b) Use for social, domestic and pleasure purposes and business purposes of any person to whom the vehicle is hired.
- * Limitation rendered inoperative by Section 8 of Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

Policy does not cover:

- (a) Use for racing, pace-making, reliability trials or speed-testing.
- (b) Use whilst drawing a trailer except the towing (other than for reward) of any one disabled mechanically propelled vehicle.
- (c) Use for the carriage of passengers for hire or reward by any person to whom the vehicle is hired.

I/We hereby certify that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia).

27 December 2022

Issue Date



Hicham Raissi
 Chief Executive Officer

Allianz Insurance Singapore Pte. Ltd.

Intermediary Code	: 0000256 MARSH (SINGAPORE) PTE. LTD.
Excess	: Section 1: Own Damage
	: Section 1: Windscreen
	: Section 2: Liabilities to Third Parties

S\$	700.00
S\$	100.00
S\$	0.00

10:45



0.10
KB/s



5G



77



DRIVING LICENCE

REPUBLIC OF SINGAPORE



LICENCE NO.

S7301122A



CLASS AND ISSUE DATE

3 • 10 OCT 1991

CERTIFICATE OF MERIT

NOT ELIGIBLE

DEMERIT POINTS

8

CARD SERIAL NO.

000896190F



Hide details



SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	13/01/2023 11:27 (SGT)
Reported by	Driver
Date of Accident	13/01/2023 07:00 (SGT)
Exact Location of Accident	Singapore
Additional Location Information	EAST COAST ROAD
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SGA3030E
-----------------------------	----------

INSURED/POLICYHOLDER

Is company?	Yes
Name Of Registered Owner	MERCEDES-BENZ FLEET MANAGEMENT SINGAPORE PTE. LTD.
Company Reg No	1XXXXX778Z
Email Address	MERVYN.FONG@MERCEDES-BENZ.COM
Mobile Phone No	(Phone) +65-92203199
Alternative Phone No	-

VEHICLE PARTICULARS

Manufacturer	Mercedes
Model	E300e
Variant	-
Exact purpose for which vehicle was being used at time of accident	-
Are you claiming under your own insurance policy for repair to your vehicle?	Yes
Vehicle Category	Private car
Transmission	Auto
CC	1991

INSURANCE COMPANY

Name of Insurance Company	Allianz Insurance Singapore Pte. Ltd.
Policy Number / Cover Note Number	SP2003907937

DRIVER

Name of Driver	CHUA CHEE GAY
NRIC No	SXXXX122A
Date Of Birth	04/01/1973

Occupation	Indoor
Date Of Driving Pass	10/10/1991
Driving experience	31 YEARS AND 3 MONTHS
Gender	Male
Mobile Number	(Phone) +65-96993030
Alt. Phone Number	-
Email Address	CHEEGAY@THB.COM.SG
Address	3A TAY LIAN TECK DRIVE
Address complement	-
Postcode	455643
Is the driver the policyholder?	No
If No, Relationship of the Driver with the Insured	LEASING
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Side Swipe
Weather Conditions	Clear
Road Surface	Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	2
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No
Translator's name	-
Translator's ID	-
Translator's phone number	-
Translator's email	-
Original language used in the statement	-

PASSENGER 1

Name	UNKNOWN
Gender	Male

DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

CAR 'B' SUDDENLY CUT INTO MY LANE FROM THE ONLY RIGHT TURN AND BRUSHED INTO MY CAR.

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	Yes
Reasons for not uploading a video of the accident	KINDLY REFER TO CSE CH.

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLW9126Z
Vehicle Manufacturer	Audi

Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	White
Vehicle Category	Private car
Name of Driver	-
Passport No/FIN	SXXXX4971
Contact Number	-
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;

(ii) investigating the accident and/or my claims;

(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;

(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or

(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan

Go Chee Han
DID: 6771 4336 HP: 9181 7717
Email: cheehan.go@cyclecarriage.com.sg
Cycle & Carriage Industries Pte Ltd
Insurance Service Centre - Pandan Loop

A: SGA3030E
B: SLW9126E

↑ ↑ ↑

Describe Circumstances of the Accident

Car 'B' suddenly cut into my lane from the only right turn lane and brushed into my car.

Declaration

We declare the foregoing particulars are true in every respect.

Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Go Chee Han
DID : 6771 4336 HP : 9181 7717
Email : charliego@gocheehang.com.sg
Cycle & Carriage Insurance Pte Ltd
Chartered Surveyors & Assessors



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SGA3030E

ALLIANZ INSURANCE SINGAPORE PTE.
LTD.
MOTOR CLAIM DEPARTMENT
79 ROBINSON ROAD
#09-01
SINGAPORE 068897
67143369

Vehicle & Document Information
WIP No 62398
Reg No/Reg Date SGA3030E / 29/11/2022
Date In/Mileage / 0
Chassis No W1K2130532B0482733
Engine No 27492032014190
Make/Model MB/E 300 e SEDAN
Colour/Trim 025 595 Nautic Blue/ 042 201 Leather Bla

Account No	Terms	Date/Time Printed	CSE	Operator
WA000001	Credit	13/01/2023/ 18:19	CH	371 / Go Chee Han
Description of Goods / Services				
Qty	Unit Price	Disc%	Amount	

Z REQUEST

Customer Request
M BPNSUN

POLICY NO/ACC DATE : SP2033907937 // 13-1-2023
DRIVE IN/EXCESS : 13-1-2023 // TBA
DATE IN/DATE SURVEY:
BY/AUTHORIZED ON :

A BPILAB

PANEL BEATING TO REPAIR AFFECTED AREAS, REMOVE AND REPLACE WITH NEW BODY PANELS AND REFINISH.

A BPIRES

RESPRAY RH/FRONT DOOR & RH/REAR DOOR & RH/REAR FENDER & REAR BUMPER RH/RUNNING BOARD & END PANEL

A BPILAB

USING XENTRY DIAGNOSTIC TO CHECK ON CONTROL UNIT RESET MEMORY TO IDENTIFICATION STANDARD. NETT

A BPILAB

CHECK REAR LIGHTING SYSTEM AND WATER TEST FOR ANY LEAKAGE. NETT

A 72164001

REPLACE RIGHT REAR DOOR, TRANSFER COMPONENT PARTS

A BPILAB

REMOVE & REFIT LUGGAGE COMPARTMENT, TRIM, GARNISH-CARPET FOR NECESSARY REPAIR. NETT

A BPILAB

REMOVE & INSTALL INTERIOR SEATS, CARPET, GARNISH UNHOLSTRY ETC FOR NECESSARY REPAIR.

A BPILAB

TO DRAIN OUT PETROL & REPLACE FUEL TANK RECESS IF NECESSARY. NETT

A BPILAB

TO INSPECT & CONDUCT WHEEL ALIGNMENT. NETT

S BPNSUB

LABOUR TO REMOVE AND INSTALL TYRE FROM RIM, (RUN FLAT)
WHEEL BALANCE AND INSTALL NEW VALVE HEAD

From Hy 90010068
11 days
17/01/23 @ 1530
EXCESS : 700
Revers
Resy before paint

4800 6720.00

4000 4200.00

0.10 380.00

120.00

480.00

480.00

960 1440.00

240.00

540.00

60.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Go Chee Han

DID: 6771 4336 HP: 9181 7717

Email: cheehan.go@cyclecarrriage.com.sg

Cycle & Carriage Industries Pte Ltd

Customer Service Centre - Pandan Loop

Confirmed & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg



and Mercedes-Benz are trademarks of Mercedes-Benz Group AG



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SGA3030E

ALLIANZ INSURANCE SINGAPORE PTE.
LTD.
MOTOR CLAIM DEPARTMENT
79 ROBINSON ROAD
#09-01
SINGAPORE 068897
67143369

Vehicle & Document Information
WIP No 62398
Reg No/Reg Date SGA3030E / 29/11/2022
Date In/Mileage / 0
Chassis No W1K2130532B0482733
Engine No 27492032014190
Make/Model MB/E 300 e SEDAN
Colour/Trim 025 595 Nautic Blue/ 042 201 Leather Bla

Account No	Terms	Date/Time Printed	CSE	Operator	Qty	Unit Price	Disc%	Amount
WA000001	Credit	13/01/2023/ 18:19	CH	371 / Go Chee Han			0.07	560.00
Description of Goods / Services								
A BPILAB								300.00
S BPNSUB REMOVE & REPLACE REAR WINDSCREEN WITH INSTALL . NETT								180.00
SUPPLY & INSTALL 1 PC REAR WINDSCREEN HUPER OPTIK SOLAR FILM.NETT								120.00
A 97250001 CAVITY PRESERVATION ON REPLACED OR REPAIRED BODY PANELS PERFORM								
A 97510101 BEADS, SEAMS AND FLANGES ON REPLACEMENT BODY PANELS/ COMPONENTS								
M RH/REAR DOOR					1.00	2946.63	00.00	2946.63
M RH/REAR DOOR SEAL					1.00	317.72	00.00	317.72
M RH/REAR DOOR INSULATION					1.00	44.29	00.00	44.29
M RH/REAR DOOR DOWEL					2.00	4.40	00.00	8.80
M RH/REAR FENDER					1.00	2648.20	00.00	2648.20
M TANK FILLER RECESS					1.00	237.80	00.00	237.80
M INTERMEDIATE LAYER					1.00	5.12	00.00	5.12
M REAR WINDOW					1.00	1566.23	00.00	1566.23
M WINDOW ANTENNA					1.00	145.80	00.00	145.80
M ONE-COMPONENT ADHESIVE					2.00	183.81	00.00	367.62
M RH/REAR DISK WHEEL					1.00	966.89	00.00	966.89
M REAR BUMPER					1.00	987.75	00.00	987.75
M RIVET FOR BUMPER					12.00	5.34	00.00	64.08
M RH/RUNNING BOARD					1.00	907.86	00.00	907.86
M WHITE SEAM SEALING COMPOUND					1.00	116.42	00.00	116.42
M BLIND RIVET 6.4 X 12					20.00	1.70	00.00	34.00
M BLIND RIVET W CSK. HEAD 6.4 X 14.0					3.00	2.01	00.00	6.03
M TS TWO-COMPONENT ADHESIVE					1.00	904.72	00.00	904.72
M TWO-COMPONENT ADHESIVE					1.00	118.43	00.00	118.43
M CAVITY PRESERVATIVE					1.00	116.39	00.00	116.39
M ZINC DUST PAINT					1.00	66.41	00.00	66.41

Go Chee Han
DID: 6771 4336 HP: 9181 7717
Email: cheehan.go@cyclecarrage.com.sg
Cycle & Carriage Industries Pte Ltd
Customer Service Centre - Pandan Loop

Confirmed & accepted by

8% GST on **Nett** 28,397.19
28397.19 **2271.78**
Total Payable 30,668.97

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.
Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg



and Mercedes-Benz are trademarks of Mercedes-Benz Group AG



Mercedes-Benz

SUPPLEMENTARY

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SGA3030E

ALLIANZ INSURANCE SINGAPORE PTE.
LTD.
MOTOR CLAIM DEPARTMENT
79 ROBINSON ROAD
#09-01
SINGAPORE 068897
67143369

Vehicle & Document Information

WIP No 62398
Reg No/Reg Date SGA3030E / 29/11/2022
Date In/Mileage 20/02/2023/ 9757
Chassis No W1K2130532B0482733
Engine No 27492032014190
Make/Model MB/E 300 e SEDAN
Colour/Trim 025 595 Nautic Blue/ 042 201 Leather Bla

Account No	Terms	Date/Time Printed	CSE	Operator	Description of Goods / Services	Qty	Unit Price	Disc%	Amount
WA000001	Credit	25/05/2023/ 18:08	CH	371 / Go Chee Han					
M. BPNSUN									
POLICY NO/ACC DATE : SP2033907937 // 13-1-2023									
DRIVE IN/EXCESS : 13-1-2023 // \$700									
DATE IN/DATE SURVEY: 17-1-2023 // RASUL - LKK									
BY/AUTHORIZED ON : 20-1-2023 // VERON - LKK									
X DAMPING, SIDE WALL						1.00	18.97	00.00	18.97

Confirmed & accepted by

8% GST on **Nett 18.97** **1.52**

Total Payable 20.49

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.
Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6298 1818
Fax: 6779 5383
www.mercedes-benz.com.sg



and Mercedes-Benz are trademarks of Mercedes-Benz Group AG