

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To inspect Vehicle No: SHA 3030Eat Workshop m/s CYCLE & CARRIAGEof 188, 1st Mon LoopInsured: ALW

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: 700

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: 280K

IDAC Accident Report: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUTVeh No: SHA 3030E Yr Regn: 2022 / NOVType: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: MERCEDES BENZ E300E AV c.c. _____Colour: BLUE A/C: Insured / Std / NI / NASp. Reading: 2577 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WIK2130532B 048273Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 245/40R19

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 6 mm R/Bal. 6 mmL/Bal. 6 mm L/Bal. 6 mmD.O.A. 13/01/23 D.O.I. 17/01/23Survey held at CYCLE & CARRIAGE (PC)

Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or

O/S REAR

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

REPAIR LIMIT - 114K

Date/Time, File Pass to?



: Preli. Report

1)



: Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech. Invs (\$☐ : Weekend (\$

Survey Fee:

Transportation:

S + RS SI

Photos

Others

Report Format : _____

Lump Sum / I.B.I: (\$ _____)

TOTAL



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SGA3030E

ALLIANZ INSURANCE SINGAPORE PTE.
LTD.
MOTOR CLAIM DEPARTMENT
79 ROBINSON ROAD
#09-01
SINGAPORE 068897
67143369

Vehicle & Document Information
WIP No 62398
Reg No/Reg Date SGA3030E / 29/11/2022
Date In/Mileage / 0
Chassis No W1K2130532B0482733
Engine No 27492032014190
Make/Model MB/E 300 e SEDAN
Colour/Trim 025 595 Nautic Blue/ 042 201 Leather Bla

Account No	Terms	Date/Time Printed	CSE	Operator			
WA000001	Credit	13/01/2023/ 18:19	CH	371 / Go Chee Han			
Description of Goods / Services				Qty	Unit Price	Disc%	Amount

Z REQUEST

Customer Request
M-BPNSUN

POLICY NO/ACC DATE : SP2033907937 // 13-1-2023
DRIVE IN/EXCESS : 13-1-2023 // TBA
DATE IN/DATE SURVEY:
BY/AUTHORIZED ON :

A BPILAB

PANEL BEATING TO REPAIR AFFECTED AREAS, REMOVE AND REPLACE WITH NEW BODY PANELS AND REFINISH.

A BPIRES

RESPRAY RH/FRONT DOOR & RH/REAR DOOR & RH/REAR FENDER & REAR BUMPER RH/RUNNING BOARD & END PANEL

A BPILAB

USING XENTRY DIAGNOSTIC TO CHECK ON CONTROL UNIT RESET/MEMORY TO IDENTIFICATION STANDARD. NETT

A BPILAB

CHECK REAR LIGHTING SYSTEM AND WATER TEST FOR ANY LEAKAGE. NETT

A 72164001

REPLACE RIGHT REAR DOOR, TRANSFER COMPONENT PARTS

A BPILAB

REMOVE & REFIT LUGGAGE COMPARTMENT, TRIM, GARNISH-CARPET FOR NECESSARY REPAIR. NETT

A BPILAB

REMOVE & INSTALL INTERIOR SEATS, CARPET, GARNISH UNHOLSTRY ETC FOR NECESSARY REPAIR.

A BPILAB

TO DRAIN OUT PETROL & REPLACE FUEL TANK RECESS IF NECESSARY. NETT

A BPILAB

TO INSPECT & CONDUCT WHEEL ALIGNMENT. NETT

S BPNSUB

LABOUR TO REMOVE AND INSTALL TYRE FROM RIM, (RUN FLAT)
WHEEL BALANCE AND INSTALL NEW VALVE HEAD

Confirmed & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Go Chee Han

DID : 6771 4336 HP : 9181 7717

Email : cheechee.go@cyclocarriage.com.sg

Cycle & Carriage Industries Pte Ltd

Customer Service Centre - Pandan Loop

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SGA3030E

ALLIANZ INSURANCE SINGAPORE PTE.
LTD.
MOTOR CLAIM DEPARTMENT
79 ROBINSON ROAD
#09-01
SINGAPORE 068897
67143369

Vehicle & Document Information
WIP No 62398
Reg No/Reg Date SGA3030E / 29/11/2022
Date In/Mileage / 0
Chassis No W1K2130532B0482733
Engine No 27492032014190
Make/Model MB/E 300 e SEDAN
Colour/Trim 025 595 Nautic Blue/ 042 201 Leather B1a

Account No	Terms	Date/Time Printed	CSE	Operator				
WA000001	Credit	13/01/2023/ 18:19	CH	371 / Go Chee Han				
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
A BPILAB							0.07	560.00
REMOVE & REPLACE REAR WINDSCREEN WITH INSTALL . NETT								300.00
S BPN SUB								180.00
SUPPLY & INSTALL 1 PC REAR WINDSCREEN HUPER OPTIK SOLAR FILM.NETT								120.00
A 97250001								
CAVITY PRESERVATION ON REPLACED OR REPAIRED BODY PANELS PERFORM								
A 97510101								
BEADS, SEAMS AND FLANGES ON REPLACEMENT BODY PANELS/ COMPONENTS								
M	RH/REAR DOOR	1.00	2946.63	00.00	2946.63			
M	RH/REAR DOOR SEAL	1.00	317.72	00.00	317.72			
M	RH/REAR DOOR INSULATION	1.00	44.29	00.00	44.29			
M	RH/REAR DOOR DOWEL	2.00	4.40	00.00	8.80			
M	RH/REAR FENDER	1.00	2648.20	00.00	2648.20			
M	TANK FILLER RECESS	1.00	237.80	00.00	237.80			
M	INTERMEDIATE LAYER	1.00	5.12	00.00	5.12			
M	REAR WINDOW	1.00	1566.23	00.00	1566.23			
M	WINDOW ANTENNA	1.00	145.80	00.00	145.80			
M	ONE-COMPONENT ADHESIVE	2.00	183.81	00.00	367.62			
M	RH/REAR DISK WHEEL	1.00	966.89	00.00	966.89			
M	REAR BUMPER	1.00	987.75	00.00	987.75			
M	RIVET FOR BUMPER	12.00	5.34	00.00	64.08			
M	RH/RUNNING BOARD	1.00	907.86	00.00	907.86			
M	WHITE SEAM SEALING COMPOUND	1.00	116.42	00.00	116.42			
M	BLIND RIVET 6.4 X 12	20.00	1.70	00.00	34.00			
M	BLIND RIVET W CSK. HEAD 6.4 X 14.0	3.00	2.01	00.00	6.03			
M	TS TWO-COMPONENT ADHESIVE	1.00	904.72	00.00	904.72			
M	TWO-COMPONENT ADHESIVE	1.00	118.43	00.00	118.43			
M	CAVITY PRESERVATIVE	1.00	116.39	00.00	116.39			
M	ZINC DUST PAINT	1.00	66.41	00.00	66.41			

THIS IS NOT AN OFFICIAL TAX INVOICE

ESTIMATE

Go Chee Han
DID : 6771 4336 HP : 9181 7717
Email : cheehan.go@cyclcarriage.com.sg
Cycle & Carriage Industries Pte Ltd
Customer Service Centre - Pandan Loop

Go Chee Han
DID : 6771 4336 HP : 9181 7717
Email : cheehan.go@cyclcarriage.com.sg
Cycle & Carriage Industries Pte Ltd
Customer Service Centre - Pandan Loop

Confirmed & accepted by

8% GST on 28397.19
Total Payable 30,668.97

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.
Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6777 5292

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Company
Owner ID:	778Z

Vehicle Details

Vehicle No.:	SGA3030E
Vehicle to be Exported:	No
Intended Deregistration Date:	18 Jan 2023
Vehicle Make:	MERCEDES BENZ
Vehicle Model:	E300E AVANTGARDE LEDHL
Primary Colour:	Blue
Manufacturing Year:	2022
Engine No.:	27492032014190
Chassis No.:	W1K2130532B048273
Maximum Power Output:	245.0 kW (328 bhp)
Open Market Value:	\$63,212.00
Original Registration Date:	29 Nov 2022
First Registration Date:	29 Nov 2022
Transfer Count:	0

Actual ARF Paid:	\$70,782.00
------------------	-------------

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	28 Nov 2032
PARF Rebate Amount:	\$53,086.00

Intended COE Rebate Details

COE Expiry Date:	28 Nov 2032
COE Category:	B - Car-Details at OneMotoring
COE Period(Years):	10
QP Paid:	\$113,881.00
COE Rebate Amount:	\$112,299.00
Total Rebate Amount:	\$165,385.00

The information contained herein is correct as at 18 Jan 2023

OK

Mercedes-Benz E-Class E300e Plug-in Hybrid Avantgarde



WWW.SGCARMART.COM

1 / 9

PREMIUM AD

Price	\$266,666
Depreciation	<div>i</div> \$24,920 / year
Reg. Date	25-Apr-2022 (9yrs 3mths 6days COE left)
Manufactured	<div>i</div> 2022
Mileage	10,000 km
Transmission	Auto
Engine Cap	1,991 cc
Road Tax	<div>i</div> \$1,202 / year
Power	245.0 kW (328 bhp) View specs of the Mercedes-Benz E-Class Saloon Plug-in Hybrid
Curb Weight	<div>i</div> 1,915 kg
Fuel Type	Petrol-Electric
COE	<div>i</div> \$94,889
OMV	<div>i</div> \$63,481
ARF	<div>i</div> \$71,266
Dereg Value	<div>i</div> \$141,423 as of today
No. of Owners	<div>i</div> 1
Type of Veh	Luxury Sedan
Features	
Original Condition.	
Accessories	