



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### Affiliated to Federation Internationale Des Experts En Automobile

MS FIRST CAPITAL INSURANCE LTD  
16 RAFFLES QUAY  
#42-01 HONG LEONG BUILDING  
SINGAPORE 048581

Ref: CS/FCI23000480/Kwy3q2

Date: 25/04/2023

Code: FCI2

#### 1. Policy Particulars :- THIRD PARTY CLAIM

<b>Insured Veh.</b>	YL 4694L	<b>Veh. Inspected</b>	GBJ 7223B
<b>Policy No.</b>	D-22099586MFCV/1	<b>Coverage (\$)</b>	0.00
<b>Claim No.</b>	D23000008MFCV	<b>Excess (\$)</b>	0.00
<b>Assign From</b>	CAROLINE CABRERA	<b>Assign Date</b>	16/01/2023

#### 2. Vehicle Particulars & Condition

<b>Make &amp; Model</b>	MERCEDES BENZ SPRINTER 316CDI (A)	<b>c.c</b>	2143
<b>Engine No.</b>	HIDDEN	<b>Year of Reg.</b>	2019
<b>Chassis No.</b>	WDB9076332P104507	<b>Colour</b>	WHITE
<b>Odometer</b>	120599 KM	<b>Steering</b>	IN ORDER
<b>Brakes</b>	IN ORDER	<b>Modification</b>	NIL
<b>General</b>	GOOD		

#### 3. Conditions of Tyres

	Size	Make	Balance
<b>R/H Front Tyre</b>	235/65 R16	MICHELIN	8 mm
<b>L/H Front Tyre</b>	235/65 R16	MICHELIN	8 mm
<b>R/H Rear Tyre</b>	235/65 R16	TOYO	7 mm
<b>L/H Rear Tyre</b>	235/65 R16	TOYO	7 mm

#### 4. Description of Damages

	THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION. DAMAGES SEE DETAILS.
--	---

#### 5. General Information

<b>Accident Date</b>	21/12/2022	<b>Inspection Date</b>	17/01/2023
<b>Survey held at</b>	BLK 160 SIN MING DRIVE #02- 01 AUTOCITY (S) 575722		
<b>Repairer</b>	MEGA AUTO PTE LTD		

#### 5a. Remarks

	A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--	--

#### 5b. Estimate Days of Repair

	ESTIMATED NORMAL PERIOD FOR REPAIR:	<b>3 Working Days</b>
--	-------------------------------------	-----------------------