



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LIBERTY INSURANCE PTE LTD 51 CLUB STREET, #03-00 LIBERTY HOUSESINGAPORE 069428			Ref: CS/LIP23000485/Kvy3m4 Date: 31/01/2023 Code: LIP	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SNB 4158B	Veh. Inspected	SFJ 4338B
	Policy No.		Coverage (\$)	0.00
	Claim No.	IVS23/0092	Excess (\$)	0.00
	Assign From	TED SEAH	Assign Date	16/01/2023
2. Vehicle Particulars & Condition				
	Make & Model	TOYOTA CAMRY (A)	c.c	2487
	Engine No.	HIDDEN	Year of Reg.	
	Chassis No.	AXVH701028164	Colour	METALLIC PEARL WHITE
	Odometer	91147 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	215/55 R17	YOKOHAMA	9 mm
	L/H Front Tyre	215/55 R17	YOKOHAMA	9 mm
	R/H Rear Tyre	215/55 R17	YOKOHAMA	9 mm
	L/H Rear Tyre	215/55 R17	YOKOHAMA	9 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	06/01/2023	Inspection Date	17/01/2023
	Survey held at	TK CAR REPAIRS 176 SIN MING DRIVE #01-12 SIN MING AUTOCARE SINGAPORE 575721		
5a. Remarks				
	A)REGISTRATION DATE: 15 JUL 2019 B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days	