

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile						
	LONPAC INSURAN	NCE BHD		Ref:	CS/LPC23000487/Avy3e2	
	300 BEACH ROAD #17-04/07 THE CO	NCOURSESINGAPORE 199555		Date:	03/03/2023	
				Code:	LPC2	
1.	Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	XE 3178R	Veh. Inspected	k	SMS 8459D	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	22/23/23/VC06/026840	Excess (\$)		0.00	
	Assign From	GERALD POH	Assign Date		16/01/2023	
2.	2. Vehicle Particulars & Condition					
	Make & Model	HONDA SHUTTLE	c.c		1496	
	Engine No.	HIDDEN	Year of Reg.		2020	
	Chassis No.	GK82103487	Colour		RED	
	Odometer	30408 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	GOOD				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	205/50 R16	CONTINENTAL		6 mm	
	L/H Front Tyre	205/50 R16	CONTINENTAL		6 mm	
	R/H Rear Tyre	205/50 R16	CONTINENTAL		6 mm	
	L/H Rear Tyre	205/50 R16	CONTINENTAL		6 mm	
4.	1. Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION.					
	DAMAGES SEE DETAILS.					
5.	General Information					
	Accident Date	13/01/2023	Inspection Dat	te	16/01/2023	
	Survey held at	JEC AUTO SERVICE PTE LTD				
		1 KAKI BUKIT AVENUE 6 #02-11 AUTOBAY SINGAPORE 417883				
5a.	Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	Estimate Days of Repair					
	ESTIMATED NORMAL PERIOD FOR REPAIR: 9 Working Days					