

JEC AUTO SERVICE PTE LTD

1 KAKI BUKIT AVENUE 6, #02-11 AUTOBAY@KAKI BUKIT
SINGAPORE 417883
TEL: 92327457

TO	: LONPAC	DATE	: 16/1/2023
ATTENTION	: MOTOR INSURANCE CLAIM	JOB TYPE	: T/P CLAIM
ESTIMATE REPORT	:		
VEHICLE DETAILS			
VEHICLE NO	: SMS8459D		
VEHICLE MODEL	: HONDA SHUTTLE		
CHASSIS NO	: GK82103487		
ACCIDENT DETAILS	DATE	:	
	TIME	:	
THIRD PARTY REQUESTOR / CONTACT	:	XIAN / 92327457	

CLAIM DETAILS: PARTS

	ITEMS	QTY	UNIT PRICE	TOTAL	
1	FRONT BUMPER <i>Distorted</i>	1	\$ 1,050.50	\$ 1,050.50	✓
2	FRONT BUMPER SIDE HOLDER <i>Distorted</i>	1	\$ 35.90	\$ 35.90	✓
3	FRONT BUMPER FOG LAMP COVER <i>New</i>	1	\$ 65.80	\$ 65.80	+
4	HEADLAMP <i>Cracked</i>	1	\$ 2,128.70	\$ 2,128.70	✓
5	HEADLAMP LOWER BRACKET <i>Cracked</i>	1	\$ 48.30	\$ 48.30	✓
6	BONNET <i>Distorted</i>	1	\$ 1,080.10	\$ 1,080.10	+
7	BONNET HINGE <i>New</i>	1	\$ 98.50	\$ 98.50	+
8	FRONT LH FENDER <i>Distorted</i>	1	\$ 489.50	\$ 489.50	✓
9	FRONT LH FENDER INNER SHIELD <i>New</i>	1	\$ 158.90	\$ 158.90	✓
10	FRONT LH FENDER GLASS <i>3 new</i>	1	\$ 369.40	\$ 369.40	+
11	FRONT LH FENDER GLASS MOULDING <i>3 new</i>	1	\$ 74.10	\$ 74.10	+
12	FRONT LH FENDER INNER MEMBER <i>Broken</i>	1	\$ 485.20	\$ 485.20	+
13	FRONT LH FENDER INNER ENCLOSURE <i>New</i>	1	\$ 34.30	\$ 34.30	+
14	FRONT LH DOOR <i>Distorted</i>	1	\$ 1,154.10	\$ 1,154.10	✓
15	FRONT LH DOOR LOCK <i>3 new</i>	1	\$ 321.30	\$ 321.30	+
16	FRONT LH DOOR WEATHERSTRIPE <i>3 new</i>	1	\$ 193.40	\$ 193.40	+
17	FRONT LH DOOR HINGE <i>3 new</i>	2	\$ 48.90	\$ 97.80	+
18	FRONT LH DOOR CHECK <i>3 new</i>	1	\$ 52.40	\$ 52.40	+
19	FRONT LH DOOR WING MIRROR <i>Missing</i>	1	\$ 754.90	\$ 754.90	✓
20	FRONT LH DOOR GLASS <i>New</i>	1	\$ 468.70	\$ 468.70	+
21	FRONT LH DOOR GLASS OUTER MOULDING <i>cut</i>	1	\$ 105.40	\$ 105.40	✓
22	FRONT LH DOOR INNER TRIM BOARD <i>New</i>	1	\$ 554.90	\$ 554.90	+
23	ROCKER PANEL SIDE SKIRTING LH <i>3 new</i>		\$ 650.30	\$ 650.30	+
24	FRONT LH LOWER ARM <i>Broken</i>	1	\$ 321.80	\$ 321.80	✓
25	FRONT LH SHOCK ABSORBER <i>Broken</i>	1	\$ 345.10	\$ 345.10	✓

26	FRONT LH KNUCKLE ARM <i>Dm</i>	1	\$	395.50	\$ 395.50	-
27	FRONT LH WHEEL HUB C/W BEARING <i>Dm</i>	1	\$	294.20	\$ 294.20	-
28	FRONT LH ANTI ROLL BAR LINKAGE <i>3m</i>	1	\$	109.80	\$ 109.80	+
29	STEERING RACK & PINION <i>3m</i>	2	\$	2,160.20	\$ 2,160.20	+

7802.30
6241.84

TOTAL PRICE: \$ 14,099.00
LESS 20% \$ 2,819.80
SUB TOTAL PRICE: \$ 11,279.20

SPECIAL NETT ITEMS

	ITEMS	QTY	UNIT PRICE	TOTAL	
1	FRONT BUMPER CLIPS <i>3m</i>	1 SET	\$ 30.00	\$ 30.00	-
2	FRONT FENDER INNER SHIELD CLIPS	1 SET	\$ 30.00	\$ 30.00	-
3	FRONT FENDER GLASS SEALANT <i>3m</i>	1	\$ 40.00	\$ 40.00	-
4	FRONT DOOR INNER TRIM CLIPS <i>3m</i>	1 SET	\$ 30.00	\$ 30.00	+
5	FRONT DOOR BLACK TAPE <i>3m</i>	1 SET	\$ 60.00	\$ 60.00	✓
6	FRONT LH DOOR VISOR	1	\$ 80.00	\$ 80.00	60.
7	ROCKER PANEL SIDE SKIRTING CLIPS <i>3m</i>	1 SET	\$ 30.00	\$ 30.00	+
8	FRONT LH WHEEL RIM <i>3m</i>	1	\$ 800.00	\$ 800.00	400
9	FRONT LH TYRE <i>3m</i>	1	\$ 300.00	\$ 300.00	+

670

TOTAL : \$ 1,400.00

LABOUR

	JOB	PRICE	ADJUSTED COST	APPROVED
1	PANEL BEATING, REMOVE AND REFIT PARTS	\$ 1,600.00	1000	
2	SPRAY PAINTING TO AFFECTED AREA	\$ 1,400.00	1000	
3	WIRING CHECK	\$ 50.00	30	
4	TO SPRAY TUFF COAT	\$ 150.00	60	
5	TO TRANSFER DOOR FITTINGS	\$ 150.00	80	
6	TO REMOVE FRONT UNDERCARRIAGE	\$ 400.00	220	
7	TO PERFORM WHEEL ALIGNMENT	\$ 150.00	80	

TOTAL: \$ 3,900.00

2470

ESTIMATE REPORT

TOTAL PARTS COST: \$ 12,679.20
TOTAL LABOUR COST: \$ 3,900.00
TOTAL REPAIR COST: \$ 16,579.20

Adrian L

w/s. 09 Days.

total: 9381.84.

w/s: 7.5K.

APPROVED DETAILS

SURVEYOR:

CONTACT:

PART BY PART / LUMP SUM:

NO. OF DAYS:

LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: Date:	FAX:
---	------