



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile **CS3/SMO22007269/Aqy3-1**

SOMPO INSURANCE SINGAPORE PL
50 RAFFLES PLACE #03-03
SINGAPORE LAND TOWERSINGAPORE 048623

Ref: ~~CS3/SMO22007269/Aqy3-1~~
Date: ~~01/08/2022~~ 16/01/2023
Code: SMO

1. Policy Particulars :- (THIRD PARTY CLAIM)

Insured Veh.	GBH 4090Y	Veh. Inspected	SLV 1536G
Policy No.		Coverage (\$)	0.00
Claim No.	CMTD2202581/RUC	Excess (\$)	0.00
Assign From	CH MOTOR RUTH CHUA	Assign Date	01/08/2022 16/01/2023

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	29/07/2022	Inspection Date	01/08/2022
Survey held at	CH MOTOR VEHICLE REPAIR TRADING BLK 3019A #01-30 UBI ROAD 1 SINGAPORE 408713		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.