



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623		Ref: CS3/SMO22007269/Aqy3e2-1 Date: 27/01/2023 Code: SMO	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	GBH 4090Y	Veh. Inspected	SLV 1536G
Policy No.		Coverage (\$)	0.00
Claim No.	CMTD2202581/RUC	Excess (\$)	0.00
Assign From	RUTH CHUA	Assign Date	16/01/2023
2. Vehicle Particulars & Condition			
Make & Model	TOYOTA C-HR HYBRID	c.c	1797
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	ZYX102050709	Colour	BLACK
Odometer	63092 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	225/50 R18	YOKOHAMA	6 mm
L/H Front Tyre	225/50 R18	YOKOHAMA	6 mm
R/H Rear Tyre	225/50 R18	YOKOHAMA	6 mm
L/H Rear Tyre	225/50 R18	YOKOHAMA	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	29/07/2022	Inspection Date	01/08/2022
Survey held at	CH MOTOR VEHICLE REPAIR TRADING BLK 3019A #01-30 UBI ROAD 1 SINGAPORE 408713		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		7 Working Days	