

J&M CONSULTANCY PTE LTD

11 Changi South Lane #02-08
ONN WAH BUILDING Singapore 486154
Company Reg No: 202125502E
Tel: 6214-0474 Fax: 6384-5205

VEHICLE INSPECTION REPORT

To: DANA ABERNATHY Date : 5 January 2023
C/o: A-Tec Automotive Pte Ltd Our ref : ATEC/01/0002/JM
8 Kaki Bukit Avenue 4
#04-20 Premier @ Kaki Bukit, Singapore 415875

Accident Date : 11 June 2022 Type of Survey : Third party
Inspection Date : 6 July 2022
Repairer Name : A-Tec Automotive Pte Ltd
8 Kaki Bukit Avenue 4
#04-20 Premier @ Kaki Bukit, Singapore 415875

PARTICULARS OF VEHICLE

Registration No : FBN 6148 X Year / Capacity : 2018/ 400cc
Make / Model : Kawasaki/ Ninja Colour : Black
Chassis No : JKAEX400GGDA07580 Mileage : - km
Engine No :

CONDITION OF TYRES

	Make	Size	Thread Balance
Front Nearside	Michelin	110/70 R17	80%
Front Offside	-	-	-
Rear Nearside	Michelin	150/60 R17	80%
Rear Offside	-	-	-

GENERAL DESCRIPTION OF DAMAGE VEHICLE

The impact damages sustained on the vehicle at the time of inspection is on the left & right portion.
(Details refer to the photographs attached)

Enclosed number of photographs: 55 copies

REMARKS

This inspection was conducted entirely on a "WITHOUT PREJUDICE" basis and we have not given authorization and instruction to the repairer to proceed with the repair.

Vehicle Registration No: FBN 6148 X

Our Ref No: ATEC/01/0002/JM

RECOMMENDATIONS

We have thoroughly inspected each and every item on the estimate against the physical damage found on the vehicle and we have listed the breakdown of our finding and our recommendation.

Under normal circumstances, the repair period would be about **7 (Seven)** working days.

Qty	Description	Condition	Repairer's Estimate	Revised Amount
-----	-------------	-----------	---------------------	----------------

SPARE PARTS - LIST ITEMS

1	Front headlamp	Cracked/Malfunction	\$ 850.00	\$ 850.00	755✓
1	Front body cowling LH	Warped	\$ 550.00	\$ 550.00	✓
1	Front body cowling RH	Warped	\$ 550.00	\$ 550.00	✓
1	Front wheel fork assy LH	Bent	\$ 680.00	\$ 680.00	X nn
1	Front wheel fork assy RH	Bent	\$ 680.00	\$ 680.00	X nn
1	Front fender assy	Warped	\$ 480.00	\$ 480.00	X nn
1	Front side cover LH	Warped	\$ 250.00	\$ 250.00	✓
1	Front side cover RH	Warped	\$ 250.00	\$ 250.00	✓
1	Front side mirror RH	Repair	\$ 250.00	\$ -	
1	Front side mirror LH	Scratched	\$ 250.00	\$ 250.00	150✓
1	Front clutch lever RH	Scratched	\$ 220.00	\$ 220.00	70✓
1	Front handle grip LH	Scratched	\$ 200.00	\$ 200.00	X nn
1	Front engine cover	Warped	\$ 400.00	\$ 400.00	X nn
1	Rear exhaust cover	Warped/Scratched	\$ 420.00	\$ 420.00	160✓
Total			\$ 6,030.00	\$ 5,780.00	2735
Less 10%			\$ 603.00	\$ 578.00	-10%
			\$ 5,427.00	\$ 5,202.00	2461.50

SPECIAL NETT ITEMS

1	Rear top box set	Necessary	\$ 500.00	\$ 500.00	X nn
1	Front wheel tyre	Torn	\$ 120.00	\$ 120.00	X nn
			\$ 620.00	\$ 620.00	
Total parts			\$ 6,047.00	\$ 5,822.00	

Vehicle Registration No: FBN 6148 X

Our Ref No: ATEC/01/0002/JM

S/No	Description	Repairer's Estimate	Revised Amount
------	-------------	---------------------	----------------

Total cost of parts c/f

\$ 6,047.00

\$ 5,822.00

LABOUR

1	To putty and spray painting the affected areas. Job Allowance.	\$ 2,000.00	\$ 1,800.00	300
2	To replace damaged parts.	\$ 1,800.00	\$ 1,600.00	300
3	To check front and rear lighting and wiring.	\$ 150.00	\$ 120.00	30
4	To apply anti rust proofing to the affected areas.	\$ 300.00	\$ 280.00	20
5	To remove and install front inner garnish components to facilitate the repair.	\$ 180.00	\$ 160.00	×
6	To remove and install front wheel components to facilitate the repair.	\$ 180.00	\$ 160.00	×

Grand Total:

\$ 10,657.00

\$ 9,942.00

650

3111.50

The repairer has agreed to undertake the repair under a Lump Sum Basis. We have further adjusted the amount to a **Lump Sum Repair Contract of : \$ 7,900**

**L/S - 2489.20
= 2500**

3 days