

## Vehicle Damage Assessment Report for [SFJ7882B]

Estimate Created: 09/03/2023 13:09 by Insurlogic 4 (Insurlogic\_Pte\_Ltd)

Owned: 10/03/2023 12:40 by Insurlogic 4 (Insurlogic\_Pte\_Ltd)

### General Information

---

|                   |                              |                  |
|-------------------|------------------------------|------------------|
| Insurance Company | ERGO                         | Claim Number     |
| Claim Type        | OD                           |                  |
| Workshop          | LKK_Auto_Consultants_Pte_Ltd | Reference Number |

### Vehicle Information

---

|                      |          |                    |         |
|----------------------|----------|--------------------|---------|
| Brand                | Toyota   | Model              | Harrier |
| Engine Type          |          |                    |         |
| License Plate Number | SFJ7882B | VIN (or Chassis #) |         |

### Vehicle Condition

---

|                 |                 |         |
|-----------------|-----------------|---------|
| Damaged Diagram | Odometer        | 0.00 Km |
|                 | Tyres Condition |         |
|                 | Front Left      | mm      |
|                 | Front Right     | mm      |
|                 | Rear Left       | mm      |
|                 | Rear Right      | mm      |

### Comments

---

- FINAL REVIEW BASED ON INFORMATION PROVIDED BY LKK:  
CONCLUDED THE COST OF REPAIR AT \$17,000.00 WITH 10 WORKING DAYS.

Insurlogic 4 (09/03/2023 14:09)

**Parts**

| Description                   | Number/Type | Qty | Cost    | Markup/Disc.% | Sum      |
|-------------------------------|-------------|-----|---------|---------------|----------|
| front bumper                  |             | 1   | 800.00  | 10.00 %       | 880.00   |
| RH front bumper side retainer |             | 1   | 60.00   | 10.00 %       | 66.00    |
| RH front bumper fog lamp      |             | 1   | 210.00  | 10.00 %       | 231.00   |
| RH headlamp                   |             | 1   | 3100.00 | 10.00 %       | 3,410.00 |
| RH front fender               |             | 1   | 680.00  | 10.00 %       | 748.00   |
| RH front fender inner cowling |             | 1   | 220.00  | 10.00 %       | 242.00   |
| RH front wheel bearing        |             | 1   | 450.00  | 10.00 %       | 495.00   |
| RH front lower arm            |             | 1   | 480.00  | 10.00 %       | 528.00   |
| RH front shock absorber       |             | 1   | 380.00  | 10.00 %       | 418.00   |
| LH rear shock absorber        |             | 1   | 380.00  | 10.00 %       | 418.00   |
| LH rear control arm           |             | 1   | 300.00  | 10.00 %       | 330.00   |
| LH rear knuckle arm           |             | 1   | 520.00  | 10.00 %       | 572.00   |
| LH rear lower arm             |             | 1   | 400.00  | 10.00 %       | 440.00   |
| LH rear wheel bearing hub     |             | 1   | 294.95  | 10.00 %       | 324.45   |
| Rear bootlid                  |             | 1   | 1200.00 | 10.00 %       | 1,320.00 |
| Rear boot lid Harrier badge   |             | 1   | 50.00   | 10.00 %       | 55.00    |
| Rear end panel                |             | 1   | 600.00  | 10.00 %       | 660.00   |
| LH rear taillamp              |             | 1   | 850.00  | 10.00 %       | 935.00   |
| LH rear fender inner garnish  |             | 1   | 380.00  | 10.00 %       | 418.00   |
| Rear bumper                   |             | 1   | 850.00  | 10.00 %       | 935.00   |
| Rear bumper side retainer     |             | 2   | 60.00   | 10.00 %       | 132.00   |
| Rear bumper sensor            |             | 4   | 191.25  | 10.00 %       | 841.50   |
| Rear bumper sensor holder     |             | 4   | 21.25   | 10.00 %       | 93.50    |
| Rear bumper inner sponge      |             | 1   | 100.00  | 10.00 %       | 110.00   |
| Rear bumper reflector         |             | 2   | 50.00   | 10.00 %       | 110.00   |
| LH rear air vent              |             | 1   | 140.00  | 10.00 %       | 154.00   |
| LH rear fender                |             | 1   | 1100.00 | 10.00 %       | 1,210.00 |
| LH rear fender inner panel    |             | 1   | 1000.00 | 10.00 %       | 1,100.00 |

Parts Subtotal 17,176.45

**Materials**

| Description        | Number/Type | Qty | Cost   | Markup/Disc.% | Sum    |
|--------------------|-------------|-----|--------|---------------|--------|
| RH front wheel rim |             | 1.0 | 800.00 | 0.00 %        | 800.00 |

|                                   |     |       |        |       |
|-----------------------------------|-----|-------|--------|-------|
| Tailgate windscreen glass sealant | 1.0 | 40.00 | 0.00 % | 40.00 |
|-----------------------------------|-----|-------|--------|-------|

Materials Subtotal 840.00

## Labor

### Replace/RnR

| Description                                  | Type | Cost    | Markup/Disc % | Price    |
|--|------|---------|---------------|----------|
| To check wiring and diagnostic               | RnR  | 30.00   | 0.00 %        | 30.00    |
| Remove and refix upholstery                  | RnR  | 60.00   | 0.00 %        | 60.00    |
| remove and replace reverse sensor            | RnR  | 40.00   | 0.00 %        | 40.00    |
| Labour charge for knock dent and renew parts | RnR  | 1800.00 | 0.00 %        | 1,800.00 |
| Remove and refix rear windscreen             | RnR  | 120.00  | 0.00 %        | 120.00   |

### Repair

| Description      | Severity | Cost | Markup/Disc % | Price |
|------------------|----------|------|---------------|-------|
| LH rear door     | Medium   | 0.00 | 0.00 %        | 0.00  |
| Rear floor panel | Medium   | 0.00 | 0.00 %        | 0.00  |

### Paint

| Description       | Paint Type | Cost    | Markup/Disc % | Price    |
|-------------------|------------|---------|---------------|----------|
| To spray painting | Full spray | 1800.00 | 0.00 %        | 1,800.00 |

|            |               |                        |                 |
|------------|---------------|------------------------|-----------------|
| Labor Rate | S\$ 50 / Hour | General Labor Subtotal | 2,050.00        |
|            |               | Paint Labor Subtotal   | 1,800.00        |
|            |               | <b>Labor Subtotal</b>  | <b>3,850.00</b> |

## Summary

|                       |                  |
|-----------------------|------------------|
| Repair Cost           | 21,866.45        |
| Discount(22 %)        | (4,810.62)       |
|                       | 17,055.83        |
| Excess                | (1,000.00)       |
| GST(0.00 %)           | 0.00             |
| <b>Grand Subtotal</b> | <b>16,055.83</b> |